

Single-phase Current Relay K8AB-AS

Ideal for current monitoring for industrial facilities and equipment.

- Monitor for overcurrents or undercurrents.
- Manual resetting and automatically resetting supported by one Relay.
- Startup lock and operating time can be set separately.
- One SPDT output relay, 6 A at 250 VAC (resistive load).
- Output relay can be switched between normally open and normally closed.
- Process control signal (4 to 20 mA) supported.
- Commercial CT input signal (0 to 1 A, 0 to 5 A) supported.
- Output status can be monitored using LED indicator.



Rus CE

Model Number Structure

■ Model Number Legend

1. Basic Model

K8AB: Measuring and Monitoring Relays

2. Functions

AS: Single-phase Current Relay (One-sided operation)

3. Measuring Current

- 1: 2 to 20 mA AC/DC, 10 to 100 mA AC/DC, 50 to 500 mA AC/DC
- 2: 0.1 to 1 A AC/DC, 0.5 to 5 A AC/DC, 0.8 to 8 A AC/DC
- 3: 10 to 100 A AC, 20 to 200 A AC (See note.)

Note: The K8AB-AS3 is specially designed to be used in combination with the OMRON K8AC-CT200L Current Transformer (CT). (Direct input is not possible.)

4. Supply Voltage

24 VDC: 24 VDC 24 VAC: 24 VAC 100-115 VAC: 100 to 115 VAC 200-230 VAC: 200 to 230 VAC

Ordering Information

■ List of Models

Single-phase Current Relay	Measuring current	Supply voltage	Model	
	2 to 20 mA AC/DC, 10 to 100 mA AC/DC, 50 to 500 mA AC/DC	24 VDC, not insulated	K8AB-AS1 24 VDC (See note 1.)	
		24 VAC, insulated	K8AB-AS1 24 VAC	
	50 to 500 ma AC/DC	100-115 VAC, insulated K8AB-AS1 100-115 VAC	K8AB-AS1 100-115 VAC	
		200-230 VAC, insulated	K8AB-AS1 200-230 VAC	
(0)	0.1 to 1 A AC/DC, 0.5 to 5 A AC/DC, 0.8 to 8 A AC/DC	24 VDC, not insulated	K8AB-AS2 24 VDC (See note 1.)	
		24 VAC, insulated	K8AB-AS2 24 VAC	
	0.6 to 6 A AC/DC	100-115 VAC, insulated K8AB-	K8AB-AS2 100-115 VAC	
		200-230 VAC, insulated	K8AB-AS2 200-230 VAC	
	10 to 100 A AC,	24 VDC, not insulated	K8AB-AS3 24 VDC (See note 1.)	
	20 to 200 A AC (See note 2.)	24 VAC, insulated	K8AB-AS3 24 VAC	
	(See Hole 2.)	100-115 VAC, insulated	K8AB-AS3 100-115 VAC	
		200-230 VAC, insulated	K8AB-AS3 200-230 VAC	

Note: 1. Models with a 24-VDC power supply have a non-isolated power supply.

The inputs and power supply are connected internally, so a malfunction may occur due to an unwanted current path if the inputs and power supply are connected to the same line.

If an unwanted current path exists, use a K8AB AC Power Supply or isolate with an external power supply.

2. The K8AB-AS3 is designed to be used in combination with an OMRON K8AC-CT200L Current Transformer (CT). (Direct input is not possible.)

■ Accessory (Order Separately)

OMRON CT

Current Transformer	Input range	Applicable Relay	Model
JAGA OTRON	10 to 100 A AC, 20 to 200 A AC	K8AB-AS3	K8AC-CT200L

Other CTs

CT current on secondary side	Applicable Relay	
0 to 1 A AC,	K8AB-AS2	
0 to 5 A AC		

Ratings and Specifications

■ Input Range

Model	Model Range Connection terminal Input imped		Input impedance	Overload capacity		
K8AB-AS1 2 to 20 mA AC/DC		I1-COM	Approx. 5 Ω	120% max. input continuous		
	10 to 100 mA AC/DC	I2-COM	Approx. 1 Ω	150% max. input for 1 s		
	50 to 500 mA AC/DC	I3-COM	Approx. 0.2 Ω			
K8AB-AS2	0.1 to 1 A AC/DC	I1-COM	Approx. 0.12 Ω (load: 0.5 VA)			
	0.5 to 5 A AC/DC	I2-COM	Approx. 0.02 Ω (load: 1.5 VA)			
	0.8 to 8 A AC/DC	I3-COM	Approx. 0.02 Ω (load: 3 VA)			
K8AB-AS3	10 to 100 A AC	I2-COM	Uses commercial CT	120% max. input continuous 200% max. input for 30 s		
20 to 200 A AC		I3-COM	Uses commercial CT	600% max. input for 1 s		

■ Ratings

Power supply Non-isolated power su		24 VDC (See note.)		
voltage	Isolated power supply	24 VAC, 100 to 115 VAC, 200 to 230 VAC		
Power consumption		24 VDC: 1 W max. 24 VAC: 4 VA max. 100 to 115 VAC: 4 VA max. 200 to 230 VAC: 5 VA max.		
Operating value setting range (SV)		10% to 100% of maximum measuring current K8AB-AS1: 2 to 20 mA AC/DC		
Operating value		100% operation at set value		
Reset value settin	g range (HYS.)	5% to 50% of operating value		
Reset method		Manual reset/automatic reset (switchable) Note: Manual reset: Turn OFF power supply for 1 s or longer.		
Operating time se		0.1 to 30 s		
	setting range (LOCK) r for overcurrent operation.	0 to 30 s (The startup lock timer starts when the input has reached approximately 30% or more of the set value.) Note: Enabled only for overcurrent operation.		
Indicators		Power (PWR): Green, Relay output (RY): Yellow, Alarm outputs (ALM): Red		
Input impedance		Refer to the "Input Range" on the previous page.		
Output relays		One SPDT relay (NO/NC switched using DIP switch.)		
Output relay ratings		Rated load Resistive load 6 A at 250 VAC (cos\(\phi = 1 \)) 6 A at 30 VDC (L/R = 0 ms) Inductive load 1 A at 250 VAC (cos\(\phi = 0.4 \)) 1 A at 30 VDC (L/R = 7 ms) Maximum contact voltage: Maximum contact current: 6 A AC Maximum switching capacity: 1,500 VA Minimum load: 10 mA at 5 VDC Mechanical life: 10,000,000 operations Electrical life: Make: 50,000 times, Break: 30,000 times		
Ambient operating	g temperature	-20 to 60°C (with no condensation or icing)		
Storage temperati	ure	-40 to 70°C (with no condensation or icing)		
Ambient operating	g humidity	25% to 85% (with no condensation)		
Storage humidity		25% to 85% (with no condensation)		
Altitude		2,000 m max.		
Terminal screw tig	htening torque	0.49 N·m		
Terminal wiring m	ethod	Recommended wire Solid wire: 2.5 mm² Twisted wires: AWG16, AWG18 Note: 1. Ferrules with insulating sleeves must be used with twisted wires. 2. Two wires can be twisted together. Recommended ferrules Al 1,5-8BK (for AWG16) manufactured by Phoenix Contact Al 1-8RD (for AWG18) manufactured by Phoenix Contact Al 0,75-8GY (for AWG18) manufactured by Phoenix Contact		
		Munsell 5Y8/1		
Case material ABS resin (self-extinguishing resin) UL94-V0		ABS resin (self-extinguishing resin) UL94-V0		
Weight		DC models: Approx. 110 g AC models: Approx. 150 g		
Mounting		Mounted to DIN Track or via M4 screws (tightening torque: 1.2 N⋅m)		

Note: Models with a 24-VDC power supply have a non-isolated power supply; the inputs and power supply are connected internally. If both the input and power supply are grounded, an unwanted current path will be created and the Unit will not operate normally. If an unwanted current path exists, use a K8AB model with an AC power supply or use an isolated DC power supply.


■ Specifications

Allowable power	supply voltage range	85% to 110% of power supply voltage		
Allowable power supply frequency range		50/60 Hz ±5 Hz		
Input frequency range		K8AB-AS1 and K8AB-AS2: DC input or AC input (45 to 65 Hz) K8AB-AS3: AC input (45 to 65 Hz)		
Overload capacity		K8AB-AS1 and K8AB-AS2: Continuous input: 120% of maximum input, 1 s max.: 150% of maximum input. K8AB-AS3: Continuous input: 120% of maximum input, 30 s max.: 200% of maximum input, 1 s max.: 600% of maximum input Note: Overload capacity of primary side of CT.		
Setting error Operating value Reset value		Set value ±10% full scale		
	Operating time			
	Startup lock time			
Repeat error	Operating value	Operating value $\pm 2\%$ Error calculation: Error = ((Maximum operating value – Minimum operating value (over 10 operations))/2)/ Average value \times 100%		
	Reset value	Reset value ±2% Error calculation: Error = ((Maximum reset value – Minimum reset value (over 10 resets))/2)/Average value × 100%		
	Operating time	Operating time repeat error: ±50 ms Overcurrent: Measured when input suddenly changes from 0% to 120% of setting. Undercurrent: Measured when input suddenly changes from 120% to 0% of setting.		
	Startup lock time	Startup lock time repeat error: ±50 ms (measured at sudden change from 0% to 120% of setting)		
Temperature infl	uence	Operating value Drift based on measured value at standard temperature: -20°C to standard temperature: ±1,000 ppm/°C max. Standard temperature to 60°C: ±1,000 ppm/°C max. (Humidity: 25% to 80%) Operating time Fluctuation based on measured value at standard temperature: -20°C to standard temperature: ±10% max. Standard temperature to 60°C: ±10% max. (Humidity: 25% to 80%)		
Humidity influence		Operating value Based on ambient humidity of 65% 25% to 80%: ±5% max. Operating time Based on ambient room humidity 25% to 80%: ±10% max.		
Influence of pow	er supply voltage	Operating value: ±5% max. Operating time: ±10% max. Note: The error in the operating value and operating time under standard conditions.		
Influence of pow	er supply frequency	Operating value: ±5% max. (at 45 to 65 Hz) Operating time: ±10% max. (at 45 to 65 Hz) Note: The error in the operating value and operating time under standard conditions.		
Influence of inpu	it frequency	Operating value (45 to 65 Hz) K8AB-AS1 and K8AB-AS2: ±5% max. K8AB-AS3: ±10% max. Operating time (45 to 65 Hz) ±10% max. Note: The error in the operating value and operating time under standard conditions.		
Applicable standards	Conforming standards	EN60255-5 and EN60255-6 Installation environment (Pollution Degree 2, Overvoltage Category III)		
	EMC	EN61326		
	Safety standards	UL508		
Insulation resistance		$20~M\Omega$ min. Between external terminals and case Between power supply terminals and input terminals (excluding models with DC power supply) Between power supply terminals and output terminals Between input terminals and output terminals		
Dielectric strength		2,000 VAC for one minute Between external terminals and case Between power supply terminals and input terminals (excluding models with DC power supply) Between power supply terminals and output terminals Between input terminals and output terminals		
Noise immunity		1,500 V power supply terminal common/normal mode Square-wave noise of $\pm 1~\mu s/100$ ns pulse width with 1-ns rise time		
Vibration resista	nce	Frequency 10 to 55 Hz, 0.35-mm single amplitude, acceleration 50 m/s² 10 sweeps of 5 min each in X, Y, and Z directions		
Shock resistance	e	100 m/s², 3 times each in 6 directions along three axes (up/down, left/right, forward/backward)		
Degree of protect	tion	Terminal section: Finger protection		


Connections


■ Wiring Diagram

Overcurrent Operation Diagram (Output: Normally Open)



<u>Undercurrent Operation Diagram</u> (Output: Normally Closed)






Note: The K8AB-AS3 is designed to be used in combination with the OMRON K8AC-CT200L Current Transformer (CT). The 24-VDC power supply type is a non-insulated power supply.

The inputs and power supply are connected internally, so a malfunction may occur due to an unwanted current path if the inputs and power supply are connected to the same line.

Nomenclature

■ Front



Indicators

Item	Meaning		
Power indicator (PWR: Green)	Lit when power is being supplied.		
Relay status indicator (RY: Yellow)	Lit when relay is operating.		
Alarm indicator (ALM: Red)	Lit when there is an overcurrent or undercurrent.		
	The indicator flashes to indicate the error status after the input has exceeded the threshold value while the operating time is being clocked.		


Setting Knobs

Item	Usage
Current knob (SV)	Used to set the current to 10% to 100% of maximum measuring current.
Hysteresis knob (HYS.)	Used to set the rest value to 5% to 50% of the operating value.
Operating time knob (T)	Used to set the operating time to 0.1 to 30 s.
Startup lock time knob (LOCK)	Used to set the startup lock time to 0 to 30 s.

Note: 1. Use either a solid wire of 2.5 mm² maximum or a ferrule with insulating sleeve for the terminal connection.

The length of the exposed current-carrying part inserted.

The length of the exposed current-carrying part inserted into the terminal must be 8 mm or less to maintain dielectric strength after connection.



Recommended ferrules

Phoenix Contact

- Al 1,5-8BK (for AWG16)
- AI 1-8RD (for AWG18)
- Al 0,75-8GY (for AWG18)
- 2. Tightening torque Recommended: 0.49 N·m Maximum: 0.54 N·m

■ Operation and Setting Methods

Setting Ranges and Wiring Connections

Model	Measuring current	Wiring connection
K8AB-AS1	2 to 20 mA AC/DC	I1-COM
	10 to 100 mA AC/DC	I2-COM
	50 to 500 mA AC/DC	I3-COM
K8AB-AS2	0.1 to 1 A AC/DC	I1-COM
	0.5 to 5 A AC/DC	I2-COM
	0.8 to 8 A AC/DC	I3-COM
K8AB-AS3	10 to 100 A AC (See note 2.)	I2-COM
	20 to 200 A AC (See note 2.)	I3-COM

Note: 1. The DC input terminals have no polarity.

The K8AB-AS3 is designed to be used in combination with the OMRON K8AC-CT200L Current Transformer (CT). (Direct input is not possible.)

Connections

1. Input

Connect the input between the I1-COM, I2-COM, or I3-COM terminals, according to the input current. Malfunctions may occur if the input is connected to unused terminals and the Unit will not operate correctly.

Terminal I1 is not used by the K8AB-AS3.

If using the OMRON K8AC-CT200L CT, connect to terminals k and I on the K8AC-CT200L. (Terminals kt and It are not used.)

2. Power Supply

Connect the power supply to terminals A1 and A2.

Note: Models with DC power supply have a non-isolated power supply. The input and power supply terminals are connected internally so the K8AB-AS will not operate normally if an unwanted current path is created. If an unwanted current path exists, use a model with an AC power supply or isolate with an external power supply.

3. Outputs


SPDT relays are output to terminals 11, 12, and 14.

Note: Use the recommended ferrules if using twisted wires.

<For K8AB-AS3> Single-phase power K8AB-AS3 Power supply voltage A2 K8AC-11 CT200L 12 Current inpu 13 COM Signal output Relay 12 signa output Load

DIP Switch Settings

The resetting method, relay drive method, and operating mode are set using the DIP switch located on the bottom of the Unit. K8AB-AS \square does not use SW1.



DIP Switch Functions

SWITCH	ON ● ↑	4 ON	3	2	1
	OFF ○↓	OFF			
Resetting method	Automatic reset			•	
	Manual reset			0	
Relay drive method	Normally closed		•		NO USE
	Normally open		О		NO USE
Operating mode	Undercurrent	•			
	Overcurrent	О			

Note: All pins are set to OFF at the factory.

Setting Method

1. Setting Current

The current knob (SV) is used to set the current.

The current can be set to 10% to 100% of the maximum measuring current.

Turn the knob while there is an input to the input terminals until the alarm indicator flashes (when the set value and the input have reached the same level.)

Use this as a guide to set the current.

The maximum measuring current will differ depending on the model and the input terminal.

Example: K8AB-AS3 Using Input Terminals I3-COM

The maximum measuring current will be 200 A AC and the setting range will be 20 to 200 A.

2. Hysteresis

Hysteresis is set using the hysteresis knob (HYS.)

The setting range is 5 to 50% of the operating value.

Turn the knob while there is an input to the input terminals until the alarm indicator flashes (when the set value and the input have reached the same level.)

Use this as a guide to set the hysteresis.

Example: Maximum of 200 A AC, Current Setting (SV) of 50%, and Overcurrent Operation

Operation will be at 100 A and resetting at 90 A when the hysteresis (HYS.) is set to 10%.

3. Operating Time

The operating time is set using the operating time knob (T).

The operating time can be set to between 0.1 and 30 s.

Turn the knob while there is an input to the input terminals until the alarm indicator flashes (when the set value and the input have reached the same level.)

Use this as a guide to set the operating time.

If the input current exceeds (drops lower than) the current setting, the alarm indicator will start flashing for the set period and then stay lit.

4. Startup Lock Time

The startup lock time is set using the startup lock time knob (LOCK).


The startup lock time can be set to between 0 and 30 s.

Turn the knob while there is an input to the input terminals until the alarm indicator flashes (when the set value and the input have reached the same level.)

Use this as a guide to set the startup lock time.

The startup lock time will start when the input current reaches 30% or more of the current setting.

Use startup lock time to prevent unwanted operation, e.g., as a result of inrush current.




Dimensions


(Unit: mm)

Single-phase Current Relays

K8AB-AS1 K8AB-AS2 K8AB-AS3








OMRON CT

K8AC-CT200L





Note: The OMRON Current Transformer (CT) is designed to be used with the K8AB-AS3. Use terminals k and I for connections. (Terminals kt and It are not used.)

Safety Precautions

■ Precautions for Safe Use

Make sure to follow the instructions below to ensure safety.

- 1. Do not use or keep this product in the following environments.
 - Outdoors, or places subject to direct sunlight or wearing weather.
 - Places where dust, iron powder, or corrosive gases (in particular, sulfuric or ammonia gas) exist.
 - Places subject to static electricity or inductive noise.
 - Places where water or oil come in contact with the product.
- 2. Make sure to install this product in the correct direction.
- 3. There is a remote risk of electric shock. Do not touch terminals while electricity is being supplied.
- 4. Make sure to thoroughly understand all instructions in the Instructions Manual before handling this product.
- Make sure to confirm terminal makings and polarity for correct wiring.
- 6. Tighten terminal screws firmly using the following torque. Recommended tightening torque: 0.49 N⋅m Maximum tightening torque: 0.54 N⋅m max.
- Operating ambient temperature and humidity for this product must be within the indicated rating when using this product.
- 8. There is a remote risk of explosion. Do not use this product where flammable or explosive gas exists.
- 9. Make sure that no weight rests on the product after installation.
- 10.To enable an operator to turn off this product easily, install switches or circuit breakers that conform to relevant requirements of IEC60947-1 and IEC60947-3, and label them appropriately.
- 11.For DC input, use a SELV power-supply capable of overcurrent protection. Specifically, a SELV power-supply has a double or reinforced insulation for input and output, and output voltage of 30 Vr.m.s with 42.4 V at peak or DC60V maximum. Recommended power-supply: Model S8VS-06024□. (Omron product)

■ Precautions for Correct Use

For Proper Use

- 1. Do not use the product in the following locations.
 - Places subject to radiant heat from heat generating devices.
 - · Places subject to vibrations or physical shocks.
- Make sure to use setting values appropriate for the controlled object. Failure to do so can cause unintended operation, and may result in accident or corruption of the product.
- Do not use thinner or similar solvent for cleaning. Use commercial alcohol.
- When discarding, properly dispose of the product as industrial waste.
- 5. Only use this product within a board whose structure allows no possibility for fire to escape.

About Installation

- 1. When wiring, use only recommended crimp terminals.
- Do not block areas around the product for proper dissipation of heat. (If you do not secure space for heat dissipation, life cycle of the product will be compromised.)
- 3. To avoid electrical shocks, make sure that power is not supplied to the product while wiring.
- **4.** To avoid electrical shocks, make sure that power is not supplied to the product when performing DIP switch settings.

Noise Countermeasures

- Do not install the product near devices generating strong high frequency waves or surges.
- When using a noise filter, check the voltage and current and install it as close to the product as possible.
- 3. In order to prevent inductive noise, wire the lines connected to the product separately from power lines carrying high voltages or currents. Do not wire in parallel with or on the same cable as power lines.
 - Other measures for reducing noise include running lines along separate ducts and using shield lines.

To avoid faulty operations, malfunctions, or failure, observe the following operating instructions.

- When turning on the power, make sure to realize rated voltage within 1 second from the time of first supply of electricity.
- 2. Make sure to use power supply for operations, inputs, and transformer with the appropriate capacity and rated burden.
- **3.** Maintenance and handling of this product may only be performed by qualified personnel.
- 4. Distortion ratio of input wave forms must be 30% or less. Use of this product with circuits that have large distortion in wave forms may result in unwanted operations.
- Using this product for thyristor controls or inverters will result in errors.
- When setting the volume, adjust the control from the minimum side to the maximum side.

Questions and Answers



Checking Operation




Overcurrents

Gradually increase the input from 80% of the setting. The input will equal the operating value when the input exceeds the setting and the alarm indicator starts flashing. Operation can be checked by the relay outputs that will start after the operating time has passed.


Undercurrent

Gradually decrease the input from 120% of the setting and check the operation using the same method as for overcurrent.

Example: Overcurrent Operating Mode, Normally Open Relay Drive, and an Operating Time of 5 s



Connection Diagram



Q How to Measure the Operating Time



Overcurrent

Change the input suddenly from 0% to 120% of the set value and measure the time until the Unit operates.

Undercurrent

Change the input suddenly from 120% to 0% of the set value and measure the time until the Unit operates.

Q Monito

Monitoring Switch-mode Power Supplies



Switch-mode Power Supplies cannot be monitored. In circuits with a capacitor input, including switch-mode power supplies, the input capacitor recharge current flows in pulse form as the load current. The K8AB-AS\(\sigma\) has a built-in filter as a countermeasure against high frequencies and cannot be used to remove pulse current.

Grounding the Power Supply for K8AB Models with a DC Power Supply




The input and power supply must be isolated. Models with a DC power supply have a non-isolated power supply. The input and power supply are connected internally so the K8AB-AS will not operate normally if an unwanted current path exists. If an unwanted current path exists, use a K8AB model with an AC power supply or use an isolated DC power supply.

Q Using Multiple K8AB Relays with a DC Power Supply



The input and power supply must be isolated. The input and power supply are connected internally so an unwanted current path will be created if more than one K8AB is used with one DC power supply, as shown in the diagram, and the K8AB will not operate correctly. If an unwanted current path exists, use a K8AB model with an AC power supply or use a different isolated DC power supply for each K8AB.



Q Operating Adjustment Knobs



Use a screwdriver to turn the knobs. There is a stopper to prevent the knob from turning any further once it has been turned completely to the left or right. Do not force the knob past these limits.

Can the K8AB be used to monitor a motor with a rated current of 5 A?

If it's possible to do so, are there any precautions required?


Α

The K8AB-AS1 and K8AB-AS2 cannot be used with a motor load.

Use the K8AB-AS3 together with a K8AC-CT200L Current Transformer.

A current that is many times the rated current can flow to a motor due to startup current or stall current.


The startup current of a motor is shown in the following graph.



For a 5 A motor, the startup current would be approximately 30 A. The startup current would thus exceed the overload capacity of the K8AB-AS1 or K8AB-AS2 (150% of rated current for 1 s).

It is thus necessary to use the K8AB-AS3 to monitor a motor load. (K8AB-AS3 overload capacity: 120% of rated current continuously, 200% of rated current for 30 s, and 600% of rated current for 1 s)

The K8AB-AS3 has a wide input range, so wind the wire around the CT several times.



Reason for Winding the Wire around the CT Used with the K8AB-AS3

Example: Monitoring Overloads for a Motor Rated at 5 A

K8AB Settings

Overcurrent detection, operating value: 25%, operating time: $0.1 \, s$, startup lock timer: $0.1 \, to \, 30 \, s$ (set according to the duration of the startup current)

The K8AB-AS3 can be set to between 10% to 100% of the rated current (10 A to 100 A). The wire is wound five times around the CT so that a current of 10 A or greater will flow. This will make the input current to the K8AB 5 A/winding x 5 windings, or 25 A. If there is a startup current that is 6 times the rated current, the startup current would be 25 A \times 6, or 150 A (i.e., 150% of the rated current). The overload capacity of the K8AB-AS3 is 200% of the rated current for 30 s, so the K8AB-AS3 would not fail even if the startup current continued for 30 s, enabling overload detection.

Warranty and Application Considerations

Read and Understand this Catalog

Please read and understand this catalog before purchasing the products. Please consult your OMRON representative if you have any questions or comments.

Warranty and Limitations of Liability

WARRANTY

OMRON's exclusive warranty is that the products are free from defects in materials and workmanship for a period of one year (or other period if specified) from date of sale by OMRON.

OMRON MAKES NO WARRANTY OR REPRESENTATION, EXPRESS OR IMPLIED, REGARDING NON-INFRINGEMENT, MERCHANTABILITY, OR FITNESS FOR PARTICULAR PURPOSE OF THE PRODUCTS. ANY BUYER OR USER ACKNOWLEDGES THAT THE BUYER OR USER ALONE HAS DETERMINED THAT THE PRODUCTS WILL SUITABLY MEET THE REQUIREMENTS OF THEIR INTENDED USE. OMRON DISCLAIMS ALL OTHER WARRANTIES, EXPRESS OR IMPLIED.

LIMITATIONS OF LIABILITY

OMRON SHALL NOT BE RESPONSIBLE FOR SPECIAL, INDIRECT, OR CONSEQUENTIAL DAMAGES, LOSS OF PROFITS, OR COMMERCIAL LOSS IN ANY WAY CONNECTED WITH THE PRODUCTS, WHETHER SUCH CLAIM IS BASED ON CONTRACT, WARRANTY, NEGLIGENCE, OR STRICT LIABILITY.

In no event shall the responsibility of OMRON for any act exceed the individual price of the product on which liability is asserted. IN NO EVENT SHALL OMRON BE RESPONSIBLE FOR WARRANTY, REPAIR, OR OTHER CLAIMS REGARDING THE PRODUCTS UNLESS OMRON'S ANALYSIS CONFIRMS THAT THE PRODUCTS WERE PROPERLY HANDLED, STORED, INSTALLED, AND MAINTAINED AND NOT SUBJECT TO CONTAMINATION, ABUSE, MISUSE, OR INAPPROPRIATE MODIFICATION OR REPAIR.

Application Considerations

SUITABILITY FOR USE

OMRON shall not be responsible for conformity with any standards, codes, or regulations that apply to the combination of products in the customer's application or use of the products.

Take all necessary steps to determine the suitability of the product for the systems, machines, and equipment with which it will be used. Know and observe all prohibitions of use applicable to this product.

NEVER USE THE PRODUCTS FOR AN APPLICATION INVOLVING SERIOUS RISK TO LIFE OR PROPERTY WITHOUT ENSURING THAT THE SYSTEM AS A WHOLE HAS BEEN DESIGNED TO ADDRESS THE RISKS, AND THAT THE OMRON PRODUCTS ARE PROPERLY RATED AND INSTALLED FOR THE INTENDED USE WITHIN THE OVERALL EQUIPMENT OR SYSTEM.

Disclaimers

PERFORMANCE DATA

Performance data given in this catalog is provided as a guide for the user in determining suitability and does not constitute a warranty. It may represent the result of OMRON's test conditions, and the users must correlate it to actual application requirements. Actual performance is subject to the OMRON *Warranty and Limitations of Liability.*

CHANGE IN SPECIFICATIONS

Product specifications and accessories may be changed at any time based on improvements and other reasons. Consult with your OMRON representative at any time to confirm actual specifications of purchased product.

DIMENSIONS AND WEIGHTS

Dimensions and weights are nominal and are not to be used for manufacturing purposes, even when tolerances are shown.

ALL DIMENSIONS SHOWN ARE IN MILLIMETERS.

To convert millimeters into inches, multiply by 0.03937. To convert grams into ounces, multiply by 0.03527.

Cat. No. N142-E1-02 In the interest of product improvement, specifications are subject to change without notice.

OMRON Corporation

Industrial Automation Company

Control Devices Division H.Q. Shiokoji Horikawa, Shimogyo-ku, Kyoto, 600-8530 Japan

Tel: (81)75-344-7109/Fax: (81)75-344-7149