Notification#20240308000.0
Device symbolization update for Select Devices
Information Only

Date: March 09, 2024
To: Digi-Key PCN

Dear Customer:

This is an information-only announcement of a change to a device that is currently offered by Texas Instruments.

The changes discussed within this notification are for your information only.

Any negotiated alternative change requirements will be provided via the customer's defined process. Customers with previously negotiated, special requirements will be handled separately. Any inquiries should be directed to your local Field Sales Representative.

For questions regarding this notice, contact your local Field Sales Representative or the Change Management team.

Sincerely,

Change Management Team
SC Business Services

Products Affected:

The devices listed on this page are a subset of the complete list of affected devices. According to our records, you have recently purchased these devices. The corresponding customer part number is also listed, if available.

DEVICE	CUSTOMER PART NUMBER
TLVM13610RDFR	NULL
TLVM13620RDHR	NULL
TLVM13630RDHR	NULL
TLVM13660RDLR	NULL
TLVM23615RDNR	NULL
TLVM23625RDNR	NULL
TPSM33615FRDNR	NULL
TPSM33615RDNR	NULL
TPSM33625FRDNR	NULL
TPSM33625RDNR	NULL
TPSM365R3FRDNR	NULL
TPSM365R3RDNR	NULL
TPSM365R6FRDNR	NULL
TPSM365R6RDNR	NULL
TPSM365R6V3RDNR	NULL
TPSM365R6V5RDNR	NULL
TPSM53602RDAR	NULL
TPSM53603RDAR	NULL
TPSM53604RDAR	NULL
TPSM5601R5HEXTRDAR	NULL
TPSM5601R5HRDAR	NULL
TPSM5601R5HSRDAR	NULL
TPSM5601R5RDAR	NULL
TPSM5601R5SRDAR	NULL
TPSM560R6HRDAR	NULL
TPSM560R6RDAR	NULL
TPSM5D1806RDBR	NULL
TPSM63602RDHR	NULL
TPSM63602V3RDHR	NULL
TPSM63602V5RDHR	NULL
TPSM63603EXTRDHR	NULL
TPSM63603RDHR	NULL
TPSM63603SRDHR	NULL
TPSM63603V3RDHR	NULL
TPSM63603V5RDHR	NULL
TPSM63604RDLR	NULL
TPSM63606RDLR	NULL
TPSM63606SRDLR	NULL
TPSM63608RDFR	NULL
TPSM63610EXTRDFR	NULL
TPSM63610RDFR	NULL
TPSM828303ARDSR	NULL
TPSM82864AA0HRDMR	NULL
TPSM82864AA0SRDJR	NULL
TPSM82866AA0HRDMR	NULL
TPSM82866AA0SRDJR	NULL
TPSM8287A06BASRDVR	NULL
TPSM8287A12BBSRDVR	NULL

|	
TPSM82913RDUR	NULL
TPSM84209RKHR	NULL
TPSM84209RKHT	NULL
TPSM843A22RDGR	NULL
TPSM843A22RDGR-ET	NULL
TPSM843A26RDGR-ET	NULL
TPSM843B22RDGR-ET	NULL
TPSM863252RDXR	NULL
TPSM863257RDXR	NULL
TPSM8A28RDGR	NULL
TPSM8A29RDGR	NULL

Technical details of this Product Change follow on the next page(s).

Notification Number:	20240308000.0	Notification Date:	March 09, 2024
Title:	Device symbolization update for Select Devices		
Customer Contact:	Change Management team	**Dept:**	Quality Services

Change Type:

☐	Assembly Site	☐	Design	☐	Wafer Bump Material
☐	Assembly Process	☐	Data Sheet	☐	Wafer Bump Process
☐	Assembly Materials	☐	Part number change	☐	Wafer Fab Site
☐	Mechanical Specification	☐	Test Site	☐	Wafer Fab Materials
☒	Packing/Shipping/Labeling	☐	Test Process	☐	Wafer Fab Process

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an update to the device marking of the devices listed below to improve traceability by adding a 2D barcode:

Current	New, with 2D barcode

NOTE: Some of the other device marking content may be modified to accommodate the 2D barcode.

Reason for Change:

Improved internal traceability

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

Device marking change only

Changes to product identification resulting from this notification:

Device marking change only. No change to pack labels.

Product Affected:

DCM82830RDSR	TPSM365R3FRDNR	TPSM63603V3RDHR	TPSM84209RKHR
DCM82866AA0HRDMR	TPSM365R3RDNR	TPSM63603V5RDHR	TPSM84209RKHT
DCM82866AA0SRDJR	TPSM365R6FRDNR	TPSM63604RDLR	TPSM843A22RDGR
DCM8287ARDVR	TPSM365R6RDNR	TPSM63606EXTRDLR	TPSM843A22RDGR-ET
PPSM82864AA0SRDJR	TPSM365R6V3RDNR	TPSM63606RDLR	TPSM843A26RDGR
PPSM82866AA0SRDJR	TPSM365R6V5RDNR	TPSM63606SRDLR	TPSM843A26RDGR-ET
PTPSM5D1804RDBR	TPSM53602RDAR	TPSM63608RDFR	TPSM843B22RDGR
PTPSM5D1805RDBR	TPSM53603RDAR	TPSM63610EXTRDFR	TPSM843B22RDGR-ET
PTPSM82913RDUR	TPSM53604RDAR	TPSM63610RDFR	TPSM861252RDXR

PTPSM843A22RDGR	TPSM5421R5V5RDAR	TPSM828301ARDSR	TPSM861257RDXR
PTPSM861252RDXR	TPSM5601R5HEXTRDAR	TPSM828302ARDSR	TPSM863252RDXR
PTPSM861257RDXR	TPSM5601R5HRDAR	TPSM828303ARDSR	TPSM863257RDXR
PTPSM8828RDGR	TPSM5601R5HSRDAR	TPSM82864AA0HRDMR	TPSM86637RCGR
PTPSM8A28RDGR	TPSM5601R5RDAR	TPSM82864AA0SRDJR	TPSM86638RCGR
PTPSMUDC009RDNT	TPSM5601R5SRDAR	TPSM82866AA0HRDMR	TPSM86837RCGR
SN1809047RKHT	TPSM5601R5V3RDAR	TPSM82866AA0SRDJR	TPSM86838RCGR
SN53604RDAT	TPSM560R6HRDAR	TPSM8287A06BASRDVR	TPSM8828RDGR
TLVM13610RDFR	TPSM560R6RDAR	TPSM8287A08BAHRDWR	TPSM8A28RDGR
TLVM13620RDHR	TPSM5D1804RDBR	TPSM8287A10BAHRDWR	TPSM8A29RDGR
TLVM13630RDHR	TPSM5D1805RDBR	TPSM8287A12BAMRDVT	TPSMDC82912RDUR
TLVM13640RDLR	TPSM5D1806MRDBR-ET	TPSM8287A12BASRDVR	XPSM82866AA0HRDMR
TLVM13660RDLR	TPSM5D1806RDBR	TPSM8287A12BBMRDVT	XPSM82867HRDJR
TLVM23615RDNR	TPSM63602RDHR	TPSM8287A12BBSRDVR	XPSM8287A06BASRDVR
TLVM23625RDNR	TPSM63602V3RDHR	TPSM8287A15BAHRDWR	XPSM8287A08BAHRDWR
TPSM33615FRDNR	TPSM63602V5RDHR	TPSM8287A15BBHRDWR	XPSM8287A10BAHRDWR
TPSM33615RDNR	TPSM63603EXTRDHR	TPSM82912RDUR	XPSM8287A10BBSRDVR
TPSM33625FRDNR	TPSM63603RDHR	TPSM82913RDUR	XPSM8287A15BAHRDWR
TPSM33625RDNR	TPSM63603SRDHR	TPSM82913RDUR-ET	XPSM8287A15BBHRDWR

For questions regarding this notice, e-mails can be sent to Change Management team or your local Field Sales Representative.