

PRODUCT DISCONTINUANCE NOTIFICATION PDN 2133

NOTE: THIS IS NOT A NEW PDN ISSUANCE

This revision 1.3.0 is an update to revision 1.2.0 on the recommended action and order terms.

Description:

Intel[®] is discontinuing Enpirion[®] Power Solutions – devices, evaluation boards (EVB) and USB communications I/F dongle. A complete list of device family ordering part numbers (OPNs) is listed in Attachment 1A-1B.

Reason for Change:

• Enpirion Power Solutions - devices, evaluation boards (EVB) and USB communications I/F dongle are being discontinued due to Intel decision to exit the Enpirion power business.

Recommended Action:

On PDN 2133 revision 1.1.0, Intel communicated our inability to fulfill all existing last time buy (LTB) backlog. Since then, we have been able to secure additional capacity and plan to support existing LTB backlog. We expect last time buy shipments to extend beyond the last time ship date of March 31, 2023.

Because our supply gap has been closed, we are reverting to the original PDN 2133 revision 1.0.0 non-cancellable terms. Customers will have up to September 16, 2022, to cancel any unscheduled orders or orders scheduled > 90 days. Orders scheduled < 90 days remain non-cancellable. On September 16, 2022, all existing backlog will become non-cancellable.

Key Obsolescence Dates

| Device Family | Last Order Acceptance (1) | Last Time Shipments ⁽²⁾ |
|--|------------------------------|--|
| Enpirion Power Solutions - devices, evaluation boards (EVB) and USB communications I/F dongle | March 18, 2022 | Dec 31, 2023 (est.) or until we have used up our remaining wafer allocation |

- (1) Order Terms:
 - a. Customers will have up to September 16, 2022, to cancel any unscheduled orders or orders scheduled > 90 days. Orders scheduled < 90 days remain non-cancellable. On September 16, 2022, all existing orders will become non-cancellable.
 - b. Non-reschedulable after a delivery date is assigned. Cancellations may be allowed in accordance with subsection (a) above.
 - c. Non-returnable for shipped items.
- (2) While Intel has secured additional supply and expects to be able to support existing LTB backlog, Intel cannot guarantee the fulfillment of all last-time-buy orders. Fulfillment is contingent on global supply availability.

Products Affected:

The list of affected Ordering Part Numbers (OPNs) can be downloaded here: <u>https://www.intel.com/content/dam/www/programmable/us/en/pdfs/literature/pcn/pdn21</u> <u>33-opn-list.xlsx</u> or refer to Attachment 1A-1B.

Please refer to the contact information provided below for any questions or requests for assistance.

Contact:

For more information and assistance, including on redesign efforts, please contact Sales or Customer Service in your region.

Customer Notifications Subscription:

Customers that have subscribed to Intel PSG's customer notification mailing list will receive updates automatically via email.

If you would like to receive customer notifications by email, please subscribe to our customer notification mailing list at

https://www.intel.com/content/www/us/en/programmable/my-intel/mal-emailsub/technicalupdates.html

Revision History

| Date | Rev | Description |
|------------|-------|--|
| 09/17/2021 | 1.0.0 | Initial Release |
| 01/21/2022 | 1.1.0 | Updated redesign recommendation (see Recommended Action section) and NCNRR terms (see notes 1 & 2 on Key Obsolescence Dates section) |
| 07/01/2022 | 1.2.0 | Communicated our ability to support all lifetime buy backlog and updated cancellation terms. |
| 07/15/2022 | 1.3.0 | Updated Recommended Action Section and Order Terms |

©2022 Intel Corporation. All rights reserved. Intel, the Intel logo, Altera, Arria, Cyclone, Enpirion, HardCopy, Max, Nios, Quartus and Stratix words and logos are trademarks of Intel Corporation or its subsidiaries in the U.S. and/or other countries. Other marks and brands may be claimed as the property of others. Intel reserves the right to make changes to any products and services at any time without notice. Intel assumes no responsibility or liability arising out of the application or use of any information, product, or service described herein except as expressly agreed to in writing by Intel. Intel customers are advised to obtain the latest version of device specifications before relying on any published information and before placing orders for products or services.

Attachment 1A Affected Ordering Part Numbers (OPNs) – Devices

| Discontinued OPN Replacement OPN | | |
|----------------------------------|------------------------------------|--|
| | Replacement OPN | |
| EC2630QI | None | |
| EC2650QI | None | |
| EC7100VQI | None | |
| EC7401QI | None | |
| ED8401P01QI | None | |
| ED8401P03QI | None | |
| ED8401P05QI | None | |
| EM2030L01QI | None | |
| EM2040N01QI | None | |
| EM2120H01QI | None | |
| EM2120L01QI | None | |
| EM2121H01QI | None | |
| EM2121L01QI | None | |
| EM2130H01QI | None | |
| EM2130H01QIES# | Refer note at the end of the table | |
| EM2130L01QI | None | |
| EM2130L01QIES # | Refer note at the end of the table | |
| EM2130L02QI | None | |
| EM2140P01QI | None | |
| EM2140P01QIES # | Refer note at the end of the table | |
| EM2260P01QI | None | |
| EM2280P01QI | None | |
| EN117CSW | None | |
| EN2340QI | None | |
| EN2342QI | None | |
| EN2360QI | None | |
| EN2390QI | None | |
| EN2392QI | None | |
| EN23F0QI | None | |
| EN23F2QI | None | |
| EN29A0QI | None | |
| EN5311QI | None | |
| EN5311QI-C | None | |
| EN5312QI | None | |
| EN5319QI | None | |
| EN5322QI | None | |
| EN5329QI | None | |
| EN5335QI | None | |
| EN5336QI | None | |
| EN5337QI | None | |
| EN5339QI | None | |
| EN5364QI | None | |
| | | |

| Replacement OPN |
|-----------------|
| None |
| |

Affected Ordering Part Numbers (OPNs) – Devices (continued)

Affected Ordering Part Numbers (OPNs) – Devices (continued)

| Anceled Ordening Far Humbers (OF N3) Devices (continued) | |
|--|-----------------|
| Discontinued OPN | Replacement OPN |
| ER3105DI | None |
| ER6230QI | None |
| ES1010SI | None |
| ES1021QI | None |
| ES1030QI | None |
| ET2760ALI | None |
| ET6160LI | None |
| EV1320QI | None |
| EV1340QI | None |
| EV1380QI | None |
| EX3AV | None |
| EY1601SA-ADJ | None |
| EY1602SI-ADJ | None |
| EZ6301QI | None |
| EZ6303QI | None |
| | |

Engineering Samples are no longer available for Last Time Buy. Customers are advised to order the equivalent Production OPNs.

Attachment 1B Affected Ordering Part Numbers (OPNs) – EVB & I/F Dongle

| Discontinued OPN | rs (OPINS) – EVB & I/F Dongle Replacement OPN |
|-------------------------------|--|
| EVB-EC2630QI | None |
| EVB-EC2650QI | None |
| EVB-EC2030QI EVB-EC7100VQI | None |
| EVB-EC7401QI | None |
| | |
| | None |
| EVB-EM2130L01QI | None |
| EVB-EM2130L02QI | None |
| EVB-EM2140P01QI | None |
| EVB-EM2260P01QI | None |
| EVB-EM2280P01QI | None |
| EVB-EN2340QI | None |
| EVB-EN2342QI | None |
| EVB-EN2360QI | None |
| EVB-EN2390QI | None |
| EVB-EN2392QI | None |
| EVB-EN23F0QI | None |
| EVB-EN23F2QI | None |
| EVB-EN29A0QI | None |
| EVB-EN5311QI | None |
| EVB-EN5312QI | None |
| EVB-EN5319QI | None |
| EVB-EN5322QI | None |
| EVB-EN5329QI | None |
| EVB-EN5335QI | None |
| EVB-EN5336QI | None |
| EVB-EN5337QI | None |
| EVB-EN5339QI | None |
| EVB-EN5364QI | None |
| EVB-EN5365QI | None |
| EVB-EN5366QI | None |
| EVB-EN5367QI | None |

Affected Ordering Part Numbers (OPNs) – EVB & I/F dongle (continued)

| Discontinued OPN | Replacement OPN |
|------------------|-----------------|
| EVB-EN5394QI | None |
| EVB-EN5395QI | None |
| EVB-EN5396QI | None |
| EVB-EN6310QA | None |
| EVB-EN6310QI | None |
| EVB-EN6337QA | None |
| EVB-EN6337QI | None |
| EVB-EN6338QI | None |
| EVB-EN6340QI | None |
| EVB-EN6347QA | None |
| EVB-EN6347QI | None |
| EVB-EN6360QA | None |
| EVB-EN6360QI | None |
| EVB-EN6362QI | None |
| EVB-EN6363QI | None |
| EVB-EN6382QI | None |
| EVB-EN63A0QA | None |
| EVB-EN63A0QI | None |
| EVB-EP5348UI | None |
| EVB-EP5352QI | None |
| EVB-EP5357HUI | None |
| EVB-EP5357LUI | None |
| EVB-EP5358HUA | None |
| EVB-EP5358HUI | None |
| EVB-EP5358LUA | None |
| EVB-EP5358LUI | None |
| EVB-EP5362QI | None |
| EVB-EP5368QI | None |
| EVB-EP5382QI | None |
| EVB-EP5388QI | None |
| EVB-EP53A7HQI | None |
| EVB-EP53A7LQI | None |
| EVB-EP53A8HQA | None |
| EVB-EP53A8HQI | None |
| EVB-EP53A8LQA | None |
| EVB-EP53A8LQI | None |
| EVB-EP53F8QI | None |
| EVB-ER2120QI | None |
| EVB-ER3105DI | None |
| EVB-ER3125QI | None |
| EVB-ER6230QI | None |

Affected Ordering Part Numbers (OPNs) – EVB & I/F dongle (continued)

| Discontinued OPN | Replacement OPN |
|------------------|-----------------|
| EVB-ES1010SI | None |
| EVB-ES1030QI | None |
| EVB-EV1320QI | None |
| EVB-EV1340QI | None |
| EVB-EV1380QI | None |
| EVB-EY1601SA-ADJ | None |
| EVB-EY1602SI-ADJ | None |
| EVB-EY1603TI-ADJ | None |
| EVB-EZ6301QI | None |
| EVB-EZ6303QI | None |
| EVI-EM2COMIF | None |