

Product Change Notice

Date:	June 12, 2023
Overview:	Labeling change for select parts, moving from rotor stamping to adhesive labels on the cable
Reason for Change:	Consistency – We have been phasing out the rotor stamping and moving toward adhesive labels which offer higher process reliability and traceability
Affected Part No(s):	Please see part number listing on page 3 of this PCN
Design Change Detail:	We are moving from stamping the product information on the rotor to putting adhesive labels on the cable
Effective Date:	Running change beginning immediately
Last Time Buy Deadline:	N/A
Pricing:	No change
ebm-papst employee:	Jeannine Zenobi
Attachments:	Sample labels and listing of affected part numbers (detailed on pages 2 and 3 of this PCN, respectively)
Comments:	This change does not affect the form / fit / function of the product

Old Version – Stamped label on rotor

ebmpapst	M2D068-BF04-04
220/380V~ 50Hz 29W 0.12A	
2400min ⁻¹ Ins.Cl.F TOP-out	
Made in Germany	

New Version - Adhesive label on cable

(This example shows a different part number than above)

The adhesive label measures 108x25 mm and will be attached to the cable.

The stamped label on the rotor will be removed.



Affected Part Numbers

M2D068-DF02-12	M4E068-DF01-05
M2E068-BF07-01	M4E068-DF01-50
M2E068-CF01-60	M4E068-DF01-85
M2E068-DF05-01	M4E068-DF01-91
M2E068-DF05-14	M4E068-DF01-92
M2E068-DF05-79	M4E068-DF47-86
M2E068-DF05-B8	M4E068-EC01-40
M2E068-DF13-79	M4E068-EC01-53
M2E068-EC01-01	M4E068-EC01-54
M2E068-EC01-22	M6E068-DF04-06
M2E068-EC07-18	R2E133-AX01-09
M4E068-CF01-01	R2E146-BF32-15
M4E068-DF01-01	R2E146-BF32-16

Form No: 1274	Quality Record - No	Page 1 of 1
Rev. – Orig, Released 08/28/14	Retention Period – 1 year	Dept. Owner – Sales/Marketing