

## **Process/Product Change Notification**

1.Company Information	on			
Company Name: MEMSIC	C Semiconductor (WUXI) Co.,Lto	d		
Address: 2 Xinhuihuan R	oad, Wuxi New District Wuxi, Jia	angsu Province		
Charger: Wei Zhen		E-Mail: zwei@memsic.com		
Tel: +86 510 66616306		Fax:		
2.Change Information				
PCN No.:	PCN02181001	Application Date:	2018/10/9	
Process/Product Affected:	5x5 Pb&Sn lid products , Refer to appendix for detailed	Implementation Date (or First Lot No.):	2018/11/9	
Customer P/N (Optional):	N/A	Last Buy Date: / Last Shipment Date: (for products before change)	N/A	
Reason of Change:	Current laser marking machine is not stable, which led to the large variation of laser mark quality. Change and upgrade type of laser mark machine to improve the marking quality.			
Anticipated Impact:	<ol> <li>No negative impact.</li> <li>Change could lead to better uniformity of laser marking and make image recognition more accurate</li> </ol>			
Change Description:	Before change: YAG laser mark machine After change: Fiber laser mark machine			
3. Qualification Plan/Results (If applicable, attach relevant supporting data/material)				
□Sample Quantity ( ) □Drawing/Spec □Inspection/Test Data or I □Environmental Data □Others ( )	or Date of Sample available( / Plan	/ )		
4.Notes				
<ol> <li>Reliability test: passed.</li> <li>Yield comparison: pass</li> <li>Clearer marking image</li> <li>Clearer marking image</li> </ol>	ed.			

Customer Acknowledgement (if Required)			
Company	Acknowledgement	Date	

## Affected Part numbers:

MXR6500EP/GP/MP MXD6235MP MXC62320MP/GP/HP/NP/EP MXC6235xQB (x=0,5) MXR7202ML MXR2999EL/GL/ML MXA2312EL/ML/GL MXA2500EL/ML/GL MXD2020EL MXS2020EL