

Notification Number:	20170307000	Notification Date:	March 8, 2017
Title:	Datasheet for TLV320AIC3104-Q1		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is updated as seen in the change revision history below:



TLV320AIC3104-Q1

SLAS715B – JUNE 2010 – REVISED FEBRUARY 2017

www.ti.com

Changes from Revision A (March 2016) to Revision B

Page

• Changed the <i>Input Impedance and VCM Control</i> section	25
• Changed the <i>Hardware Reset</i> section.....	33
• Added the <i>Receiving Notification of Documentation Updates</i> section	80
• Changed the <i>Electrostatic Discharge Caution</i> statement	80

Device Family	Change From:	Change To:
TLV320AIC3104-Q1	SLAS715A	SLAS715B

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/lit/ds/symlink/tlv320aic3104-q1.pdf>

Reason for Change:

To more accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

Changes to product identification resulting from this PCN:

None.

Product Affected:

6PAIC3104IRHBRQ1

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com