

Product change notification (PCN)

Title / short description	UK series - EX marking removal
Affected article category	Terminal blocks
Change category	Marking, Documentation, Form and appearance
Change number	CBE220143-01
Reason for PCN/PDN Revision	Data exchange errors

Purpose/objective of the change

Expiration of Ex certification

Detailed description of the change

Due to the discontinuation of EX certification, the explosion protection marking will be removed from the items.

Identifying characteristics

Lot increase on packaging

Start of Production (SOP)	-	Last Time Delivery (LTD)	-
Effective date (EOP)	2024-12-31	End of Service (EOSR)	-
End of Sales (EOS)	-		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|---|--|
| ☐ Software / Firmware Bugfix | ☐ Short-term delivery stop by supplier | ☐ Short-term recall by supplier |
| ☐ Force majeure | ☐ Product improvement with customer benefits | |
| ☐ Others | | |

Attachments

- CBE220143 - UK - Removal EX-Marking.pdf
- Material_list.csv
- PCN-CBE220143-01 UK-Serie - Entfernung der EX-Markierung_DE
- PCN-CBE220143-01 UK series - EX marking removal_EN

Material list

Item no.	Item Type	Hardware / Firmware		Item no.	Substitute item Type
old	new				
0561002	MXK 4	06	07	3248035	MUT 4
0561028	MXK 4 BU	05	06	3248036	MUT 4 BU
3003347	UK 2,5 N	07	08	3044076	UT 2,5
0719100	UK 2,5 N BK	07	08	3045088	UT 2,5 BK
3003350	UK 2,5 N BU	07	08	3044089	UT 2,5 BU
0719074	UK 2,5 N RD	07	08	3045062	UT 2,5 RD
0719090	UK 2,5 N WH	07	08	3045075	UT 2,5 WH
3038011	UK 2,5 N YE	07	08	3045059	UT 2,5 YE
3001501	UK 3 N	07	08	3044076	UT 2,5
3001514	UK 3 N BU	07	08	3044089	UT 2,5 BU
0719142	UK 3 N GN	07	08	3045091	UT 2,5 GN
0719113	UK 3 N OG	07	08	3045046	UT 2,5 OG
0719139	UK 3 N RD	07	08	3045062	UT 2,5 RD
0719126	UK 3 N YE	07	08	3045059	UT 2,5 YE
3004362	UK 5 N	06	07	3044102	UT 4
0719207	UK 5 N BG	06	07	-	-
0711344	UK 5 N BK	06	07	3045143	UT 4 BK
3007330	UK 5 N BN	06	07	3045224	UT 4 BN
3004388	UK 5 N BU	08	09	3044115	UT 4 BU
3003965	UK 5 N GN	06	07	3045156	UT 4 GN
3002908	UK 5 N OG	06	07	3045101	UT 4 OG
3026696	UK 5 N RD	06	07	3045127	UT 4 RD
3007327	UK 5 N WH	06	07	3045130	UT 4 WH
3003952	UK 5 N YE	06	07	3045114	UT 4 YE
3004524	UK 6 N	07	08	3044131	UT 6
0719236	UK 6 N BK	07	08	3045208	UT 6 BK
3004977	UK 6 N BU	07	08	3044144	UT 6 BU
0719223	UK 6 N RD	06	07	3045185	UT 6 RD
0719249	UK 6 N YE	06	07	3045172	UT 6 YE
3005073	UK 10 N	11	12	3044160	UT 10
3022328	UK 10 N BK	08	09	3046320	UT 10 BK
3005086	UK 10 N BU	12	13	3044188	UT 10 BU
3022315	UK 10 N RD	08	09	3046304	UT 10 RD
3006043	UK 16 N	09	10	3044199	UT 16
3006056	UK 16 N BU	05	06	3044209	UT 16 BU
3000570	UK 16 N GN	02	03	3044211	UT 16 GN
3000571	UK 16 N RD	02	03	3044207	UT 16 RD
3000569	UK 16 N YE	02	03	3044198	UT 16 YE

Item no.	Item Type	Hardware / Firmware		Item no.	Substitute item Type
		old	new		
3008012	UK 35	07	08	3044225	UT 35
3048315	UK 35 BK	06	07	3044226	UT 35 BK
3008025	UK 35 BU	07	08	3044238	UT 35 BU
3048328	UK 35 RD	06	07	3044227	UT 35 RD
3048219	UK 35-FE	05	06	3047676	UT 35-FE
3008009	UK 35-IB	07	08	3047727	UT 35 IB
3048072	UK 35-IB BU	07	08	3047730	UT 35 IB BU
3048154	UK 35-IB-FE	05	06	-	-
0441119	USLKG 2,5 N	08	09	3044092	UT 2,5-PE
0443081	USLKG 2,5 N-1	07	08	3044092	UT 2,5-PE
0441083	USLKG 3	06	07	3044092	UT 2,5-PE
0441106	USLKG 3-1	06	07	3044092	UT 2,5-PE
0442079	USLKG 6 N	07	08	3044157	UT 6-PE
0444048	USLKG 6 N-1	07	08	3044157	UT 6-PE
0441504	USLKG 5	07	08	3044128	UT 4-PE
0441517	USLKG 5-1	07	08	3044128	UT 4-PE
3003923	USLKG 10 N	07	08	3044173	UT 10-PE
0442082	USLKG 10 N-1	07	08	3044173	UT 10-PE
0443023	USLKG 16 N	07	08	3044212	UT 16-PE
0443036	USLKG 16 N-1	06	07	3044212	UT 16-PE
0444019	USLKG 35	06	07	3044241	UT 35-PE
0444020	USLKG 35 BK	02	03	-	-