TO: DIGIKEY -- ECN Notifications

This e-mail is to notify you of a change in the part(s) you have requested which are listed below.

| Samtec Part# | Customer Part# |
|--------------------------|-----------------------------|
| HSEC8-110-01-S-DV-A | HSEC8-110-01-S-DV-A-ND |
| HSEC8-110-01-S-DV-A-K-TR | HSEC8-110-01-S-DV-A-K-TR-ND |
| HSEC8-110-01-SM-DV-A | SAM8079-ND |
| HSEC8-110-01-SM-DV-A | SAM8079-ND |
| ECN#: 202499 | |
| Date: 05/08/13 | |

Please review the notes for specific information in regards to the nature of this change. It is Samtec's opinion that the revision will be a drop in replacement for the part you are currently using, but each customer's application is different. Please review your application to confirm that this change will not cause any disruptions. Please contact Samtec at <u>CustomerECN@samtec.com</u>, if you have any questions related to this change.

Notes:FOR -110 POSITIONS ONLY, THE OUTSIDE CARD SLOT WIDTH WAS INCREASED IN ORDER TO ALLOW THE MATING CARD TO BE INSERTED AT A LARGER ANGLE. THE OVERALL FOOTPRINT IS NOT AFFECTED. MATCHES CHANGES MADE FOR 40-100 POSITIONS MADE ON REVISION AK. THIS CHANGE WILL BE CONSIDERED AS ROLLING, ONCE CURRENT INVENTORY IS DEPLETED.