

Product Discontinuation Notice for XC9500XL, CoolRunner XPLA 3, CoolRunner II, Spartan II, and Spartan 3, 3A, 3AN, 3E, 3ADSP Product Families

XCN23009 (v1.0) January 01, 2024

**Product Discontinuation Notice** 

#### **Overview**

The purpose of this notification is to communicate that Advanced Micro Devices, Inc. is discontinuing XC9500XL<sup>™</sup>, CoolRunner<sup>™</sup> XPLA<sup>™</sup> 3, CoolRunner II, Spartan<sup>™</sup> II, and Spartan 3, 3A, 3AN, 3E, 3ADSP Commercial/ Industrial "XC" and Automotive "XA" Product Families.

### **Description**

AMD will be discontinuing XC9500XL, CoolRunner XPLA 3, CoolRunner II, Spartan II, and Spartan 3, 3A, 3AN, 3E, 3ADSP Commercial/ Industrial "XC" and Automotive "XA" Product Families due to declining run-rate and supplier sustainability reasons. This notice should be used in conjunction with previous discontinuance notices which can be found at AMD.com.

#### **Products Affected**

The products affected include standard part numbers of all temperature and speed grade variations listed in the tables below. All specification control document (SCD) versions of the standard part numbers are also affected.

Table 1: XC9500XL Products Affected

| Part Number      | Replacement Part      |
|------------------|-----------------------|
| XA95144XL-CSG144 | No direct replacement |
| XA9536XL-VQG44   | No direct replacement |
| XA9572XL-TQG100  | No direct replacement |
| XA9572XL-VQG44   | No direct replacement |
| XA9572XL-VQG64   | No direct replacement |
| XC95144XL-CS144  | No direct replacement |
| XC95144XL-CSG144 | No direct replacement |
| XC95144XL-TQ100  | No direct replacement |
| XC95144XL-TQ144  | No direct replacement |
| XC95144XL-TQG100 | No direct replacement |
| XC95144XL-TQG144 | No direct replacement |
| XC95288XL-BG256  | No direct replacement |
| XC95288XL-BGG256 | No direct replacement |
| XC95288XL-CS280  | No direct replacement |
| XC95288XL-CSG280 | No direct replacement |
| XC95288XL-FG256  | No direct replacement |
| XC95288XL-FGG256 | No direct replacement |

| Part Number      | Replacement Part      |
|------------------|-----------------------|
| XC95288XL-TQ144  | No direct replacement |
| XC95288XL-TQG144 | No direct replacement |
| XC9536XL-CS48    | No direct replacement |
| XC9536XL-CSG48   | No direct replacement |
| XC9536XL-VQ44    | No direct replacement |
| XC9536XL-VQ64    | No direct replacement |
| XC9536XL-VQG44   | No direct replacement |
| XC9536XL-VQG64   | No direct replacement |
| XC9572XL-CS48    | No direct replacement |
| XC9572XL-CSG48   | No direct replacement |
| XC9572XL-TQ100   | No direct replacement |
| XC9572XL-TQG100  | No direct replacement |
| XC9572XL-VQ44    | No direct replacement |
| XC9572XL-VQ64    | No direct replacement |
| XC9572XL-VQG44   | No direct replacement |
| XC9572XL-VQG64   | No direct replacement |



Table 2: CoolRunner XPLA3 Products Affected

| Part Number      | Replacement Part      |
|------------------|-----------------------|
| XCR3032XL-CS48   | No direct replacement |
| XCR3032XL-CSG48  | No direct replacement |
| XCR3032XL-VQ44   | No direct replacement |
| XCR3032XL-VQG44  | No direct replacement |
| XCR3064XL-CP56   | No direct replacement |
| XCR3064XL-CPG56  | No direct replacement |
| XCR3064XL-CS48   | No direct replacement |
| XCR3064XL-CSG48  | No direct replacement |
| XCR3064XL-VQ100  | No direct replacement |
| XCR3064XL-VQ44   | No direct replacement |
| XCR3064XL-VQG100 | No direct replacement |
| XCR3064XL-VQG44  | No direct replacement |
| XCR3128XL-CS144  | No direct replacement |
| XCR3128XL-CSG144 | No direct replacement |
| XCR3128XL-TQ144  | No direct replacement |
| XCR3128XL-TQG144 | No direct replacement |

Table 3: Spartan II Products Affected

| Part Number    | Replacement Part      |
|----------------|-----------------------|
| XC2S100-FG256  | No direct replacement |
| XC2S100-FGG256 | No direct replacement |
| XC2S100-TQ144  | No direct replacement |
| XC2S100-TQG144 | No direct replacement |
| XC2S150-FG256  | No direct replacement |
| XC2S150-FG456  | No direct replacement |
| XC2S150-FGG256 | No direct replacement |
| XC2S150-FGG456 | No direct replacement |
| XC2S15-TQ144   | No direct replacement |
| XC2S15-TQG144  | No direct replacement |
| XC2S15-VQ100   | No direct replacement |
| XC2S15-VQG100  | No direct replacement |
| XC2S200-FG256  | No direct replacement |

Table 4: CoolRunner II Products Affected

| Part Number    | Replacement Part      |
|----------------|-----------------------|
| XA2C128-CPG132 | No direct replacement |
| XA2C128-VQG100 | No direct replacement |
| XA2C256-TQG144 | No direct replacement |
| XA2C256-VQG100 | No direct replacement |
| XA2C32A-VQG44  | No direct replacement |
| XA2C384-TQG144 | No direct replacement |

| Part Number      | Replacement Part      |
|------------------|-----------------------|
| XCR3128XL-VQ100  | No direct replacement |
| XCR3128XL-VQG100 | No direct replacement |
| XCR3256XL-CS280  | No direct replacement |
| XCR3256XL-CSG280 | No direct replacement |
| XCR3256XL-FT256  | No direct replacement |
| XCR3256XL-FTG256 | No direct replacement |
| XCR3256XL-TQ144  | No direct replacement |
| XCR3256XL-TQG144 | No direct replacement |
| XCR3384XL-FT256  | No direct replacement |
| XCR3384XL-FTG256 | No direct replacement |
| XCR3384XL-TQ144  | No direct replacement |
| XCR3384XL-TQG144 | No direct replacement |
| XCR3512XL-FG324  | No direct replacement |
| XCR3512XL-FGG324 | No direct replacement |
| XCR3512XL-FT256  | No direct replacement |
| XCR3512XL-FTG256 | No direct replacement |

| Part Number    | Replacement Part      |
|----------------|-----------------------|
| XC2S200-FG456  | No direct replacement |
| XC2S200-FGG256 | No direct replacement |
| XC2S200-FGG456 | No direct replacement |
| XC2S30-CS144   | No direct replacement |
| XC2S30-CSG144  | No direct replacement |
| XC2S30-TQ144   | No direct replacement |
| XC2S30-TQG144  | No direct replacement |
| XC2S30-VQ100   | No direct replacement |
| XC2S30-VQG100  | No direct replacement |
| XC2S50-FG256   | No direct replacement |
| XC2S50-FGG256  | No direct replacement |
| XC2S50-TQ144   | No direct replacement |
| XC2S50-TQG144  | No direct replacement |

| Part Number   | Replacement Part      |
|---------------|-----------------------|
| XC2C32A-CPG56 | No direct replacement |
| XC2C32A-DIE   | No direct replacement |
| XC2C32A-QFG32 | No direct replacement |
| XC2C32A-VQ44  | No direct replacement |
| XC2C32A-VQG44 | No direct replacement |
| XC2C384-FG324 | No direct replacement |



Table 4: CoolRunner II Products Affected (Continued)

| Part Number    | Replacement Part      |
|----------------|-----------------------|
| XA2C64A-VQG100 | No direct replacement |
| XA2C64A-VQG44  | No direct replacement |
| XC2C128-CP132  | No direct replacement |
| XC2C128-CPG132 | No direct replacement |
| XC2C128-DIE    | No direct replacement |
| XC2C128-TQ144  | No direct replacement |
| XC2C128-TQG144 | No direct replacement |
| XC2C128-VQ100  | No direct replacement |
| XC2C128-VQG100 | No direct replacement |
| XC2C256-CP132  | No direct replacement |
| XC2C256-CPG132 | No direct replacement |
| XC2C256-FT256  | No direct replacement |
| XC2C256-FTG256 | No direct replacement |
| XC2C256-TQ144  | No direct replacement |
| XC2C256-TQG144 | No direct replacement |
| XC2C256-VQ100  | No direct replacement |
| XC2C256-VQG100 | No direct replacement |
| XC2C32A-CP56   | No direct replacement |

| Part Number    | Replacement Part      |
|----------------|-----------------------|
| XC2C384-FGG324 | No direct replacement |
| XC2C384-FT256  | No direct replacement |
| XC2C384-FTG256 | No direct replacement |
| XC2C384-TQ144  | No direct replacement |
| XC2C384-TQG144 | No direct replacement |
| XC2C512-FG324  | No direct replacement |
| XC2C512-FGG324 | No direct replacement |
| XC2C512-FT256  | No direct replacement |
| XC2C512-FTG256 | No direct replacement |
| XC2C64A-CP56   | No direct replacement |
| XC2C64A-CPG56  | No direct replacement |
| XC2C64A-DIE    | No direct replacement |
| XC2C64A-QFG48  | No direct replacement |
| XC2C64A-VQ100  | No direct replacement |
| XC2C64A-VQ44   | No direct replacement |
| XC2C64A-VQG100 | No direct replacement |
| XC2C64A-VQG44  | No direct replacement |

Table 5: Spartan 3, 3A, 3AN, 3E, 3ADSP Products Affected

| Part Number     | Replacement Part      |
|-----------------|-----------------------|
| XA3S1000-FG456  | No direct replacement |
| XA3S1000-FGG456 | No direct replacement |
| XA3S1500-FGG676 | No direct replacement |
| XA3S200-FTG256  | No direct replacement |
| XA3S200-VQG100  | No direct replacement |
| XA3S400-FGG456  | No direct replacement |
| XA3S400-FTG256  | No direct replacement |
| XA3S50-VQG100   | No direct replacement |
| XC3S1000-FG320  | No direct replacement |
| XC3S1000-FG456  | No direct replacement |
| XC3S1000-FG676  | No direct replacement |
| XC3S1000-FGG320 | No direct replacement |
| XC3S1000-FGG456 | No direct replacement |
| XC3S1000-FGG676 | No direct replacement |
| XC3S1000-FT256  | No direct replacement |
| XC3S1000-FTG256 | No direct replacement |
| XC3S1500-FG320  | No direct replacement |

| Part Number       | Replacement Part      |
|-------------------|-----------------------|
| XC3S50A-VQ100     | No direct replacement |
| XC3S50A-VQG100    | No direct replacement |
| XC3S700A-FG400    | No direct replacement |
| XC3S700A-FG484    | No direct replacement |
| XC3S700A-FGG400   | No direct replacement |
| XC3S700A-FGG484   | No direct replacement |
| XC3S700A-FT256    | No direct replacement |
| XC3S700A-FTG256   | No direct replacement |
| XC3S1400AN-FG676  | No direct replacement |
| XC3S1400AN-FGG676 | No direct replacement |
| XC3S200AN-FT256   | No direct replacement |
| XC3S200AN-FTG256  | No direct replacement |
| XC3S400AN-FG400   | No direct replacement |
| XC3S400AN-FGG400  | No direct replacement |
| XC3S400AN-FT256   | No direct replacement |
| XC3S400AN-FTG256  | No direct replacement |
| XC3S50AN-TQ144    | No direct replacement |



Table 5: Spartan 3, 3A, 3AN, 3E, 3ADSP Products Affected (Continued)

| Part Number      | Replacement Part      |  |
|------------------|-----------------------|--|
| XC3S1500-FG456   | No direct replacement |  |
| XC3S1500-FG676   | No direct replacement |  |
| XC3S1500-FGG320  | No direct replacement |  |
| XC3S1500-FGG456  | No direct replacement |  |
| XC3S1500-FGG676  | No direct replacement |  |
| XC3S2000-FG456   | No direct replacement |  |
| XC3S2000-FG676   | No direct replacement |  |
| XC3S2000-FG900   | No direct replacement |  |
| XC3S2000-FGG456  | No direct replacement |  |
| XC3S2000-FGG676  | No direct replacement |  |
| XC3S2000-FGG900  | No direct replacement |  |
| XC3S200-FT256    | No direct replacement |  |
| XC3S200-FTG256   | No direct replacement |  |
| XC3S200-TQ144    | No direct replacement |  |
| XC3S200-TQG144   | No direct replacement |  |
| XC3S200-VQ100    | No direct replacement |  |
| XC3S200-VQG100   | No direct replacement |  |
| XC3S4000-FG676   | No direct replacement |  |
| XC3S4000-FG900   | No direct replacement |  |
| XC3S4000-FGG676  | No direct replacement |  |
| XC3S4000-FGG900  | No direct replacement |  |
| XC3S400-FG320    | No direct replacement |  |
| XC3S400-FG456    | No direct replacement |  |
| XC3S400-FGG320   | No direct replacement |  |
| XC3S400-FGG456   | No direct replacement |  |
| XC3S400-FT256    | No direct replacement |  |
| XC3S400-FTG256   | No direct replacement |  |
| XC3S400-TQ144    | No direct replacement |  |
| XC3S400-TQG144   | No direct replacement |  |
| XC3S5000-FG676   | No direct replacement |  |
| XC3S5000-FG900   | No direct replacement |  |
| XC3S5000-FGG676  | No direct replacement |  |
| XC3S5000-FGG900  | No direct replacement |  |
| XC3S50-TQ144     | No direct replacement |  |
| XC3S50-TQG144    | No direct replacement |  |
| XC3S50-VQ100     | No direct replacement |  |
| XC3S50-VQG100    | No direct replacement |  |
| XA3S1400A-FGG484 | No direct replacement |  |

| Part Number      | Replacement Part      |  |
|------------------|-----------------------|--|
| XC3S50AN-TQG144  | No direct replacement |  |
| XC3S700AN-FG484  | No direct replacement |  |
| XC3S700AN-FGG484 | No direct replacement |  |
| XA3S100E-CPG132  | No direct replacement |  |
| XA3S100E-TQG144  | No direct replacement |  |
| XA3S100E-VQG100  | No direct replacement |  |
| XA3S1200E-FGG400 | No direct replacement |  |
| XA3S1200E-FTG256 | No direct replacement |  |
| XA3S1600E-FG400  | No direct replacement |  |
| XA3S1600E-FGG400 | No direct replacement |  |
| XA3S1600E-FGG484 | No direct replacement |  |
| XA3S250E-CPG132  | No direct replacement |  |
| XA3S250E-FT256   | No direct replacement |  |
| XA3S250E-FTG256  | No direct replacement |  |
| XA3S250E-TQG144  | No direct replacement |  |
| XA3S250E-VQG100  | No direct replacement |  |
| XA3S500E-CPG132  | No direct replacement |  |
| XA3S500E-FT256   | No direct replacement |  |
| XA3S500E-FTG256  | No direct replacement |  |
| XC3S100E-CP132   | No direct replacement |  |
| XC3S100E-CPG132  | No direct replacement |  |
| XC3S100E-TQ144   | No direct replacement |  |
| XC3S100E-TQG144  | No direct replacement |  |
| XC3S100E-VQ100   | No direct replacement |  |
| XC3S100E-VQG100  | No direct replacement |  |
| XC3S1200E-DIE    | No direct replacement |  |
| XC3S1200E-FG320  | No direct replacement |  |
| XC3S1200E-FG400  | No direct replacement |  |
| XC3S1200E-FGG320 | No direct replacement |  |
| XC3S1200E-FGG400 | No direct replacement |  |
| XC3S1200E-FT256  | No direct replacement |  |
| XC3S1200E-FTG256 | No direct replacement |  |
| XC3S1600E-FG320  | No direct replacement |  |
| XC3S1600E-FG400  | No direct replacement |  |
| XC3S1600E-FG484  | No direct replacement |  |
| XC3S1600E-FGG320 | No direct replacement |  |
| XC3S1600E-FGG400 | No direct replacement |  |
| XC3S1600E-FGG484 | No direct replacement |  |

Table 5: Spartan3, 3A, 3AN, 3E, 3ADSP Products Affected (Continued)

| Part Number      | Replacement Part      |  |
|------------------|-----------------------|--|
| XA3S200A-FTG256  | No direct replacement |  |
| XA3S400A-FGG400  | No direct replacement |  |
| XA3S400A-FTG256  | No direct replacement |  |
| XC3S1400A-FG484  | No direct replacement |  |
| XC3S1400A-FG676  | No direct replacement |  |
| XC3S1400A-FGG484 | No direct replacement |  |
| XC3S1400A-FGG676 | No direct replacement |  |
| XC3S1400A-FT256  | No direct replacement |  |
| XC3S1400A-FTG256 | No direct replacement |  |
| XC3S200A-FG320   | No direct replacement |  |
| XC3S200A-FGG320  | No direct replacement |  |
| XC3S200A-FT256   | No direct replacement |  |
| XC3S200A-FTG256  | No direct replacement |  |
| XC3S200A-VQ100   | No direct replacement |  |
| XC3S200A-VQG100  | No direct replacement |  |
| XC3S400A-FG320   | No direct replacement |  |
| XC3S400A-FG400   | No direct replacement |  |
| XC3S400A-FGG320  | No direct replacement |  |
| XC3S400A-FGG400  | No direct replacement |  |
| XC3S400A-FT256   | No direct replacement |  |
| XC3S400A-FTG256  | No direct replacement |  |
| XC3S50A-FT256    | No direct replacement |  |
| XC3S50A-FTG256   | No direct replacement |  |
| XC3S50A-TQ144    | No direct replacement |  |
| XC3S50A-TQG144   | No direct replacement |  |
|                  |                       |  |

| Part Number       | Replacement Part      |  |
|-------------------|-----------------------|--|
| XC3S250E-CP132    | No direct replacement |  |
| XC3S250E-CPG132   | No direct replacement |  |
| XC3S250E-FT256    | No direct replacement |  |
| XC3S250E-FTG256   | No direct replacement |  |
| XC3S250E-TQ144    | No direct replacement |  |
| XC3S250E-TQG144   | No direct replacement |  |
| XC3S250E-VQ100    | No direct replacement |  |
| XC3S250E-VQG100   | No direct replacement |  |
| XC3S500E-CP132    | No direct replacement |  |
| XC3S500E-CPG132   | No direct replacement |  |
| XC3S500E-FG320    | No direct replacement |  |
| XC3S500E-FGG320   | No direct replacement |  |
| XC3S500E-FT256    | No direct replacement |  |
| XC3S500E-FTG256   | No direct replacement |  |
| XC3S500E-VQG100   | No direct replacement |  |
| XA3SD1800A-CSG484 | No direct replacement |  |
| XA3SD1800A-FGG676 | No direct replacement |  |
| XC3SD1800A-CS484  | No direct replacement |  |
| XC3SD1800A-CSG484 | No direct replacement |  |
| XC3SD1800A-FG676  | No direct replacement |  |
| XC3SD1800A-FGG676 | No direct replacement |  |
| XC3SD3400A-CS484  | No direct replacement |  |
| XC3SD3400A-CSG484 | No direct replacement |  |
| XC3SD3400A-FG676  | No direct replacement |  |
| XC3SD3400A-FGG676 | No direct replacement |  |

## **Key Dates and Ordering Information**

- Final orders (LTB) will be accepted until June 29th, 2024, subject to material availability.
- An order remaining open on or after April 30<sup>th</sup>, 2024, will be deemed Non-Cancellable, Non-Returnable (NCNR).
- Final deliveries (LTS) must occur on or before December 28<sup>th</sup>, 2024.
- Return Material Authorizations (RMA) for replacement devices due to quality issues will be accepted until June 27<sup>th</sup>, 2025.

## Response

No response required.

Customers are requested to place last-time-buy orders in a timely manner prior to the key dates listed above to avoid product availability issues. If you anticipate that your last time buy requirements will exceed the current rate, please provide your AMD Sales Representative with a forecast of the requirements. All orders will be supported on a first-come, first-served basis with the non-cancellable and non-returnable (NCNR) condition. For additional information or questions, contact your local AMD Sales representative.



**Important Notice**: AMD Customer Notifications (XCNs, XDNs, and Quality Alerts) can be delivered via e-mail alerts sent by the Support website (<a href="http://www.xilinx.com/support">http://www.xilinx.com/support</a>). Register today and personalize your "Documentation and Design Advisory Alerts" area to include Customer Notifications. AMD Support provides many benefits, including the ability to receive alerts for new and updated information about specific products, as well as alerts for other publications such as data sheets, errata, application notes, etc. For information on how to sign up, refer to Xilinx Answer Record 18683.

# **Revision History**

The following table shows the revision history for this document.

| Date       | Version | Revision        |
|------------|---------|-----------------|
| 01/01/2024 | 1.0     | Initial release |



# **Please Read: Important Legal Notices**

The information presented in this document is for informational purposes only and may contain technical inaccuracies, omissions, and typographical errors. The information contained herein is subject to change and may be rendered inaccurate for many reasons, including but not limited to product and roadmap changes, component and motherboard version changes, new model and/or product releases, product differences between differing manufacturers, software changes, BIOS flashes, firmware upgrades, or the like. Any computer system has risks of security vulnerabilities that cannot be completely prevented or mitigated. AMD assumes no obligation to update or otherwise correct or revise this information. However, AMD reserves the right to revise this information and to make changes from time to time to the content hereof without obligation of AMD to notify any person of such revisions or changes. THIS INFORMATION IS PROVIDED "AS IS." AMD MAKES NO REPRESENTATIONS OR WARRANTIES WITH RESPECT TO THE CONTENTS HEREOF AND ASSUMES NO RESPONSIBILITY FOR ANY INACCURACIES, ERRORS, OR OMISSIONS THAT MAY APPEAR IN THIS INFORMATION. AMD SPECIFICALLY DISCLAIMS ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, OR FITNESS FOR ANY PARTICULAR PURPOSE. IN NO EVENT WILL AMD BE LIABLE TO ANY PERSON FOR ANY RELIANCE, DIRECT, INDIRECT, SPECIAL, OR OTHER CONSEQUENTIAL DAMAGES ARISING FROM THE USE OF ANY INFORMATION CONTAINED HEREIN, EVEN IF AMD IS EXPRESSLY ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

#### **AUTOMOTIVE APPLICATIONS DISCLAIMER**

AUTOMOTIVE PRODUCTS (IDENTIFIED AS "XA" IN THE PART NUMBER) ARE NOT WARRANTED FOR USE IN THE DEPLOYMENT OF AIRBAGS OR FOR USE IN APPLICATIONS THAT AFFECT CONTROL OF A VEHICLE ("SAFETY APPLICATION") UNLESS THERE IS A SAFETY CONCEPT OR REDUNDANCY FEATURE CONSISTENT WITH THE ISO 26262 AUTOMOTIVE SAFETY STANDARD ("SAFETY DESIGN"). CUSTOMER SHALL, PRIOR TO USING OR DISTRIBUTING ANY SYSTEMS THAT INCORPORATE PRODUCTS, THOROUGHLY TEST SUCH SYSTEMS FOR SAFETY PURPOSES. USE OF PRODUCTS IN A SAFETY APPLICATION WITHOUT A SAFETY DESIGN IS FULLY AT THE RISK OF CUSTOMER, SUBJECT ONLY TO APPLICABLE LAWS AND REGULATIONS GOVERNING LIMITATIONS ON PRODUCT LIABILITY.

© Copyright 2024 Advanced Micro Devices, Inc. AMD, the AMD Arrow logo, ISP, CPLD, XPLA, CoolRunner, Spartan and combinations thereof are trademarks of Advanced Micro Devices, Inc. Other product names used in this publication are for identification purposes only and may be trademarks of their respective companies.