



PRODUCT CHANGE NOTIFICATION

MULTIFUSE® PPTC RESETTABLE FUSES



Bourns® Model MF-RX/250 Series Multifuse® PPTC Resettable Fuses

Change of Coating Material

Riverside, California - December 13, 2023 – Effective February 29, 2024, Bourns will change the coating material of the [Model MF-RX/250 Series Multifuse® PPTC Resettable Fuses](#) as part of its ongoing material management optimization. The affected part numbers are listed below.

Affected Part Numbers			
MF-RX012/250-0	MF-RX012/250-2	MF-RX012/250-A-0	MF-RX012/250-A-2
MF-RX012/250-C-0	MF-RX012/250-C-2	MF-RX012/250-F-0	MF-RX012/250-F-2
MF-RX012/250-G-0	MF-RX012/250-G-2	MF-RX012/250-H-0	MF-RX012/250-H-2
MF-RX012/250-T-0	MF-RX012/250-T-2	MF-RX012/250-1-0	MF-RX012/250-1-2
MF-RX012/250-2-0	MF-RX012/250-2-2	MF-RX012/250U-0	MF-RX012/250U-2
MF-RX012/250-0-E6	MF-RX012/250-205-2	MF-RX012/250-A05-2	MF-RX012/250-F05-2
MF-RX012/250-T05-2			
MF-RX014/250-0	MF-RX014/250-2	MF-RX014/250-A-0	MF-RX014/250-A-2
MF-RX014/250-B-0	MF-RX014/250-B-2	MF-RX014/250-C-0	MF-RX014/250-C-2
MF-RX014/250-T-0	MF-RX014/250-T-2	MF-RX014/250U-0	MF-RX014/250U-2
MF-RX014/250-A05-0	MF-RX014/250-A05-2	MF-RX014/250-T05-0	MF-RX014/250-0-AZ
MF-RX014/250-0-V4			
MF-RX018/250-0	MF-RX018/250-2	MF-RX018/250U-0	MF-RX018/250U-2
MF-RX018/250-0-V3			

Bourns has completed its evaluation of the alternative coating materials from the supplier. There is no change to the fit, form, function, quality or reliability of the affected part numbers. The Model MF-RX/250 Series with the replacement material will continue to be RoHS compliant* and halogen free**. Samples and test reports are available upon request.

Bourns recommends that customers test the affected part numbers made with the new coating material in their specific applications for verification of satisfactory performance.

Implementation dates are as follows:

Last time buy date for products with current coating material: February 29, 2024

Last time ship date for products with current coating material: March 31, 2024

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).

Users should verify that the described changes will not impact the performance of the product in their specific applications.

*RoHS Directive 2015/863, Mar 31, 2015 and Annex.

**Bourns considers a product to be "halogen free" if (a) the Bromine (Br) content is 900 ppm or less; (b) the Chlorine (Cl) content is 900 ppm or less; and (c) the total Bromine (Br) and Chlorine (Cl) content is 1500 ppm or less.

MF2332