

**ROHM Co., Ltd.**

21 Saiin Mizosaki-cho, Ukyo-ku,
Kyoto 615-8585 Japan
TEL:+81-75-311-2121 FAX:+81-75-315-0172
<http://www.rohm.com>

Notification of Product Discontinuance**Doc. No.: 03082024**

This letter intends as a formal notification of discontinuance of products supplied by ROHM Co., Ltd.

Please refer to the attached PN list. ROHM Co., Ltd. requires customers to provide acknowledgment of the receipt of this notification within 30 days from the date of this notice. Lack of acknowledgment of this notice within 30 days is considered as acceptance of the change.

After acknowledgement of the customer, lack of additional response within 90 day period constitutes acceptance of the change according to JEDEC Standard J-STD-046.

Issue Date: March 8th, 2024

Product category	Affected part number(s)	Suggested replacement product
	Please see attached file.	Please see attached file.
<u>Reason for discontinuance</u> The parts in attached file have been EOL for quite some time and there should be no longer be any existing business related to them. In an effort to clean up our cost book with our distributors, we're supplying this PCN/EOL notice to make sure your systems are properly showing all of these as EOL. Thank you for your support. Please notify us of any issues or concerns. There will be no LTB or LTS related to this EOL notice.		
<u>Product discontinuance date</u> Last time buy : N/A / Last time shipment : N/A		
<u>Supplier contact</u> Please contact the local ROHM sales office or the authorized distributor.		

Product	ROHMPart	Alt Part Number
10 - IC	BA036LBSG2-TR	BD00IC0WHFV-GTR
10 - IC	BA038LBSG2-TR	BD00IC0WHFV-GTR
10 - IC	BA040LBSG2-TR	BD00IC0WHFV-GTR
10 - IC	BA09CC0WT-V5	BD90FD0EHFP-MTR
10 - IC	BA14741FJ-GE2	N/A
10 - IC	BA15BC0WT-V5	N/A
10 - IC	BA18BC0WT-V5	BA18BC0WT
10 - IC	BA25F18WHFP-TR	N/A
10 - IC	BA3257FP-E2	N/A
10 - IC	BA3258HFP-TR	N/A
10 - IC	BA33BC0WT-V5	BA33BC0WT
10 - IC	BA3404FJ-GE2	BA3404FVM-TR
10 - IC	BA3472FVT-GE2	BA3472FVM-TR
10 - IC	BA3834F-E2	N/A
10 - IC	BA50BB2RF-E2	N/A
10 - IC	BA6162F-E2	N/A
10 - IC	BA6235F-E2	N/A
10 - IC	BA7808CP-E2	BA17808CP-E2
10 - IC	BA7809CP-E2	BA17809CP-E2
10 - IC	BA7810CP-E2	BA17810CP-E2
10 - IC	BA7818CP-E2	BA17818CP-E2
10 - IC	BA7820CP-E2	BA17820CP-E2
10 - IC	BA7824CP-E2	BA17824CP-E2
10 - IC	BA78M06CP-E2	BA178M06CP-E2
10 - IC	BA78M07CP-E2	BA178M07CP-E2
10 - IC	BA78M07FP-E2	BA178M07FP-E2
10 - IC	BA78M08CP-E2	BA178M08CP-E2
10 - IC	BA78M09CP-E2	BA178M09CP-E2
10 - IC	BA78M10CP-E2	BA178M10CP-E2
10 - IC	BA78M12CP-E2	BA178M12CP-E2
10 - IC	BA78M15CP-E2	BA178M15CP-E2
10 - IC	BA78M15FP-E2	BA178M15FP-E2
10 - IC	BA78M18CP-E2	BA178M18CP-E2
10 - IC	BA78M20CP-E2	BA178M20CP-E2
10 - IC	BA78M24CP-E2	BA178M24CP-E2
10 - IC	BD3433K-E2	Similar : BD34701KS2 or BD34705KS2, However these are for consumer not for car Audio
10 - IC	BD3805F-E2	Similar : BD37033FV-ME2
10 - IC	BD6066EKN-E2	N/A
10 - IC	BD7881GU-E2	N/A
10 - IC	BD7998EFS-E2	N/A
10 - IC	BD8355MWV-BZE2	N/A
10 - IC	BD9740KN-E2	N/A
10 - IC	BD9886F-E2	N/A
10 - IC	BD9888F-E2	N/A
10 - IC	BD9888FV-E2	N/A
10 - IC	BH1415F-E2	N/A
10 - IC	BH1415FV-E2	N/A
10 - IC	BH3852FS-E2	N/A
10 - IC	BH6578FVM-TR	N/A
10 - IC	BH7236AF-E2	N/A
10 - IC	BH7823AFVM-TR	N/A
10 - IC	BH7826FVM-TR	N/A

10 - IC	BH7868FS-E2	N/A
10 - IC	BH7881EFV-E2	Functional replacement : BD7836EFV+BH3547F. Using 2pcs, Evaluation Required.
10 - IC	BH7884EFV-E2	N/A
10 - IC	BM6202FS-E2	Pin Compatible : BM6242FS-E2
10 - IC	BM6203FS-E2	Pin Compatible : BM6243FS-E2
10 - IC	BM6204FS-E2	Pin Compatible : BM6245FS-E2
10 - IC	BM6205FS-E2	Pin Compatible : BM6246FS-E2
10 - IC	BM6206FS-E2	Pin Compatible : BM6245FS-E2
10 - IC	BM6207FS-E2	Pin Compatible : BM6246FS-E2
10 - IC	BM6208FS-E2	Pin Compatible : BM6248FS-E2
10 - IC	BM6209FS-E2	Pin Compatible : BM6249FS-E2
10 - IC	BM6214FS-E2	Pin Compatible : BM6244FS-E2
10 - IC	BR24C04-10TU-2.7	N/A
10 - IC	BR24C08A-10TU-1.8	N/A
10 - IC	BR24C08A-10TU-2.7	N/A
10 - IC	BR24C16A-10TU-1.8	N/A
10 - IC	BR24C32A-10TU-1.8	N/A
10 - IC	BR24C32A-10TU-2.7	N/A
10 - IC	BR25010-10TU-1.8	N/A
10 - IC	BR25010-10TU-2.7	N/A
10 - IC	BR25010N-10SU-1.8	N/A
10 - IC	BR25010N-10SU-2.7	N/A
10 - IC	BR25020-10TU-1.8	N/A
10 - IC	BR25020-10TU-2.7	N/A
10 - IC	BR25020N-10SU-1.8	N/A
10 - IC	BR25040-10TU-1.8	N/A
10 - IC	BR25040-10TU-2.7	N/A
10 - IC	BR25040N-10SU-1.8	N/A
10 - IC	BR25040N-10SU-2.7	N/A
10 - IC	BR25080-10TU-1.8	N/A
10 - IC	BR25080-10TU-2.7	N/A
10 - IC	BR25080N-10SU-1.8	N/A
10 - IC	BR25080N-10SU-2.7	N/A
10 - IC	BR25160-10TU-1.8	N/A
10 - IC	BR25160-10TU-2.7	N/A
10 - IC	BR25160N-10SU-1.8	N/A
10 - IC	BR25160N-10SU-2.7	N/A
10 - IC	BR25320N-10SU-1.8	N/A
10 - IC	BR25320N-10SU-2.7	N/A
10 - IC	BR25640N-10SU-2.7	N/A
10 - IC	BR93C46-10TU-1.8	N/A
10 - IC	BR93C46-10TU-2.7	N/A
10 - IC	BU21010MUV-E2	N/A
10 - IC	BU6568GV-E2	N/A
10 - IC	BU6582GVW-E2	N/A
10 - IC	BU7680G-TR	N/A
10 - IC	BU7876GLS-E2	N/A
10 - IC	BU8040GSW-E2	N/A
10 - IC	BU8766FV-E2	N/A
10 - IC	KX122-1037	KXTJ3-1057
10 - IC	KX123-1039	KXTJ3-1057
10 - IC	KX224-1053	KX134-1211
10 - IC	LM2902KVQPWR	LM2902FV-E2

10 - IC	LM324DT	LM324FV-GE2
16 - OED	ML610Q408P-NNNTB0AAL	N/A
16 - OED	ML610Q409P-NNNTB0AAL	N/A
16 - OED	ML610Q411P-NNNTB0ARL	N/A
16 - OED	ML610Q421P-NNNTB0ARL	N/A
16 - OED	ML610Q422P-NNNTB0ARL	N/A
16 - OED	ML610Q435A-NNNTC0AAL	N/A
16 - OED	ML610Q438P-NNNTC0AAL	N/A
16 - LSI	ML7213LAZ07FL	N/A
16 - LSI	ML7223LAZ07F	N/A
16 - LSI	ML7223LAZ07FL	N/A
22 - HPD	SCS120KGC	N/A
30 - TR	R5019ANJTL	R6020ENJTL
30 - TR	RSH140N03TB1	RS3E135BNGZETB
30 - TR	SH8M4TB1	SH8MA4TB1
30 - TR	ZDX050N50	N/A
30 - TR	ZDX080N50	N/A
30 - TR	ZDX130N50	N/A
40 - DI	RB551V-30FTE-17	N/A
48 - OPM	LA-101MA	N/A
48 - OPM	LA-101VA	N/A
48 - OPM	LA-101VK	N/A
48 - OPM	LA-301BL	N/A
48 - OPM	LAP-601DL	N/A
48 - OPM	LB-302VF	N/A
50 - LED	SPR-325MVWT31	N/A