



Advance Product Change Notification

202306009A : DIE ATTACH GLUE CHANGE DUE TO HENKEL 8388A DISCONTINUATION

Note: This notice is NXP Company Proprietary.

Issue Date: Jun 16, 2023

Here is your personalized notification about a NXP general announcement.
For detailed information we invite you to view this notification online

Management summary

For all MOA4 and MOA8 the used die attached glue Henkel LOCTITE ABLESTIK 8388A will change to Henkel LOCTITE ABLESTIK ABP 2035SCR.

The existing die attach glue has been discontinued by our supplier in December 2022. NXP could arrange enough die attach glue to be able to produce until November 2023.

The new die attach glue has been carefully selected to enhance the overall performance and durability of the product while ensuring compliance with the Registration, Evaluation, Authorization, and Restriction of Chemicals (REACH) regulations.

Change Category

☐ Wafer Fab Process	☒ Assembly Process	☐ Product Marking	☐ Test Process	☐ Design
☐ Wafer Fab Materials	☒ Assembly Materials	☐ Mechanical Specification	☐ Test Equipment	☐ Errata
☐ Wafer Fab Location	☐ Assembly Location	☐ Packing/Shipping/Labeling	☐ Test Location	☐ Electrical spec./Test coverage
☐ Firmware ☐ Other				

PCN Overview

Description

The die attach glue used between the chip and lead frame in chip on lead frame packaging serves as a bonding material to securely attach the chip to the lead frame.

This die attach adhesive is changed from Henkel LOCTITE ABLESTIK 8388A to Henkel LOCTITE ABLESTIK ABP 2035SCR for all MOA4 and MOA8 packages.

There are no changes to the form, fit and function of the MOA4 and MOA8 modules due to the changeover to the new die attach glue. The revised module continues to offer the same high-quality performance and reliability and complies with REACH standards. Attached to this notification, you will find the Qualification Plan which outlines the qualification procedures and criteria for the revised module.

Reason

The existing die attach glue has been discontinued by our supplier in December 2022. NXP could arrange enough die attach glue to be able to produce until November 2023.

Identification of Affected Products

Product identification does not change

Product Availability

Sample Information

Samples are available upon request

Production

Planned first shipment Dec 31, 2023

Anticipated Impact on Form, Fit, Function, Reliability or Quality

No Impact on form, fit, function, reliability or quality

Data Sheet Revision

No impact to existing datasheet

Disposition of Old Products

Existing inventory will be shipped until depleted

Additional information

Self qualification: [view online](#)

Timing and Logistics

The Self Qualification Report will be ready on Sep 04, 2023.

The Final PCN is planned to be issued on: Sep 04, 2023.

In compliance with JEDEC J-STD-046, your acknowledgement of this change is expected by Jul 16, 2023.

Contact and Support

For all inquiries regarding the ePCN tool application or access issues, please contact NXP "Global Quality Support Team".

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

For specific questions on this notice or the products affected please contact our specialist directly:

Name	Olaf Dichte
Position	Senior Quality Engineer
e-mail address	Olaf.Dichte@nxp.com

At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards. Customer Focus, Passion to Win.

NXP Quality Management Team.

About NXP Semiconductors

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

You have received this email because you are a designated contact or subscribed to NXP Quality Notifications. NXP shall not be held liable if this Notification is not correctly distributed within your

organization.

This message has been automatically distributed. Please do not reply.

NXP Semiconductors
High Tech Campus, 5656 AG Eindhoven, The Netherlands

© 2006-2023 NXP Semiconductors. All rights reserved.

Orderable Part Number#	12NC	Product Type	Product Description	Package Outline	Package Description	Product Status	Customer Specific Indicator	Product Line
MF0U12101DA8,118	935298252118	MF0U12101DA8	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF3D43C0DA4/00J	935405168118	MF3D43C0DA4/00	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF3D83C0DA4/00J	935404601118	MF3D83C0DA4/00	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF1P4220DA8/00TGJ	935419789118	MF1P4220DA8/00TG	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF1P2200DA8/00MOJ	935405847118	MF1P2200DA8/00MO	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF1P4230DA4/00J	935404438118	MF1P4230DA4/00	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF1P4230DA8/00J	935405059118	MF1P4230DA8/00	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF3D4300DA8/00J	935388158118	MF3D4300DA8/00	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF3D23C0DA8/00J	935405164118	MF3D23C0DA8/00	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF3DH8300DA4/00J	935402531118	MF3DH8300DA4/00	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF3DH8300DA8/00J	935402939118	MF3DH8300DA8/00	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF1P2230DA8/00J	935405173118	MF1P2230DA8/00	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF1PH2200DA8/00J	935405195118	MF1PH2200DA8/00	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF1PH4200DA4/00J	935383641118	MF1PH4200DA4/00	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF1PH4200DA8/00J	935383641118	MF1PH4200DA8/00	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF3D4300DA4/00J	935388157118	MF3D4300DA4/00	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF3DH2300DA8/00J	935405198118	MF3DH2300DA8/00	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF3DH4300DA8/00J	935405163118	MF3DH4300DA8/00	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF3DH43C0DA8/00J	935405213118	MF3DH43C0DA8/00	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF1PH2230DA8/00J	935405201118	MF1PH2230DA8/00	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF3D2300DA4/00J	935388053118	MF3D2300DA4/00	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF3DH83C0DA8/00J	935405214118	MF3DH83C0DA8/00	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF3DH2300DA4/00J	935402675118	MF3DH2300DA4/00	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF3DH4300DA4/00J	935404602118	MF3DH4300DA4/00	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF3DH23C0DA4/00J	935405202118	MF3DH23C0DA4/00	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF3DH43C0DA4/00J	935405207118	MF3DH43C0DA4/00	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF1PH4230DA8/00J	935405061118	MF1PH4230DA8/00	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF1PH4230DA4/00J	935404209118	MF1PH4230DA4/00	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF1P4200DA8/00MOJ	935405845118	MF1P4200DA8/00MO	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF3D2300DA8/00J	935388156118	MF3D2300DA8/00	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF3DH83C0DA4/00J	935405208118	MF3DH83C0DA4/00	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF1PH2230DA4/00J	935405199118	MF1PH2230DA4/00	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF3D83C0DA8/00J	935405069118	MF3D83C0DA8/00	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF3DH23C0DA8/00J	935405209118	MF3DH23C0DA8/00	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF1P4200DA8/00J	935404786118	MF1P4200DA8/00	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF1P4200DA4/00J	935399739118	MF1P4200DA4/00	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF1P2200DA4/00J	935404211118	MF1P2200DA4/00	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF1P2200DA8/00J	935387932118	MF1P2200DA8/00	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF1PH2200DA4/00J	935405183118	MF1PH2200DA4/00	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF1P4220DA4/00TGJ	935419103118	MF1P4220DA4/00TG	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF3D8300DA4/00J	935383963118	MF3D8300DA4/00	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF3D8300DA8/00J	935383964118	MF3D8300DA8/00	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF1P2230DA4/00J	935402951118	MF1P2230DA4/00	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF3D23C0DA4/00J	935405165118	MF3D23C0DA4/00	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF3D43C0DA8/00J	935405172118	MF3D43C0DA8/00	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF2DLH1000DA8/02J	935378413118	MF2DLH1000DA8/02	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF0AES2000DA8J	935423973118	MF0AES2000DA8	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF0AESH2000DA8J	935428914118	MF0AESH2000DA8	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF2DL1000DA4/02J	935378414118	MF2DL1000DA4/02	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF2DLH1000DA4/02J	935378415118	MF2DLH1000DA4/02	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
NT2H1311G0DA8J	935304624118	NT2H1311G0DA8	NFC Tags	CLM2M	SOT500-4	RFS	No	BLT1
NT2H1511G0DA8J	935304625118	NT2H1511G0DA8	NFC Tags	CLM2M	SOT500-4	RFS	No	BLT1
NT2H1611G0DA8J	935304626118	NT2H1611G0DA8	NFC Tags	CLM2M	SOT500-4	RFS	No	BLT1
MF1SPUS8001DA4/03	935290189118	MF1SPUS8001DA4/03	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF1SPUS6031DA8/03	935294392118	MF1SPUS6031DA8/03	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF1SPUS8031DA8/03	935294394118	MF1SPUS8031DA8/03	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
NT4H2421G0DA8/02J	935377694118	NT4H2421G0DA8/02	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
OM6724,118	935280453118	OM6724	MOB4 DUMMY MODULE	CLM2M	SOT500-2	RFS	No	BLT1
SL2S2602FA8J	935308352118	SL2S2602FA8	ICode	CLM2M	SOT500-4	RFS	No	BLT1
OM6728,118	935293962118	OM6728	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF3MODQ101DA8/06J	935307401118	MF3MODQ101DA8/06	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF3MODHQ101DA8/06J	935307858118	MF3MODHQ101DA8/06	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF1PLUS8031DA4/03,	935291414118	MF1PLUS8031DA4/03	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF1PLUS6031DA4/03,	935293105118	MF1PLUS6031DA4/03	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF1SPUS6031DA4/03	935293107118	MF1SPUS6031DA4/03	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF1SPUS8031DA4/03	935293108118	MF1SPUS8031DA4/03	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF3MOD8101DA4/05,1	935293305118	MF3MOD8101DA4/05	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF3MOD4101DA4/05,1	935293306118	MF3MOD4101DA4/05	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF3MOD2101DA4/05,1	935293307118	MF3MOD2101DA4/05	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF0MOU2001DA8,118	935293378118	MF0MOU2001DA8	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF3MODH8101DA4/05,	935293424118	MF3MODH8101DA4/05	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF3MODH4101DA4/05,	935293425118	MF3MODH4101DA4/05	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF3MODH2101DA4/05,	935293426118	MF3MODH2101DA4/05	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF1SPUS6001DA8/03	935294391118	MF1SPUS6001DA8/03	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF1SPUS8001DA8/03	935294393118	MF1SPUS8001DA8/03	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF1PLUS6001DA8/03,	935294396118	MF1PLUS6001DA8/03	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF1PLUS6031DA8/03,	935294399118	MF1PLUS6031DA8/03	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF1PLUS8001DA8/03,	935294401118	MF1PLUS8001DA8/03	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF1PLUS8031DA8/03,	935294403118	MF1PLUS8031DA8/03	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF3MOD8101DA8/05,1	935294661118	MF3MOD8101DA8/05	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF3MOD4101DA8/05,1	935294662118	MF3MOD4101DA8/05	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF3MOD2101DA8/05,1	935294663118	MF3MOD2101DA8/05	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF3MODH8101DA8/05,	935294665118	MF3MODH8101DA8/05	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF3MODH4101DA8/05,	935294666118	MF3MODH4101DA8/05	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF3MODH2101DA8/05,	935294667118	MF3MODH2101DA8/05	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF0MOU2101DA8,118	935298258118	MF0MOU2101DA8	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF3MOD4101DA4/0501	935298406118	MF3MOD4101DA4/0501	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF1PLUS6021DA4/03J	935301637118	MF1PLUS6021DA4/03B	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF1S5000XDA4/V1J	935302816118	MF1S5000XDA4/V1	MIFARE	CLM2M	SOT500-2	RFS	No	BLT1
MF1S5030XDA4/V1J	935302818118	MF1S5030XDA4/V1	MIFARE	CLM2M	SOT500-2	RFS	No	BLT1
MF1S7000XDA4/V1J	935302822118	MF1S7000XDA4/V1	MIFARE	CLM2M	SOT500-2	RFS	No	BLT1
MF1S7030XDA4/V1J	935302823118	MF1S7030XDA4/V1	MIFARE	CLM2M	SOT500-2	RFS	No	BLT1
MF1S5000XDA8/V1J	935302824118	MF1S5000XDA8/V1	MIFARE	CLM2M	SOT500-4	RFS	No	BLT1
MF1S5030XDA8/V1J	935302825118	MF1S5030XDA8/V1	MIFARE	CLM2M	SOT500-4	RFS	No	BLT1
MF1S7000XDA8/V1J	935302828118	MF1S7000XDA8/V1	MIFARE	CLM2M	SOT500-4	RFS	No	BLT1

MF1S7030XDA8/V1J	935302829118	MF1S7030XDA8/V1	MIFARE	CLM2M	SOT500-4	RFS	No	BLT1
HT1MOA4S30/E/3J	935303944118	HT1MOA4S30/E/3	HITAG	CLM2M	SOT500-2	RFS	No	BLT1
HT2MOA4S20/E/3/RJ	935303945118	HT2MOA4S20/E/3/R	HITAG	CLM2M	SOT500-2	RFS	No	BLT1
HTSMOH5602EVJ	935303947118	HTSMOH5602EV	HITAG	CLM2M	SOT500-2	RFS	No	BLT1
HTSMOH4802EVJ	935303949118	HTSMOH4802EV	HITAG	CLM2M	SOT500-2	RFS	No	BLT1
MF1SEPH1001DA4/03J	935331367118	MF1SEPH1001DA4/03	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF1SEPH1001DA8/03J	935331368118	MF1SEPH1001DA8/03	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF1SEPH1031DA4/03J	935331838118	MF1SEPH1031DA4/03	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF0MOU2101DA4,118	935287579118	MF0MOU2101DA4	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF1PLUS6001DA4/03	935290196118	MF1PLUS6001DA4/03	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF1PLUS8001DA4/03,	935290201118	MF1PLUS8001DA4/03	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF1PLUS6001DA4/03,	935290207118	MF1PLUS6001DA4/03	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF3D2200DA4/01J	935347315118	MF3D2200DA4/01	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF3D4200DA4/01J	935347316118	MF3D4200DA4/01	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF3D8200DA4/01J	935347317118	MF3D8200DA4/01	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF3DH2200DA4/01J	935347661118	MF3DH2200DA4/01	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF3DH4200DA4/01J	935347662118	MF3DH4200DA4/01	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF3DH8200DA4/01J	935347663118	MF3DH8200DA4/01	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF1SEP1001DA4/03J	935306162118	MF1SEP1001DA4/03	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF1SEP1001DA8/03J	935306163118	MF1SEP1001DA8/03	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF1SEP1031DA4/03J	935306172118	MF1SEP1031DA4/03	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF1SEP1031DA8/03J	935306173118	MF1SEP1031DA8/03	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF3D8200DA4/11J	935384813118	MF3D8200DA4/11	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF2DL1000DA8/02J	935378411118	MF2DL1000DA8/02	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF3MODQ101DA4/06J	935307405118	MF3MODQ101DA4/06	CLHW	CLM2M	SOT500-2	RFS	No	BLT1
MF1SEPH1031DA8/03J	935331839118	MF1SEPH1031DA8/03	CLHW	CLM2M	SOT500-4	RFS	No	BLT1
MF0AESH3000DA8J	935431302118	MF0AESH3000DA8	CLHW	CLM2M	SOT500-4	CQS	No	BLT1
MF0AES3000DA8J	935431429118	MF0AES3000DA8	CLHW	CLM2M	SOT500-4	CQS	No	BLT1
MF3D9300DA8/01J	935453545118	MF3D9300DA8/01	CLHW	CLM2M	SOT500-4	ASM	No	BLT1
MF3DH9300DA4/01J	935453546118	MF3DH9300DA4/01	CLHW	CLM2M	SOT500-2	ASM	No	BLT1
MF3D9300DA4/01J	935453542118	MF3D9300DA4/01	CLHW	CLM2M	SOT500-2	ASM	No	BLT1
MF3DH9300DA8/01J	935453549118	MF3DH9300DA8/01	CLHW	CLM2M	SOT500-4	ASM	No	BLT1
MF0MOA4U10/D,118	935281785118	MF0MOA4U10/D	CLHW	CLM2M	SOT500-2	DOD	No	BLT1
MF9MOA2001DA8J	935368987118	MF9MOA2001DA8	CLHW	CLM2M	SOT500-4	DOD	No	BLT1
CLC/MF2DL1000DA8Z	935387576597	CLC/MF2DL1000DA8	SMART CARD - DESFire Light	CLM2M	SOT500-4	DOD	No	BLT1
MF1P2101DA4/02J	935360473118	MF1P2101DA4/02	CLHW	CLM2M	SOT500-2	DOD	No	BLT1
MF1P2111DA4/02SJ	935377827118	MF1P2111DA4/02S	CLHW	CLM2M	SOT500-2	DOD	No	BLT1
MF1P2131DA4/02J	935360474118	MF1P2131DA4/02	CLHW	CLM2M	SOT500-2	DOD	No	BLT1
MF1PH2131DA4/02J	935360786118	MF1PH2131DA4/02	CLHW	CLM2M	SOT500-2	DOD	No	BLT1
MF1PH2101DA4/02J	935360784118	MF1PH2101DA4/02	CLHW	CLM2M	SOT500-2	DOD	No	BLT1
MF1P4111DA4/02SJ	935378716118	MF1P4111DA4/02S	CLHW	CLM2M	SOT500-2	DOD	No	BLT1
MF1P4131DA4/02J	935360477118	MF1P4131DA4/02	CLHW	CLM2M	SOT500-2	DOD	No	BLT1
MF1PH4101DA4/02J	935360787118	MF1PH4101DA4/02	CLHW	CLM2M	SOT500-2	DOD	No	BLT1
MF1PH4131DA4/02J	935360788118	MF1PH4131DA4/02	CLHW	CLM2M	SOT500-2	DOD	No	BLT1
P308GM13A4/TOCD20J	935304274118	P308GM13A4/TOCD20K0	CLHW	CLM2M	SOT500-2	DOD	No	BLT1
P304P110A4/TOK09AJ	935353799118	P304P110A4/TOK09AE0	CLHW	CLM2M	SOT500-2	DOD	No	BLT1
P304D217A4/TOK09PJ	935353736118	P304D217A4/TOK09PG0	CLHW	CLM2M	SOT500-2	DOD	No	BLT1
MF1S5000XDA4/V2J	935387922118	MF1S5000XDA4/V2	MIFARE	CLM2M	SOT500-2	DOD	No	BLT1
MF1S5030XDA4/V2J	935387924118	MF1S5030XDA4/V2	MIFARE	CLM2M	SOT500-2	DOD	No	BLT1
MF1S5000XDA8/V2J	935387923118	MF1S5000XDA8/V2	MIFARE	CLM2M	SOT500-4	DOD	No	BLT1
MF1S5030XDA8/V2J	935387927118	MF1S5030XDA8/V2	MIFARE	CLM2M	SOT500-4	DOD	No	BLT1
MF1P4101DA4/02J	935360475118	MF1P4101DA4/02	CLHW	CLM2M	SOT500-2	DOD	No	BLT1
MF1S2030XDA4/V1J	935302821118	MF1S2030XDA4/V1	MIFARE	CLM2M	SOT500-2	DOD	No	BLT1