

Taiwan Semiconductor Co. Ltd. 11Fl., No. 205, Sec. 3, Beishin Rd. Xindian Dist., New Taipei City 231 Taiwan, R.O.C.

> Tel.:+886 2 8913 1588 Fax: +886 2 8913 1788 www.taiwansemi.com

## **Product Discontinuance Notification**

This is to inform you that the affected product(s) will be discontinued. This change will take effect immediately from the date of this notification.

Please contact your local Taiwan Semiconductor Field Quality Service or Customer Quality Engineer of this notification if you have questions or clarification.

PDN No: PDN24002 rev0

Title: Product Discontinuance for Trench Schottky parts

Issue Date: 2024/04/03

If you have any questions concerning this change, please contact:

#### **PDN Coordinator**

Name: Sunnie Lin

E-Mail: sunnie.lin@ts.com.tw

Phone: +886-2-8913-1588 Ext. 2205

# **PDN** Originator

Name: Chris Lin

E-mail: chris\_lin@mail.ts.com.tw Phone: +886-2-8913-1588 Ext. 2406

### **Effectivity:**

Last time buy/ order entry: Immediately.

Last shipment date: Immediately

### **Product Category (Description):**

The product of Trench Schottky by Taiwan Semiconductor Co., Ltd

### **Reason of Discontinuance:**

End of Life (EOL)

1. Subcon disruption

## **Affected Product:**

| Package        | TSC P/N     | New TSC P/N |
|----------------|-------------|-------------|
| SMPC4.0        | TSPB5H100S  | TSUP5102    |
| SMPC4.0        | TSPB15U100S | TSUP15102   |
| TO-277A (SMPC) | TSP10U100S  | TSUP10102   |
| TO-277A (SMPC) | TSP15U100S  | TSUP15102   |
| TO-277A (SMPC) | TSP12U120S  | TSUP12122   |