



Expertise Applied | Answers Delivered

8755 W. Higgins Road
Suite 500
Chicago, IL 60631

www.littelfuse.com

Product Change Notice (PCN)

8 Nov 2023

LFPCN20231108

Product Termination Notification for Littelfuse (MOSFET DISCRETE)

To our valued customers and partners,

In our constant efforts to improve our service to our valued customers and make our supply chain more agile and lean, we are obsoleting the list of part numbers.

APPENDIX shows the all the part numbers affected, LTB information and replacement within LF MOSFET portfolio.

Last time order date: 31 Mar 2024

If you have any additional questions or concerns, please contact me or your Regional Sales Manager or Field Application Engineer for any inquiry.

Best Regards,

Raymon Zhou
Product Marketing Manager
MOSFET DISCRETE
Littelfuse Semiconductor
RZhou2@littelfuse.com

July Chen
Product Management Analyst
MOSFET DISCRETE
Littelfuse Semiconductor
JChen19@littelfuse.com



Expertise Applied | Answers Delivered

8755 W. Higgins Road
Suite 500
Chicago, IL 60631

www.littelfuse.com

Product Change Notice (PCN)

APPENDIX

MaterialNo	Replacement	LTB	MaterialNo	Replacement	LTB
IXFA18N60X	IXFA18N65X2	NA	IXFX32N50	No replacement	NA
IXFA220N06T3	No replacement	3/31/2024	IXFX44N50F	No replacement	NA
IXFA24N60X	IXFA22N65X2	NA	IXFX44N50Q	No replacement	NA
IXFA270N06T3	No replacement	3/31/2024	IXFX48N55	No replacement	NA
IXFA30N60X	IXFA34N65X2	NA	IXFX52N60Q2	No replacement	NA
IXFA3N80	No replacement	NA	IXFX55N50	IXFX64N50P	NA
IXFA4N60P3	IXFA10N60P	NA	IXFX60N55Q2	No replacement	NA
IXFA5N50P3	IXFA12N50P	NA	IXFX62N25	No replacement	NA
IXFA8N50P3	No replacement	NA	IXFX66N50Q2	No replacement	NA
IXFB120N50P2	IXFB132N50P3	NA	IXFX73N30Q	No replacement	NA
IXFB72N55Q2	No replacement	NA	IXFX74N50P2	No replacement	NA
IXFC10N80P	No replacement	NA	IXFX88N20Q	No replacement	NA
IXFC110N10P	No replacement	NA	IXFX90N60X	IXFX100N65X2	NA
IXFC12N80P	No replacement	NA	IXFY5N50P3	No replacement	NA
IXFC13N50	No replacement	NA	IXFZ140N25T	No replacement	NA
IXFC14N60P	No replacement	NA	IXFZ520N075T2	No replacement	NA
IXFC14N80P	No replacement	NA	IXKC13N80C	No replacement	NA
IXFC15N80Q	No replacement	NA	IXKC15N60C5	No replacement	NA
IXFC16N50P	No replacement	NA	IXKC19N60C5	No replacement	NA
IXFC16N80P	No replacement	NA	IXKC23N60C5	No replacement	3/31/2024
IXFC20N80P	No replacement	NA	IXKC40N60C	No replacement	3/31/2024
IXFC22N60P	No replacement	NA	IXKH24N60C5	IXTH24N65X2	NA
IXFC24N50	No replacement	NA	IXKH30N60C5	IXTH34N65X2	NA
IXFC26N50	No replacement	NA	IXKH47N60CC3	No replacement	NA
IXFC26N50P	No replacement	NA	IXKK85N60CC3	No replacement	NA
IXFC30N60P	No replacement	NA	IXKP20N60C5	IXTP20N65X2	NA
IXFC36N50P	No replacement	NA	IXKP24N60C5	IXTP24N65X2	3/31/2024
IXFC52N30P	No replacement	NA	IXKR25N80C	No replacement	3/31/2024
IXFC60N20	No replacement	NA	IXKT70N60C5	IXFT60N65X2HV	NA
IXFC74N20P	No replacement	NA	IXT-1-1N100S1-T/R	No replacement	NA
IXFC80N085	No replacement	NA	IXTA05N100P	IXTA08N100P	NA
IXFC96N15P	No replacement	NA	IXTA110N055P	No replacement	NA
IXFE180N10	No replacement	NA	IXTA110N055T	No replacement	NA
IXFE180N20	No replacement	NA	IXTA110N055T7	No replacement	NA



Expertise Applied | Answers Delivered

8755 W. Higgins Road
Suite 500
Chicago, IL 60631

www.littelfuse.com

Product Change Notice (PCN)

IXFE23N100	No replacement	NA	IXTA110N12T2	IXTA80N12T2	NA
IXFE24N100	No replacement	NA	IXTA130N065T2	IXTA120N075T2	NA
IXFE39N90	No replacement	NA	IXTA152N085T	No replacement	NA
IXFE44N50Q	No replacement	NA	IXTA152N085T7	No replacement	NA
IXFE44N50QD2	No replacement	NA	IXTA160N085T	No replacement	NA
IXFE44N50QD3	No replacement	NA	IXTA180N085T	No replacement	NA
IXFE44N60	No replacement	NA	IXTA180N085T7	No replacement	NA
IXFE48N50Q	No replacement	NA	IXTA1970	No replacement	3/31/2024
IXFE48N50QD2	No replacement	NA	IXTA1970-TRL	No replacement	3/31/2024
IXFE48N50QD3	No replacement	NA	IXTA1N100	IXTA1R4N100P	NA
IXFE50N50	No replacement	NA	IXTA1N100-TRL	IXTA1R4N100P	NA
IXFE55N50	No replacement	NA	IXTA1N80	No replacement	NA
IXFE73N30Q	No replacement	NA	IXTA1N80P	No replacement	NA
IXFE80N50	No replacement	NA	IXTA200N075T	No replacement	NA
IXFG55N50	No replacement	NA	IXTA200N075T7	No replacement	NA
IXFH10N100	IXFH10N100P	NA	IXTA200N085T	No replacement	NA
IXFH10N90	No replacement	NA	IXTA200N085T7	No replacement	NA
IXFH12N120	No replacement	NA	IXTA20N65X	IXTA20N65X2	3/31/2024
IXFH12N90	IXFH12N90P	NA	IXTA20N65X-TRL	IXTA20N65X2	3/31/2024
IXFH13N100	IXFH12N100P	NA	IXTA220N055T	No replacement	NA
IXFH13N50	No replacement	NA	IXTA220N055T7	No replacement	NA
IXFH13N80	IXFH14N80P	3/31/2024	IXTA220N075T	No replacement	NA
IXFH13N80Q	No replacement	NA	IXTA220N075T7	No replacement	NA
IXFH14N100	No replacement	NA	IXTA230N04T4	No replacement	3/31/2024
IXFH14N60P3	IXFH14N60P	NA	IXTA240N055T	No replacement	NA
IXFH14N80	No replacement	NA	IXTA240N055T7	No replacement	NA
IXFH150N17T	No replacement	NA	IXTA270N04T4	No replacement	3/31/2024
IXFH1605	No replacement	3/31/2024	IXTA270N04T4-7	No replacement	3/31/2024
IXFH17N80Q	No replacement	NA	IXTA2N100	IXTA2N100P	3/31/2024
IXFH1826	No replacement	3/31/2024	IXTA2N100-TRL	IXTA2N100P	3/31/2024
IXFH18N60X	IXFH18N65X2	NA	IXTA2N80	IXFA7N80P	NA
IXFH1988	No replacement	3/31/2024	IXTA2N80P	No replacement	NA
IXFH21N50	IXFH22N50P	3/31/2024	IXTA32N20T	IXTA48N20T	NA
IXFH21N50F	No replacement	NA	IXTA340N04T4	No replacement	3/31/2024
IXFH220N06T3	No replacement	3/31/2024	IXTA340N04T4-7	No replacement	3/31/2024
IXFH22N55	No replacement	NA	IXTA340N04T4-TRL	No replacement	3/31/2024
IXFH22N60X2A	IXFH34N60X2A	NA	IXTA36N30P-PDP	No replacement	NA



Expertise Applied | Answers Delivered

8755 W. Higgins Road
Suite 500
Chicago, IL 60631

www.littelfuse.com

Product Change Notice (PCN)

IXFH23N60Q	No replacement	NA	IXTA380N036T4-7	No replacement	NA
IXFH24N60X	IXFH22N65X2	NA	IXTA3N110	IXTA2R4N120P	NA
IXFH26N55Q	No replacement	NA	IXTA3N110-TRL	IXTA2R4N120P	NA
IXFH270N06T3	No replacement	3/31/2024	IXTA3N120LHV	No replacement	NA
IXFH28N50F	No replacement	NA	IXTA3N120LHV-TRL	No replacement	NA
IXFH28N50Q	No replacement	NA	IXTA3N50P	No replacement	NA
IXFH30N40Q	No replacement	NA	IXTA460P2	IXTA16N50P	3/31/2024
IXFH30N50	No replacement	NA	IXTA4N60P	No replacement	NA
IXFH30N60Q	No replacement	NA	IXTA50N28T	No replacement	NA
IXFH30N60X	IXFH34N65X2	NA	IXTA70N085T	No replacement	NA
IXFH35N30	No replacement	NA	IXTA76N075T	IXTA70N075T2	NA
IXFH36N55Q	No replacement	NA	IXTA80N10T7	No replacement	NA
IXFH36N55Q2	No replacement	NA	IXTA88N085T	No replacement	NA
IXFH40N50Q2	No replacement	NA	IXTA88N085T7	IXTA90N075T2	NA
IXFH40N80XA	IXFH40N85X	NA	IXTA90N055T	No replacement	NA
IXFH42N50P2	IXFH44N50P	3/31/2024	IXTA90N15T	No replacement	NA
IXFH50N60X	IXFH60N65X2	3/31/2024	IXTB1909	No replacement	NA
IXFH50N80XA	IXFH50N85X	NA	IXTC110N055T	No replacement	NA
IXFH60N20	No replacement	NA	IXTC110N25T	No replacement	NA
IXFH60N20F	No replacement	NA	IXTC13N50	No replacement	NA
IXFH60N25Q	No replacement	NA	IXTC160N10T	No replacement	NA
IXFH60N60X	IXFH60N65X2	NA	IXTC180N085T	No replacement	NA
IXFH66N20Q	No replacement	NA	IXTC200N085T	No replacement	NA
IXFH67N10	IXFH110N10P	3/31/2024	IXTC200N10T	No replacement	NA
IXFH68N20	No replacement	NA	IXTC220N055T	No replacement	NA
IXFH6N90	No replacement	NA	IXTC220N075T	No replacement	NA
IXFH70N15	No replacement	NA	IXTC240N055T	No replacement	NA
IXFH74N20	No replacement	NA	IXTC250N075T	No replacement	NA
IXFH76N07-12	No replacement	NA	IXTC26N50P	No replacement	NA
IXFH7N80	IXFH10N80P	NA	IXTC280N055T	No replacement	NA
IXFH7N90Q	No replacement	NA	IXTC36P15P	No replacement	NA
IXFH80N08	No replacement	NA	IXTC62N15P	No replacement	NA
IXFH80N085	No replacement	NA	IXTC75N10	No replacement	NA
IXFH80N10	No replacement	NA	IXTC96N25T	No replacement	NA
IXFH80N15Q	No replacement	NA	IXTF03N400	No replacement	NA
IXFH88N20Q	No replacement	NA	IXTF230N085T	No replacement	NA



Expertise Applied | Answers Delivered

8755 W. Higgins Road
Suite 500
Chicago, IL 60631

www.littelfuse.com

Product Change Notice (PCN)

IXFH8N80	No replacement	NA	IXTF250N075T	No replacement	NA
IXFH9N80	IXFH10N80P	NA	IXTF280N055T	No replacement	NA
IXFH9N80Q	No replacement	NA	IXTH03N400	No replacement	NA
IXFJ13N50	No replacement	NA	IXTH06N220P3HV	IXTH05N250P3HV	NA
IXFJ26N50	No replacement	NA	IXTH102N20T	No replacement	NA
IXFJ32N50Q	No replacement	NA	IXTH10P50	IXFH16N50P	NA
IXFJ40N30	No replacement	NA	IXTH12N100	No replacement	NA
IXFK120N25	No replacement	NA	IXTH12N120	No replacement	NA
IXFK150N15	No replacement	NA	IXTH12N90	No replacement	NA
IXFK150N15P	No replacement	NA	IXTH130N15T	IXTH130N20T	NA
IXFK15N100Q	No replacement	NA	IXTH13N80	No replacement	3/31/2024
IXFK16N90Q	No replacement	NA	IXTH14N100	No replacement	NA
IXFK1801	No replacement	3/31/2024	IXTH14N80	No replacement	3/31/2024
IXFK180N085	No replacement	NA	IXTH150N17T	No replacement	NA
IXFK20N120	No replacement	NA	IXTH152N085T	No replacement	NA
IXFK20N80Q	No replacement	NA	IXTH16N10D2	IXTH16N20D2	NA
IXFK210N17T	No replacement	NA	IXTH16P20	IXTH26P20P	3/31/2024
IXFK21N100F	No replacement	3/31/2024	IXTH180N085T	No replacement	NA
IXFK24N90Q	No replacement	NA	IXTH1918	No replacement	NA
IXFK25N90	No replacement	NA	IXTH1N100	No replacement	NA
IXFK27N80	IXFK32N80P	3/31/2024	IXTH1R8N220P3HV	IXTH05N250P3HV	NA
IXFK30N100Q2	No replacement	NA	IXTH200N075T	No replacement	NA
IXFK30N110P	No replacement	NA	IXTH200N085T	No replacement	NA
IXFK32N50Q	No replacement	NA	IXTH20N65X	IXTH20N65X2	3/31/2024
IXFK32N60	No replacement	NA	IXTH21N50	IXTH22N50P	3/31/2024
IXFK35N50	No replacement	NA	IXTH220N055T	No replacement	NA
IXFK36N60	IXFK36N60P	NA	IXTH220N075T	No replacement	NA
IXFK40N50Q2	No replacement	NA	IXTH230N085T	No replacement	NA
IXFK44N50F	No replacement	NA	IXTH240N055T	No replacement	NA
IXFK44N55Q	No replacement	NA	IXTH24N50	IXTH22N50P	3/31/2024
IXFK48N55	No replacement	NA	IXTH24N50Q	No replacement	NA
IXFK50N50	IXFK44N50P	NA	IXTH250N075T	No replacement	NA
IXFK52N30Q	No replacement	NA	IXTH270N04T4	No replacement	3/31/2024
IXFK52N60Q2	No replacement	NA	IXTH280N055T	No replacement	NA
IXFK60N25Q	No replacement	NA	IXTH28N50Q	No replacement	NA
IXFK60N55Q2	No replacement	NA	IXTH30N25	No replacement	NA
IXFK62N25	No replacement	NA	IXTH30N50	No replacement	NA



Expertise Applied | Answers Delivered

8755 W. Higgins Road
Suite 500
Chicago, IL 60631

www.littelfuse.com

Product Change Notice (PCN)

IXFK72N20	No replacement	NA	IXTH32N65X	IXTH34N65X2	3/31/2024
IXFK73N30	IXFK88N30P	3/31/2024	IXTH340N04T4	IXTH360N055T2	3/31/2024
IXFK73N30Q	No replacement	NA	IXTH36P10	IXTH52P10P	NA
IXFK74N50P2	No replacement	NA	IXTH41N25	No replacement	NA
IXFK80N15Q	No replacement	NA	IXTH420N04T2	IXTH500N04T2	NA
IXFK80N20Q	No replacement	NA	IXTH460P2	IXTH22N50P	3/31/2024
IXFK88N20Q	No replacement	NA	IXTH48N20	No replacement	NA
IXFK90N50P2	No replacement	NA	IXTH50N20	IXFH74N20P	NA
IXFK90N60X	IXFK100N65X2	NA	IXTH50N25T	IXTH76N25T	NA
IXFL30N120P	No replacement	NA	IXTH50N30	No replacement	NA
IXFL36N110P	No replacement	NA	IXTH52N65X	IXTH48N65X2	3/31/2024
IXFL39N90	No replacement	NA	IXTH5N100A	IXTH3N100P	NA
IXFL40N110P	No replacement	NA	IXTH60N15	No replacement	NA
IXFL44N60	No replacement	NA	IXTH60N25	No replacement	NA
IXFL44N80	No replacement	NA	IXTH64N65X	IXTH62N65X2	3/31/2024
IXFL60N60	No replacement	NA	IXTH67N10	No replacement	3/31/2024
IXFL70N60Q2	No replacement	NA	IXTH6N80A	No replacement	NA
IXFM10N100	No replacement	NA	IXTH6N90	No replacement	NA
IXFM10N90	No replacement	NA	IXTH6N90A	No replacement	NA
IXFM11N80	No replacement	NA	IXTH72N20	No replacement	NA
IXFM12N100	No replacement	NA	IXTH75N15	No replacement	NA
IXFM12N90	No replacement	NA	IXTH88N15	No replacement	NA
IXFM12N90Q	No replacement	NA	IXTH90N15T	No replacement	NA
IXFM13N50	No replacement	NA	IXTJ36N20	No replacement	NA
IXFM13N80	No replacement	NA	IXTJ3N150	No replacement	NA
IXFM15N60	No replacement	NA	IXTK110N30	No replacement	NA
IXFM35N30	No replacement	NA	IXTK120N25	No replacement	NA
IXFM42N20	No replacement	NA	IXTK128N15	No replacement	NA
IXFM6N90	No replacement	NA	IXTK160N20	No replacement	NA
IXFM7N80	No replacement	NA	IXTK180N15	No replacement	NA
IXFN100N10S1	No replacement	NA	IXTK250N10	No replacement	NA
IXFN100N10S2	No replacement	NA	IXTK33N50	No replacement	NA
IXFN100N10S3	No replacement	NA	IXTK62N25	No replacement	NA
IXFN100N20	IXFN140N20P	3/31/2024	IXTK75N30	No replacement	NA
IXFN100N25	No replacement	NA	IXTK80N25	No replacement	NA
IXFN150N10	IXFN200N10P	3/31/2024	IXTK90N15	No replacement	NA
IXFN150N15	No replacement	NA	IXTL2x200N085T	No replacement	NA



Expertise Applied | Answers Delivered

8755 W. Higgins Road
Suite 500
Chicago, IL 60631

www.littelfuse.com

Product Change Notice (PCN)

IXFN1849	No replacement	NA	IXTL2x220N075T	No replacement	NA
IXFN1993	No replacement	NA	IXTL2x240N055T	No replacement	NA
IXFN20N120	No replacement	NA	IXTM12N100	No replacement	NA
IXFN22N120	No replacement	NA	IXTM12N90	No replacement	NA
IXFN23N100	No replacement	NA	IXTM13N80	No replacement	NA
IXFN25N90	No replacement	NA	IXTM40N30	No replacement	NA
IXFN260N17T	No replacement	NA	IXTM50N20	No replacement	NA
IXFN30N110P	No replacement	NA	IXTM67N10	No replacement	NA
IXFN32N60	No replacement	NA	IXTM6N90	No replacement	NA
IXFN34N100	No replacement	NA	IXTM6N90A	No replacement	NA
IXFN36N110P	No replacement	NA	IXTM75N10	No replacement	NA
IXFN44N50Q	No replacement	NA	IXTN120N25	No replacement	NA
IXFN44N50U2	No replacement	NA	IXTN15N100	No replacement	NA
IXFN44N50U3	No replacement	NA	IXTN320N10T	No replacement	NA
IXFN48N55	No replacement	NA	IXTN36N50	No replacement	NA
IXFN50N50	IXFN64N50P	NA	IXTN660N04T4	No replacement	3/31/2024
IXFN72N55Q2	No replacement	NA	IXTP03N90P	IXTP08N100P	NA
IXFN73N30Q	No replacement	NA	IXTP05N100P	IXTP08N100P	NA
IXFN80N48	No replacement	NA	IXTP10N60PM	No replacement	NA
IXFN90N30	No replacement	NA	IXTP110N055P	No replacement	NA
IXFP05N100M	No replacement	NA	IXTP110N055T	No replacement	NA
IXFP12N50PM	No replacement	NA	IXTP110N12T2	IXTP80N12T2	NA
IXFP12N65X2A	No replacement	NA	IXTP130N065T2	No replacement	NA
IXFP14N60P3	IXFP16N60P3	NA	IXTP152N085T	No replacement	NA
IXFP18N60X	IXFP18N65X2	NA	IXTP16N50PM	No replacement	NA
IXFP220N06T3	No replacement	3/31/2024	IXTP180N085T	No replacement	NA
IXFP24N60X	IXFP22N65X2	NA	IXTP18N60PM	No replacement	NA
IXFP270N06T3	No replacement	3/31/2024	IXTP1N80	No replacement	NA
IXFP30N60X	IXFP34N65X2	NA	IXTP1R6N50P	No replacement	NA
IXFP34N60X2A	No replacement	NA	IXTP200N075T	No replacement	NA
IXFP3N50PM	No replacement	NA	IXTP200N085T	No replacement	NA
IXFP3N80	No replacement	NA	IXTP20N65X	IXTP20N65X2	3/31/2024
IXFP4N60P3	IXFP10N60P	NA	IXTP20N65XM	IXTP20N65X2M	3/31/2024
IXFP5N50P3	IXFP12N50P	NA	IXTP220N055T	No replacement	NA
IXFP7N60P3	IXFP10N60P	NA	IXTP220N075T	No replacement	NA
IXFP8N50P3	IXFP12N50P	NA	IXTP230N04T4	No replacement	3/31/2024
IXFP8N50PM	No replacement	NA	IXTP230N04T4M	No replacement	3/31/2024



Expertise Applied | Answers Delivered

8755 W. Higgins Road
Suite 500
Chicago, IL 60631

www.littelfuse.com

Product Change Notice (PCN)

IXFQ10N80P	No replacement	NA	IXTP240N055T	No replacement	NA
IXFQ12N80P	No replacement	NA	IXTP270N04T4	No replacement	3/31/2024
IXFQ14N80P	No replacement	NA	IXTP2N60P	No replacement	NA
IXFQ24N50P2	IXFQ26N50P3	3/31/2024	IXTP2N80	IXFP7N80P	NA
IXFQ24N60X	No replacement	NA	IXTP2N80P	No replacement	NA
IXFQ30N60X	No replacement	NA	IXTP32N65X	IXTP34N65X2	3/31/2024
IXFQ50N60X	No replacement	3/31/2024	IXTP32N65XM	IXTP24N65X2M	3/31/2024
IXFQ60N60X	No replacement	NA	IXTP340N04T4	No replacement	3/31/2024
IXFR100N25	No replacement	NA	IXTP36N30P-PDP	No replacement	NA
IXFR150N15	No replacement	NA	IXTP3N110	IXTP2R4N120P	NA
IXFR15N80Q	No replacement	NA	IXTP3N50P	No replacement	NA
IXFR1871	No replacement	NA	IXTP460P2	IXTP16N50P	3/31/2024
IXFR20N100P	IXFR26N100P	NA	IXTP4N60P	No replacement	NA
IXFR26N50Q	No replacement	NA	IXTP50N085T	No replacement	NA
IXFR26N60Q	No replacement	NA	IXTP5N60P	No replacement	NA
IXFR30N110P	No replacement	NA	IXTP60N020T	No replacement	NA
IXFR32N50Q	No replacement	NA	IXTP60N10TM	No replacement	NA
IXFR34N80	No replacement	NA	IXTP60N28TM-A	No replacement	NA
IXFR40N50Q2	No replacement	NA	IXTP70N085T	No replacement	NA
IXFR50N50	No replacement	NA	IXTP76N075T	IXTP70N075T2	NA
IXFR55N50	IXFR80N50P	NA	IXTP7N60PM	No replacement	NA
IXFR70N15	No replacement	NA	IXTP88N085T	No replacement	NA
IXFR80N15Q	No replacement	NA	IXTP8N50PM	No replacement	NA
IXFR80N20Q	No replacement	NA	IXTP90N055T	No replacement	NA
IXFT10N100	No replacement	NA	IXTQ102N15T	IXTQ86N20T	NA
IXFT12N100	IXFT20N100P	NA	IXTQ102N20T	No replacement	NA
IXFT12N50F	No replacement	NA	IXTQ110N055P	No replacement	NA
IXFT13N100	No replacement	NA	IXTQ130N15T	IXTQ86N20T	NA
IXFT13N80Q	No replacement	NA	IXTQ150N06P	No replacement	NA
IXFT14N100	No replacement	NA	IXTQ152N085T	No replacement	NA
IXFT15N100Q	No replacement	NA	IXTQ160N085T	No replacement	NA
IXFT16N90Q	No replacement	NA	IXTQ180N085T	No replacement	NA
IXFT18N90P	IXFT24N90P	NA	IXTQ200N06P	No replacement	NA
IXFT20N60Q	No replacement	NA	IXTQ200N075T	No replacement	NA
IXFT20N80P	IXFT24N80P	NA	IXTQ200N085T	No replacement	NA
IXFT21N50	No replacement	NA	IXTQ220N055T	No replacement	NA
IXFT21N50F	No replacement	NA	IXTQ220N075T	No replacement	NA



Expertise Applied | Answers Delivered

8755 W. Higgins Road
Suite 500
Chicago, IL 60631

www.littelfuse.com

Product Change Notice (PCN)

IXFT21N50Q	No replacement	NA	IXTQ230N085T	No replacement	NA
IXFT28N50F	No replacement	NA	IXTQ23N60Q	No replacement	NA
IXFT30N40Q	No replacement	NA	IXTQ240N055T	No replacement	NA
IXFT30N50	No replacement	NA	IXTQ24N55Q	No replacement	NA
IXFT30N60P	IXFT36N60P	NA	IXTQ250N075T	No replacement	NA
IXFT30N60X	IXFT60N65X2HV	NA	IXTQ26N60P	IXTQ30N60P	NA
IXFT32N50	No replacement	NA	IXTQ280N055T	No replacement	NA
IXFT40N30	IXFT69N30P	3/31/2024	IXTQ32N65X	IXTQ34N65X2M	3/31/2024
IXFT42N50P2	IXFT44N50P	3/31/2024	IXTQ36N30P-PDP	No replacement	NA
IXFT46N30T	IXFT86N30T	NA	IXTQ40N50Q	No replacement	NA
IXFT50N20	IXTT74N20P	3/31/2024	IXTQ470P2	IXTQ44N50P	3/31/2024
IXFT50N60X	IXFT60N65X2HV	3/31/2024	IXTQ50N28T	No replacement	NA
IXFT52N50P2	IXFT60N50P3	3/31/2024	IXTQ80N28T	No replacement	NA
IXFT58N20-TRL	IXTT74N20P	NA	IXTQ88N28T	No replacement	NA
IXFT60N20	No replacement	NA	IXTQ90N15T	No replacement	NA
IXFT60N20F	No replacement	NA	IXTR30N25	No replacement	NA
IXFT60N25Q	No replacement	NA	IXTR62N15P	No replacement	NA
IXFT66N20Q	No replacement	NA	IXTR90P10P	IXTR170P10P	NA
IXFT68N20	No replacement	NA	IXTS01N90P-223	No replacement	NA
IXFT6N100Q	IXFT15N100Q3	NA	IXTS01N90P-89	No replacement	NA
IXFT70N15	No replacement	NA	IXTT16N10D2	IXTT16N20D2	NA
IXFT74N20	No replacement	NA	IXTT1N100	No replacement	NA
IXFT80N08	No replacement	NA	IXTT24N50Q	No replacement	NA
IXFT80N085	No replacement	NA	IXTT28N50Q	No replacement	NA
IXFT80N10	No replacement	NA	IXTT30N60P	IXTT26N60P	NA
IXFT80N10Q	No replacement	NA	IXTT440N04T4HV	No replacement	3/31/2024
IXFT80N15Q	No replacement	NA	IXTT50N30	No replacement	NA
IXFT80N20Q	No replacement	NA	IXTT60N10	No replacement	NA
IXFV110N10PS	No replacement	NA	IXTT72N10	No replacement	NA
IXFV110N25T	No replacement	NA	IXTT72N20	No replacement	NA
IXFV110N25TS	No replacement	NA	IXTT75N10	IXTT110N10P	3/31/2024
IXFV12N100P	No replacement	NA	IXTT75N15	No replacement	NA
IXFV12N100PS	No replacement	NA	IXTT88N15	No replacement	NA
IXFV12N120P	No replacement	NA	IXTU01N100	No replacement	3/31/2024
IXFV12N120PS	No replacement	NA	IXTU01N80	No replacement	NA
IXFV12N80P	No replacement	NA	IXTU05N100	No replacement	NA
IXFV12N80PS	No replacement	NA	IXTU12N06T	No replacement	NA



Expertise Applied | Answers Delivered

8755 W. Higgins Road
Suite 500
Chicago, IL 60631

www.littelfuse.com

Product Change Notice (PCN)

IXFV12N90P	No replacement	NA	IXTU1N80P	No replacement	NA
IXFV12N90PS	No replacement	NA	IXTU1R4N60P	No replacement	NA
IXFV14N80P	No replacement	NA	IXTU2N80P	No replacement	NA
IXFV14N80PS	No replacement	NA	IXTU4N60P	No replacement	NA
IXFV15N100P	No replacement	NA	IXTU5N50P	No replacement	NA
IXFV15N100PS	No replacement	NA	IXTV02N250S	No replacement	NA
IXFV16N80P	No replacement	NA	IXTV03N400S	No replacement	NA
IXFV16N80PS	No replacement	NA	IXTV110N25TS	No replacement	NA
IXFV18N60P	No replacement	NA	IXTV18N60P	No replacement	NA
IXFV18N60PS	No replacement	NA	IXTV18N60PS	No replacement	NA
IXFV18N90P	No replacement	NA	IXTV200N10T	No replacement	NA
IXFV18N90PS	No replacement	NA	IXTV200N10TS	No replacement	NA
IXFV20N80P	No replacement	NA	IXTV22N50P	No replacement	NA
IXFV20N80PS	No replacement	NA	IXTV22N50PS	No replacement	NA
IXFV22N50P	No replacement	NA	IXTV22N60P	No replacement	NA
IXFV22N50PS	No replacement	NA	IXTV22N60PS	No replacement	NA
IXFV22N60P	No replacement	NA	IXTV230N085T	No replacement	NA
IXFV22N60PS	No replacement	NA	IXTV230N85TS	No replacement	NA
IXFV26N50P	No replacement	NA	IXTV250N075T	No replacement	NA
IXFV26N50PS	No replacement	NA	IXTV250N075TS	No replacement	NA
IXFV26N60P	No replacement	NA	IXTV26N50PS	No replacement	NA
IXFV26N60PS	No replacement	NA	IXTV26N60P	No replacement	NA
IXFV30N50P	No replacement	NA	IXTV26N60PS	No replacement	NA
IXFV30N50PS	No replacement	NA	IXTV270N055T2	No replacement	NA
IXFV30N60P	No replacement	NA	IXTV270N055T2S	No replacement	NA
IXFV30N60PS	No replacement	NA	IXTV280N055T	No replacement	NA
IXFV36N50P	No replacement	NA	IXTV280N055TS	No replacement	NA
IXFV36N50PS	No replacement	NA	IXTV30N50P	No replacement	NA
IXFV52N30P	No replacement	NA	IXTV30N50PS	No replacement	NA
IXFV52N30PS	No replacement	NA	IXTV30N60P	No replacement	NA
IXFV74N20P	No replacement	NA	IXTV30N60PS	No replacement	NA
IXFV74N20PS	No replacement	NA	IXTV36N50P	No replacement	NA
IXFV96N15P	No replacement	NA	IXTV36N50PS	No replacement	NA
IXFV96N15PS	No replacement	NA	IXTV86N25T	No replacement	NA
IXFV96N20P	No replacement	NA	IXTV96N25T	No replacement	NA
IXFX120N25	No replacement	NA	IXTX1925	No replacement	NA
IXFX14N100	No replacement	NA	IXTX660N04T4	IXTX600N04T2	3/31/2024



Expertise Applied | Answers Delivered

8755 W. Higgins Road
Suite 500
Chicago, IL 60631

www.littelfuse.com

Product Change Notice (PCN)

IXFX15N100	No replacement	NA	IXTY01N100-TRL	IXTY08N100P	3/31/2024
IXFX170N10	IXFX200N10P	NA	IXTY01N80	No replacement	NA
IXFX180N085	No replacement	NA	IXTY03N90PHV	IXTY08N100P	NA
IXFX1985	No replacement	3/31/2024	IXTY05N100	IXTY08N100P	NA
IXFX20N120	No replacement	NA	IXTY12N06T	No replacement	NA
IXFX210N17T	No replacement	NA	IXTY1N80	No replacement	NA
IXFX21N100F	No replacement	3/31/2024	IXTY1R6N50P	No replacement	NA
IXFX220N15P	IXFX180N15P	NA	IXTY2N80P	No replacement	NA
IXFX24N90Q	No replacement	NA	IXTY4N60P	No replacement	NA
IXFX25N90	No replacement	NA	IXTY50N085T	No replacement	NA
IXFX26N60Q	No replacement	NA	IXTZ550N055T2	No replacement	NA
IXFX30N110P	No replacement	NA			