

PCE Americas Inc.
711 Commerce Way
Suite 8
Jupiter
FL-33458
USA
From outside US: +1
Tel: (561) 320-9162
Fax: (561) 320-9176
info@pce-americas.com

PCE Instruments UK Ltd.
Units 12/13
Southpoint Business Park
Ensign way
Hampshire / Southampton
United Kingdom, SO31 4RF
From outside UK: +44
Tel: (0) 2380 98703 0
Fax: (0) 2380 98703 9
info@pce-instruments.com

www.pce-instruments.com/english www.pce-instruments.com

Technical Gloss Meter PCE-SGM 60

Gloss Meter PCE-SGM 60

Gloss meter for use in quality and incoming goods inspection / 60 ° angle / 3.5 "TFT display / low measurement time / small measurement area / measurement to 1000 GU

This gloss meter with small measuring area is used to quantify surfaces that must be measured. The gloss-measuring device operates on the reflection principle by sending light from a known light source onto the surface to be tested and calculates the gloss level of the surface according to the reflection of light particles. The gloss level in gloss units (GU) is then output to the display of the gloss meter.

The measurement geometry of the Gloss Meter PCE-SGM 60 is 60 degrees and is not adjustable. Evaluation software is included with the gloss meter which allows you to read out the measurement data to a computer and analyze and store your results. This gloss meter has data memory installed, which can accommodate up to 5,000 measured values depending on the setting.

- Measurement geometry: 60 °
- Measurement to 1000 gloss units
- Internal memory up to 5000 readings
- Small measurement area
- 0.5 second measurement time
- Includes evaluation software

Specifications: Gloss Meter PCE-SGM 60

Measurement Geometry 60 °

Display 3.5 "TFT touch display

Standardize ISO 2813

GB / T 9754 ASTM D 523 ASTM D 2457

Measuring Area 1.5mm x 2mm / 0.06in x 0.07in

Measuring Range 0 ... 1000 GU
Readability 0.1 GU

Repeatability Measuring range 0 ... 10 GU: ± 0.1 GU

measuring range 10 ... 100 GU: GU \pm 0.2 Measuring range 100 ... 1000 GU: GU \pm 0.2 (%)

Reproducibility Measuring range 0 ... 10 GU: ± 0.2 GU

measuring range 10 ... 100 GU \pm 0.5 GU measuring range 10 ... 1000 GU \pm 0.5 GU (%)

Chromaticity corresponds to CIE 1931 (2°) under a CIE C - light source

Measurement Accuracy $\pm 1.5 / \pm 1.5\%$

Measuring Time

Dimensions

Weight

Menu Language

Power Supply

Interface

Measurement Memory

Software

Ambient Temperature Storage Temperature

Relative Humidity

Delivery Contents for Gloss Meter PCE-SGM 60

1 x Gloss Meter PCE-SGM 60

1 x Charger

1 x USB cable

1 x Analysis software (on CD-ROM)

1 x Calibration plate

1 x User Manual

0.5 seconds

160 x 75 x 90 mm/6.3 x 3 x 3.5

350 g/12.3 oz

English, Chinese

3200 mAh Li-ion battery

USB / RS-232

Basic measurement: 1000 Statistical Mode: 5000

Continuous measurement: 5000

included

0 ... +40 ° C / 32 ... 104 ° F

-20 ... +50 ° C / -4 ... 122 ° F

<85% rel. Humidity (non-condensing)