

PRODUCT CHANGE NOTIFICATION

Product Category ABRASION PROTECTION **20231231-1**

Product Group DUCT AND ABRASION

ISSUE DATE: 11-Aug-23

IMPACTED REGIONS: ☒ NA ☒ EMEA ☒ LATAM ☒ AP

REASON FOR CHANGE: ☐ DISCONTINUATION
☒ OTHER

DESCRIPTION OF CHANGE: (Required)

Effective December 31, 2023 we will no longer include an installation tool in packages of Panduit spiral wrap products.

Photos/Drawing (where applicable)



IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2023	12	31

CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-CSVM@panduit.com	CHINA: 400-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) SGP-Customer_Service@panduit.com	INDONESIA: 001 803 65 7571 SGP-Customer_Service@panduit.com	JAPAN: +81-3-6863-6000 JPN-CS@panduit.com
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com	SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com
	TAIWAN: 0080 165 1487 SGP-Customer_Service@panduit.com	THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com	
LATIN AMERICA	BRAZIL 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) MEX-customerservice@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com
NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA FORM C2-1003 DATE: 06 APR 21 APPR: MURILLO	EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com

IMPACTED PART NUMBER(s)
T12R-CY
T12T-C
T12F-D
T12N-C0
T12N-C
T12N-D
T12F-C0
T12F-C
T12FR-CY
T12FR-C20Y
T19F-M
T19F-C0
T19F-C
T19T-C
T19N-C
T19N-C0
T19R-CY
T19FR-CY
T19FR-C20Y
T25N-C
T25N-C
T25F-C
T25T-L0
T25FR-M
T25N-M0
T25N-M0
T25N-M
T25N-M
T25N-C0
T25N-C0
T25F-C6
T25F-M0
T25F-M
T25F-C8
T25F-C10
T25F-C0
T25R-CY
T25R-M20Y
T25R-MY
T25R-C20Y
T25F-X0
T25F-C2
T25F-C4Y
T25F-C3Y
T25T-L
T25FR-CY

T25FR-MY
T25FR-C20Y
T25FR-M20Y
T25NZFR-C20
T25FG-C0
T38F-C
T38N-TL
T38N-TL
T38R-CY
T38F-TL0
T38F-TL
T38T-L
T38R-TLY
T38N-C0
T38N-C0
T38N-C
T38N-C
T38F-C0
T38FR-CY
T38FR-TLY
T38FR-C20Y
T38P-C0
T38P-C0
T38NZFR-C20
T50F-TL0
T50F-C2
T50F-C4Y
T50F-C3Y
T50N-TL0
T50N-TL0
T50R-TLY
T50R-CY
T50F-X0
T50F-X
T50FR-CY
T50FR-TLY
T50F-C7
T50F-C6
T50F-C5
T50F-TL
T50F-C8
T50T-Q
T50F-C
T50F-C10
T50F-C0
T50N-C
T50N-C

T50N-TL
T50N-TL
T50N-C0
T50N-C0
T50F-TL4Y
T50FR-C20Y
T50P-C0
T50P-C0
T50NZFR-C20
T62F-TL0
T62N-C
T62N-C
T62R-CY
T62N-C0
T62N-C0
T62F-C0
T62F-C
T62T-Q
T62FR-CY
T62FR-C20Y
T75F-C
T75F-C0
T75F-T0
T75N-T
T75N-T
T75N-C0
T75N-C0
T75N-C
T75N-C
T75T-X
T75R-CY
T75F-T
T75FR-CY
T75FR-TY
T75FR-C20Y
T75NZFR-C20
T75P-C0/N
T75P-C0/N
T100N-C0
T100N-C0
T100N-C
T100N-C
T100R-CY
T100T-X
T100F-C0
T100F-C
T100FR-CY

[illegible]