intel.

Product Change Notification

Change Notification #: 119699-00

Change Title: Select Intel® Agilex® 7 F, I & M Series Devices,

PCN 119699-00, Documentation,

Quartus® Prime Pro Firmware and Partial Reconfiguration User Guide Updates for Intel®

Agilex® 7

Date of Publication: October 10, 2023

Key Characteristics of the Change:

Documentation

Forecasted Key Milestones:

Milestones	Availability
Quartus® Prime Pro Firmware and Partial Reconfiguration User Guide Updates for Intel® Agilex® 7	Now

Description of Change to the Customer:

This is the same change described in ADV2320 issued on October 06, 2023.

Intel® is notifying customers of important updates to firmware and partial reconfiguration user guides related to Intel® Agilex® 7 F, I & M Series Devices

#	Changes to	Update Details	
1)	Quartus Prime Pro Edition Software Version 23.2	Replaced "M20K CE auto insertion feature" with a new solution in Quartus Prime Pro Edition Software Version 23.2. See KDB for details: https://www.intel.com/content/www/us/en/support/programmable/articles/000094431.html	
2)	Intel® Quartus® Prime Pro Edition User Guide: Partial Reconfiguration	Added to the <u>Partial Reconfiguration (PR) User Guide</u> Agilex 7 M20K local clock restriction, and removed description about M20K CE auto insertion feature and instruction introduced in Quartus 23.1.	
3)	Important Firmware Updates in Quartus Prime Pro Edition Software Version 23.2	For Agilex 7 F & I Series only: Update to fix M20K RAM block functional failure after a full reconfiguration operation. (See KDB for details: https://www.intel.com/content/www/us/en/support/programmable/articles/000096007.html)	

Page 1 of 3 PCN #119699-00

For all Agilex 7: Update to fix a functional failure after Partial Reconfiguration operation. (See KDB for details: https://www.intel.com/content/www/us/en/support/programmable/articles/000094452.html)
For Agilex 7 AGF019, AGF023, AGI019, AGI023, AGI040, AGI041, AGM039 devices: Update to fix reconfiguration error by nCONFIG assertion timing. (See KDB for details: https://www.intel.com/content/www/us/en/support/programmable/articles/000095342.html)

Customer Impact of Change and Recommended Action:

Customers are requested to review the changes and determine the impact on their designs. Refer to the revision history of the updated documents for a complete list and history of updates.

For questions or support, please contact your local Sales representative, or submit a question or request at the My Intel support page, log-in via: https://www.intel.com/content/www/us/en/my-intel/fpga-sign-in.html

Products Affected/Intel Ordering Codes:

The list of affected part numbers (OPNs) can be downloaded in Excel form: https://cdrdv2.intel.com/v1/dl/getContent/790564

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
October 10, 2023	00	Originally Published PCN

Page 2 of 3 PCN #119699-00

intel.

Product Change Notification 119699-00

Notices & Disclaimers

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade, except as provided in a separate written agreement.

You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes the subject matter disclosed herein.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Statements in this document that refer to future plans or expectations are forward-looking statements. These statements are based on current expectations and involve many risks and uncertainties that could cause actual results to differ materially from those expressed or implied in such statements. For more information on the factors that could cause actual results to differ materially, see our most recent earnings release and SEC filings at www.intc.com.

Customer is responsible for safety of the overall system, including compliance with applicable safety-related requirements or standards.

Intel technologies may require enabled hardware, software or service activation.

No product or component can be absolutely secure.

Your costs and results may vary.

©Intel Corporation. Intel, the Intel logo, and other Intel marks are trademarks of Intel Corporation or its subsidiaries. Other names and brands may be claimed as the property of others.

No response from customers will be deemed an acceptance of the change, and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com **Japan Email:** jccb.ijkk@intel.com

Page 3 of 3 PCN #119699-00