



Product Group: TC/Wed Jun 29, 2022/PTN-TC-004-2022-REV-0

Terminate manufacturing of T58A0107M6R3C0100 and T58A0107M6R3C0150

DESCRIPTION OF CHANGE: Vishay will discontinue production of T58A0107M6R3C0100 and T58A0107M6R3C0150

REASON FOR CHANGE: Manufacturing of T58A0107M6R3C0100 and T58A0107M6R3C0150 no longer cost effective.

T58A0107M6R3C0200 part number will be established for replacement.

EXPECTED INFLUENCE ON QUALITY/RELIABILTY/PERFORMANCE: No

PART NUMBERS/SERIES/FAMILIES AFFECTED: T58A0107M6R3C0100, T58A0107M6R3C0150,

VISHAY BRAND(s): Vishay

TIME SCHEDULE:

Last Time Buy Date: Tue Jan 3, 2023 Last Time Ship Date: Mon Jul 3, 2023

SAMPLE AVAILABILITY: Upon Request

PRODUCT IDENTIFICATION: N/A

QUALIFICATION DATA: N/A

This PCN is considered approved, without further notification, unless we receive specific customer concerns before Sun Aug 28, 2022 or as specified by contract.

ISSUED BY: Yuri Stangrit, yuri.stangrit@vishay.com

For further information, please contact your regional Vishay office.

CONTACT INFORMATION:

| Americas | Europe | Asia |
|------------------------------------|--------------------------|-------------------------------|
| David Bellomy | Thomas Poessnecker | Boon Hooi Tan |
| 7557 Rambler Road, Suite 575 | DrFelix-Zandman-Platz 1 | 37A Tampines Street 92 #07-01 |
| Dallas TX United States 75231-4142 | Selb Germany 95100 | Singapore Singapore 528886 |
| David.Bellomy@vishay.com | Poessnecker@vishay.com | Boonhooi.Tan@Vishay.com |
| Phone: (254)479-0010 | Phone: + 49 9287 712 595 | Phone: + 65 - 6780 - 7759 |
| Fax: +1 214-363-9444 | Fax: + 49 9287 712 274 | Fax: + 65 - 6780 - 7749 |