

Terminate manufacturing of T58W9476M6R3C0150

For further information, please contact your regional Vishay office.

CONTACT INFORMATION

Americas

David Bellomy
7557 Rambler Road, Suite 575
-
Dallas TX United States 75231-4142
Phone: (254)479-0010
Fax: +1 214-363-9444
David.Bellomy@vishay.com

Europe

Thomas Poessnecker
Dr.-Felix-Zandman-Platz 1
-
Selb Germany D-95100
Phone: + 49 9287 712 595
Fax: + 49 9287 712 274
Thomas.Poessnecker@Vishay.com

Asia

Boon Hooi Tan
37A Tampines Street 92, #07-00
-
Singapore Singapore 528886
Phone: +65-6780-7759
Fax: +65-6780-7749
Boonhooi.Tan@Vishay.com

Description of Change: Vishay will discontinue production of T58W9476M6R3C0150.

Reason for Change: Manufacturing of T58W9476M6R3C0150 is no longer cost effective. T58W9476M6R3C0200 part number is available for replacement.

Expected Influence on Quality/Reliability/Performance: NO

Part Numbers/Series/Families Affected: T58W9476M6R3C0150

Vishay Brand(S): Vishay

Time Schedule:

Last Time Buy Date: Mon May 27, 2024

Last Time Ship Date: Tue Aug 27, 2024

Sample Availability: Will be supported with T58W9476M6R3C0200 only

Product Identification: N/A

Qualification Data: N/A

This PTN is considered approved, without further notification, unless we receive specific customer concerns before Thu Sep 28, 2023 or as specified by contract.

Issued By: Yuri Stangrit, Yuri.Stangrit@vishay.com