



July 15, 2019

## Product Change Notice: Spec update for GTM91128LI3C1000XFX9 PCN# 07.15.19 REV. A


Datasheet for GTM91128LI3C1000XFX9 was updated to rev B to fix incorrect connector that was shown in Rev A.

Incorrect connector

Front View



## Correct connector



Pin 1: BAT(+),Pin 2: N/C,Pin 3: BAT(-)

This change will have no effect on product's form/fit/function of Globtek product.

For any questions about this product change notice, please contact your GlobTek Sales Engineer at (201) 784-1000, visit our website at www.globtek.com or Email: sales@globtek.com.