MORNSUN[®]

Product and Process Changed Notification

Document NO.: MS-PCN-21	Notification Date: 2023/4/3
Product Model	
LM600-12Bxx Series	
Changed Type	
■Design □Material □Process Flow □,	Appearance
□Others	
Reason for Change	
Old terminals are discontinued and need to be replaced by new terminals.	
Changed Content	
Whether the Appearance Changes: \blacksquare Yes \Box N	0
Before Changing:	After Changing:
There is through holes at the top of the terminal	There is no through hole at the top of the terminal cover.
cover.	
Impact on Quality & Performance	
After the change, need to open the cover and then connect the wiring.	
Last order date before the change: 2023/6/12	
The earliest receipt time of samples after change: 2023/4/13	
The earliest mass production time of the product after the change: $2023/6/13$	
Designer (Senior Manager Initiate senior manager of department): Weng Bin	
Customer Admit	
□Approved □Rejected;	
Suggestion:	

MORNSUN[®]

Sign:

Date:

Note:

If you have any questions, please submit them to us within 30 days after receiving the product and process change notice, otherwise your company will accept this change by default.