BOURNS

Product Change Notification

INDUCTIVE COMPONENTS



January, 2018

Terminal 1

Mark

Bourns® Model SRF0703A, SRF1260A, SRF1280A and SRF1278 Series **Dual-Winding Shielded Power Inductors**

Terminal 1 Identification Marker Added

Bourns is making a change to the Model SRF0703A, SRF1260A, SRF1280A and SRF1278 Series Dual-Winding Shielded Power Inductors to include an identification marker for Terminal 1. The new identification marker will assist users in better identifying the orientation of the component.



On the data sheet, the terminal number assignment (shown below) will be rearranged to align with the Terminal 1 marker. These numbers are not marked on the actual part.

The mounting base mold injection mark, which appears as a circle on the bottom view of the drawing, will be removed from data sheet.



Users should verify that the described changes will not impact the performance of the product in their specific applications.

The products' form (appearance) will change due to the addition of the terminal dot marking. There will be no change to the fit, function, quality or reliability of the product.

SRF0703A Series	SRF1260A Series	SRF1280A Series	SRF1278 Series
SRF0703A-100M	SRF1260A-100M	SRF1280A-100M	SRF1278-681ML
SRF0703A-101M	SRF1260A-101M	SRF1280A-101M	
SRF0703A-150M	SRF1260A-102M	SRF1280A-102M	
SRF0703A-151M	SRF1260A-150M	SRF1280A-150M	
SRF0703A-220M	SRF1260A-151M	SRF1280A-151M	
SRF0703A-221M	SRF1260A-1R0Y	SRF1280A-1R0Y	
SRF0703A-330M	SRF1260A-1R5Y	SRF1280A-1R5Y	
SRF0703A-331M	SRF1260A-220M	SRF1280A-220M	
SRF0703A-470M	SRF1260A-221M	SRF1280A-221M	
SRF0703A-680M	SRF1260A-2R2Y	SRF1280A-2R2Y	
SRF0703A-820M	SRF1260A-330M	SRF1280A-330M	
SRF0703A-8R2M	SRF1260A-331M	SRF1280A-331M	
	SRF1260A-3R3Y	SRF1280A-3R3Y	
	SRF1260A-470M	SRF1280A-470M	
	SRF1260A-471M	SRF1280A-471M	
	SRF1260A-4R7Y	SRF1280A-4R7Y	
	SRF1260A-680M	SRF1280A-652Y	
	SRF1260A-681M	SRF1280A-680M	
	SRF1260A-6R8Y	SRF1280A-681M	
	SRF1260A-820M	SRF1280A-6R8Y	
	SRF1260A-821M	SRF1280A-820M	
	SRF1260A-8R2Y	SRF1280A-821M	
	SRF1260A-R47Y	SRF1280A-8R2Y	
		SRF1280A-R47Y	

Affected Part Numbers

Implementation dates are as follows:

Date that manufacturing of existing products without the terminal dot will cease: **July 28, 2018** Date that deliveries of modified products with the terminal dot will begin: **July 29, 2018** First date code using the above changes: **1831**

If you have any questions or need additional information, please feel free to contact Customer Service/ Inside Sales.