



Product Change Notification

TE Connectivity

Product Change Notification: P-23-024961

PCN Date: 11-AUG-23

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

623/923 IC logo new design style on housings

Description of Changes

Dear valued customer, referring to the attached comparison the IC Logo new style is the only difference. All electrical and mechanical characteristics remain unchanged. Please find affected TCPN's in overview below

Other attachments:

[IC Logo Style comparison](#)

Reason for Changes:

Part status change. New IC logo style has been and will be implemented on all new housing tools. Please accept mixed delivery of both housing styles.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

01-JAN-2026

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|------------------------------------|---------------------------|------------------|----------------------|------------------------|------------------------|---------------------------------|---------------------------|
| AGC110N00001215000 | NO | | | "AEDC110NN00001215000" | | | |
| AGC113N00001215000 | NO | | | "AEDC113NN00001215000" | | | |
| AGC139N00001215000 | NO | | | "AEDC139NN00001215000" | | | |
| AKA020N00090200000 | NO | | | "AKUA020NN00090200000" | | | |
| AKA020N00620200000 | NO | | | "AKUA020NN00620200000" | | | |
| AKA020N00750200000 | NO | | | "AKUA020NN00750200000" | | | |
| AKA021N00750200000 | NO | | | "AKUA021NN00750200000" | | | |
| AKA034N00090200000 | NO | | | "AKUA034NN00090200000" | | | |
| ASA001N00480650000 | NO | | | "ASTA001NN00480650000" | | | |
| BKA186N00420200000 | NO | | | "BKUA186NN00420200000" | | | |
| BKA199N00110200000 | NO | | | "BKUA199NN00110200000" | | | |
| BKA199N00420200000 | NO | | | "BKUA199NN00420200000" | | | |
| BSA078N00420100000 | NO | | | "BSTA078NN00420100000" | | | |
| BSA078N00480235000 | NO | | | "BSTA078NN00480235000" | | | |
| BSA078N00580100000 | NO | | | "BSTA078NN00580100000" | | | |
| BSA078N00580235000 | NO | | | "BSTA078NN00580235000" | | | |
| BSA078N00590235000 | NO | | | "BSTA078NN00590235000" | | | |
| BSA085N00420100000 | NO | | | "BSTA085NN00420100000" | | | |
| BSA085N00480235000 | NO | | | "BSTA085NN00480235000" | | | |
| BSA085N00550100000 | NO | | | "BSTA085NN00550100000" | | | |
| BSA085N00580100000 | NO | | | "BSTA085NN00580100000" | | | |
| BSA085N00580235000 | NO | | | "BSTA085NN00580235000" | | | |
| BSA107N00080236000 | NO | | | "BSTA107NN00080236000" | | | |
| BSA107N00480136000 | NO | | | "BSTA107NN00480136000" | | | |
| BSA108N00420136000 | NO | | | "BSTA108NN00420136000" | | | |
| BSA108N00420236000 | NO | | | "BSTA108NN00420236000" | | | |
| BSA108N00480236000 | NO | | | "BSTA108NN00480236000" | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|------------------------------------|---------------------------|------------------|----------------------|------------------------|------------------------|---------------------------------|---------------------------|
| BSA078N00420100000 | NO | | | "BSTA078NN00420100000" | | | |
| BSA108N00480236000 | NO | | | "BSTA108NN00480236000" | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|------------------------------------|---------------------------|------------------|----------------------|------------------------|------------------------|---------------------------------|---------------------------|
| AGC110N00001215000 | NO | | | "AEDC110NN00001215000" | | | |
| AGC113N00001215000 | NO | | | "AEDC113NN00001215000" | | | |
| AGC139N00001215000 | NO | | | "AEDC139NN00001215000" | | | |
| AKA020N00090200000 | NO | | | "AKUA020NN00090200000" | | | |
| AKA020N00620200000 | NO | | | "AKUA020NN00620200000" | | | |
| AKA020N00750200000 | NO | | | "AKUA020NN00750200000" | | | |
| AKA021N00750200000 | NO | | | "AKUA021NN00750200000" | | | |
| AKA034N00090200000 | NO | | | "AKUA034NN00090200000" | | | |
| ASA001N00480650000 | NO | | | "ASTA001NN00480650000" | | | |
| BKA186N00420200000 | NO | | | "BKUA186NN00420200000" | | | |
| BKA199N00110200000 | NO | | | "BKUA199NN00110200000" | | | |
| BKA199N00420200000 | NO | | | "BKUA199NN00420200000" | | | |
| BSA078N00420100000 | NO | | | "BSTA078NN00420100000" | | | |
| BSA078N00480235000 | NO | | | "BSTA078NN00480235000" | | | |
| BSA078N00580100000 | NO | | | "BSTA078NN00580100000" | | | |
| BSA078N00580235000 | NO | | | "BSTA078NN00580235000" | | | |
| BSA078N00590235000 | NO | | | "BSTA078NN00590235000" | | | |
| BSA085N00420100000 | NO | | | "BSTA085NN00420100000" | | | |
| BSA085N00480235000 | NO | | | "BSTA085NN00480235000" | | | |
| BSA085N00550100000 | NO | | | "BSTA085NN00550100000" | | | |
| BSA085N00580100000 | NO | | | "BSTA085NN00580100000" | | | |
| BSA085N00580235000 | NO | | | "BSTA085NN00580235000" | | | |
| BSA107N00080236000 | NO | | | "BSTA107NN00080236000" | | | |
| BSA107N00480136000 | NO | | | "BSTA107NN00480136000" | | | |
| BSA108N00420136000 | NO | | | "BSTA108NN00420136000" | | | |
| BSA108N00420236000 | NO | | | "BSTA108NN00420236000" | | | |
| BSA108N00480236000 | NO | | | "BSTA108NN00480236000" | | | |

Comparison „Old“ and „New“ IC Logo style

CURRENT Version



FUTURE Version

