



Product Change Notification / SYST-12GBRA223

Date:

31-Jan-2024

Product Category:

USB Hubs

PCN Type:

Document Change

Notification Subject:

Data Sheet - USB7252C 4-Port USB 3.2 Gen 2 Type-C Controller Hub Data Sheet

Affected CPNs:

[SYST-12GBRA223_Affected_CPN_01312024.pdf](#)

[SYST-12GBRA223_Affected_CPN_01312024.csv](#)

Notification Text:

SYST-12GBRA223

Microchip has released a new Datasheet for the USB7252C 4-Port USB 3.2 Gen 2 Type-C Controller Hub Data Sheet of devices. If you are using one of these devices please read the document located at [USB7252C 4-Port USB 3.2 Gen 2 Type-C Controller Hub Data Sheet](#).

Data Sheet - USB7252C 4-Port USB 3.2 Gen 2 Type-C Controller Hub Data Sheet

Notification Status: Final

Description of Change: DS00003852B (12-12-23) Highlights Modified first feature: 4-Port USB 3.2 Gen2 SmartHub with:- USB 3.2 Gen 2 Type-B on upstream port- Two Native USB-C® USB 3.2 Gen 2 downstream ports- One Standard USB 3.2 Gen 2 downstream port- One Standard USB 2.0 downstream port

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 31 Jan 2024

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

[USB7252C 4-Port USB 3.2 Gen 2 Type-C Controller Hub Data Sheet](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

USB7252C-I/KDX

USB7252C/KDX

USB7252CT-I/KDX

USB7252CT/KDX

USB7252CT/KDXD01