

## **Notification of Product Discontinuance**

Doc. No.: 4023100

This letter intends as a formal notification of discontinuance of products which are currently supplied by ROHM Co., Ltd.

ROHM Co., Ltd. requires customers to provide acknowledgment of the receipt of this notification within 30 days from the date of this notice. Lack of acknowledgment of this notice within 30 days is considered as acceptance of the change.

After acknowledgement of the customer, lack of additional response within 90 day period constitutes acceptance of the change according to JEDEC Standard J-STD-046.

Your understanding and cooperation would be highly appreciated.

## Issue Date:

Product category	Affected part number(s)	Suggested replacement product	
TO-252 (In house)	see attached	see attached	
Reason for discontinuance			
To switch to outsourced TO-252 (made by 0	GEM)		
Product discontinuance date			
Last time buy :	time buy : / Last time shipment :		
<del>-</del>	_		
<u>Comments</u>			
There are no Last time buy and Last time shipment dates as there are alternative part numbers.			
<u>Supplier contact</u>			
Please contact the local ROHM sales office o	r the authorized distributor.		
[Regarding environmental data and other properties of the properti	· · · · · · · · · · · · · · · · · · ·		
Notes			

対象形名		
Affected PN	Alt PN	
 社外形名	社外形名	
External PN	External PN	
RB075BM40STL	RB075BGE40STL	
RB078BM30STL	RB078BGE30STL	
RB085BM-30TL	RB085BGE-30TL	
RB085BM-40TL	RB085BGE-40TL	
RB085BM-60TL	RB085BGE-60TL	
RB085BM-90TL	RB085BGE-90TL	
RB088BM100TL	RB088BGE100TL	
RB088BM150TL	RB088BGE150TL	
RB088BM-30TL	RB088BGE-30TL	
RB088BM-40TL	RB088BGE-40TL	
RB088BM-60TL	RB088BGE-60TL	
RB095BM-30TL	RB095BGE-30TL	
RB095BM-40TL	RB095BGE-40TL	
RB095BM-60TL	RB095BGE-60TL	
RB095BM-90TL	RB095BGE-90TL	
RB098BM100TL	RB098BGE100TL	
RB098BM150TL	RB098BGE150TL	
RB098BM-30TL	RB098BGE-30TL	
RB098BM-40TL	RB098BGE-40TL	
RB098BM-60TL	RB098BGE-60TL	
RBQ10BM45ATL	RBQ10BGE45ATL	
RBQ10BM65ATL	RBQ10BGE65ATL	
RBQ15BM45ATL	RBQ15BGE45ATL	
RBQ15BM65ATL	RBQ15BGE65ATL	
RBQ20BM45ATL	RBQ20BGE45ATL	
RBQ20BM65ATL	RBQ20BGE65ATL	
RBR10BM30ATL	RBR10BGE30ATL	
RBR10BM40ATL	RBR10BGE40ATL	
RBR10BM60ATL	RBR10BGE60ATL	
RBR15BM30ATL	RBR15BGE30ATL	
RBR15BM40ATL	RBR15BGE40ATL	
RBR15BM60ATL	RBR15BGE60ATL	
RBR20BM30ATL	RBR20BGE30ATL	
RBR20BM40ATL	RBR20BGE40ATL	
RBR20BM60ATL	RBR20BGE60ATL	
RF301BM2STL	RF301BGE2STL	
RF305BM6STL	RF305BGE6STL	
RF501BM2STL	RF501BGE2STL	
RF505BM6STL	RF505BGE6STL	

RF601BGE2DTL	
RFN10BGE3STL	
RFN10BGE6STL	
RFN3BGE2STL	
RFN3BGE6STL	
RFN5BGE2STL	
RFN5BGE3STL	
RFN5BGE6STL	
RFN6BGE2DTL	
RFNL10BGE6STL	
RFNL5BGE6STL	
RFV5BGE6STL	
RFV8BGE6STL	
RR601BGE4STL	
RSX058BGE2STL	
RSX078BGE2STL	