

Product Change Notice

Issue Date: 07-May-2024





Change Description:

Manufacturing location change and standardization of housing colorants for 5 pins cable connector used in HRPG-XXXX#XXC encoder cable option.

Parts Affected:

Broadcom Part Number	Product Description
HRPG-AD16#XXC	RPG, Det,16CPR, L XX, DXX, Cable Option
HRPG-AD32#XXC	RPG, Det,32CPR, L XX, DXX, Cable Option
HRPG-AS32#XXC	RPG, Smt,32CPR, L XX, DXX, Cable Option
HRPG-ASCA#XXC	RPG, Smt,120CPR, L XX, DXX, Cable Option

Description and Extent of Change:

Change Manufacturing Location and Housing Color Standardization 5 Pins Cable Connector			
Before Change		After Change	
Manufacturing Location A Connector Housing Color - Light Blue		Manufacturing Location B Connector Housing Color - Solid Blue	
			

Reasons for Change:

- The 5 pins cable connector manufacturer announced change manufacturing location (location A to location B)
- Standardization of housing colorant used in 5 pins cable connector (Light Blue to Solid Blue)

Effect of Change on Fit, Form, Function, Quality, or Reliability:

The 5 pins connector changed has no impact to Form, Fit, Function and product performance.

Effective Date of Change:

Product shipment with this change is effective by October 2024.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.