

Product Change Notice

Issue Date: 14-August-2023

Change Description:

Add alternate source and change to natural color material for duplex non- latching plug.

Parts Affected:

HFBR-RMD001Z
 HFBR-RMD002Z
 HFBR-RMD003Z
 HFBR-RMD005Z
 HFBR-RMD010Z
 HFBR-4506Z

Description and Extent of Change:

Change to natural color material for duplex non-latching plug for above affected part number.



Reasons for Change:

Assurance of supply.
 Eliminate color compounding.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

There is a no change in Fit and Function but there is a change in Form (appearance) as below comparison.

Appearance comparison as below.

Current color	New color
Duplex non latching plug  Color: Beige	Duplex non latching plug  Color: Natural

Effective Date of Change:

Product shipment which may contain natural color part may begin on or after **14-November-2023**.
 Timing of shipment of the natural color part will depend on customer demand and inventory level.

Qualification Data:

The qualification samples have passed full dimensions check and meet all the qualification criteria. No change in reliability performance.
 Qualification data will be provided upon request.



Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.