



Precautions

◆Notification for Insertion Extraction

1) Please insert(extract) the crimping socket straight to the mating connector. Insertion(extraction) at tilted angles applies load concentration to the connetor end and may cause deformation (at connection area, socket and header case, etc). There is firing risk using this kind of defomed connector.





Notification of wiring

Extraction

Calculation

Extraction


Calculation


Calculation of Wiring

When using a thick cable, short cable length and bending Class

You in the connector beforehand and then put it with releasing the lock.

Forced extraction has a risk of connector breakage. 1) When using a thick cable, short cable length and bending close to the connector end, these load concentration may couse deformation. When installing, please refrain from stress concentration such as cable bending close to the connector end or cable twisting.





2) Since this product uses thick wires, a larger load is applied to the connector when inserting/extracting or routing the wires. Please use a retainer to reduce the load on the connector.

HS	DRAWING NO.	EDC-163718-53-00	
	PART NO.	DF22-*P-7.92DS(53)
	CODE NO.	CL680-	\triangle $\frac{2}{2}$

FORM HC0011-5-8 1