



Product Change Notification

TE Connectivity

Product Change Notification: PCN-23-175836

PCN Date: 11-JUL-23

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Package (Carton size) change

Description of Changes

Dear Customer, In order to improve customer experience, a unified optimization adjustment will be made to the labels and box specifications on the external packaging box. Mainly changes, 1. Replace some old packaging boxes with unified specification packaging boxes, slightly dimension changes Before- 759598-000 - 1279*252*254 After- CR7224-000 - 1300*270*270 759598-000 CR7224-000 Before- 394718-000 - 1280*256*130 After- CR7225-000- 1300*260*140 394718-000 CR7225-000 Before- 406079-000- 605*308*308 After- CR7226-000- 600*310*310 406079-000 CR7226-000 2. Modification of label position, which are unified on sealing surface. This PCN will be effective in Sep.10th. For any questions or concerns please contact your local Customer Care Professional.

Reason for Changes:

PCN Attributes:

Product Category:	Kind of Change:
Heat Shrink Tubing	Packaging Type
Change Feature:	Potential Customer Impact:
Bulk	No Customer Impact
Remarks:	

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Ship Date of Changed Items (Changed Parts Only):
	10-SEP-2023
Last Ship Date of Changed Items (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments
Effectivity Date:	Date of First Samples:

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0081930003	NO			"4-1190063-2", "ES-CAP-NO.1-C1-X-35MM"			
0081930005	NO			"4-1190063-3", "ES-CAP-NO.1-C1-X-40MM"			
035377P004	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
063725P011	NO			"5-1190481-1", "ES2000-NO.2-B9-0-50MM"			
063725P018	NO			"5-1190481-8", "ES2000-NO.2-B9-0-30MM"			
063725P022	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
085193P003	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
121397P024	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
130599P003	NO			"6-1190948-1", "ES2000-NO.4-B7-0-75MM"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
130599P007	NO			"6-1190948-5", "ES2000-NO.4-B7-0-60MM"			
1335390003	NO			"8-1190969-8", "ES-CAP-NO.3-B8-X-40MM"			
193197P004	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			
193197P008	NO			"5-1191401-1", "ES1000-NO.1-C1-X-50MM"			
206247P038	NO			"2-1191495-7", "SCT-NO.4-E2-0-STK"			
2525596002	NO			"5-1191848-0", "RBK-ILS-125-NR1-0-50MM"			
269647-000	NO			"1-1191990-6", "ES-CAP-HW-NO.3-M8-0-45MM"			
3371890003	NO			"7-1192545-9", "ES-CAP-NO.1-C1-0-35MM"			
3371890005	NO			"8-1192545-0", "ES-CAP-NO.1-C1-0-40MM"			
415877P006	NO			"5-1193134-9", "FL2500-NO.1-I8-0-27MM"			
4367790003	NO			"1-1193283-5", "ES-CAP-NO.2-B9-0-35MM"			
5070082131	NO			"2-1193965-3", "RNF-100-1/2-CL-STK"			
5201976026	NO			"5-1194087-5", "RT-3-NO.2-0-1IN"			
5202062019	NO			"5-1194088-8", "RT-3-NO.1-0-STK"			
537637P041	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
543633P051	NO			"3-1194264-7", "SCT-NO.1-E6-0-50MM"			
543633P064	NO			"5-1194264-0", "SCT-NO.1-E6-0-STK"			
576105P004	NO			"7-1194570-9", "ES1000-NO.2-B9-X-STK"			
607381P046	NO			"5-1194804-3", "SCT-NO.2-E5-0-STK"			
636901P014	NO			"8-1195035-6", "QS1500-NO.3-F7-0-STK"			
7501716003	NO			"3-1195850-2", "RBK-ILS-125-NR4-0-75MM"			
829131P012	NO			"7-1196474-1", "ES2000-NO.1-C1-0-50MM"			
829131P019	NO			"7-1196474-7", "ES2000-NO.1-C1-0-27MM"			
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
D20444-000	NO			"1-1199653-5", "FL2500-NO.1-I8-0-STK"			
E43149-000	NO			"3-1199653-6", "FL2500-NO.2-I9-0-STK"			
E95757-000	NO			"4-1199653-3", "FL2500-NO.4-J2-0-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
130599P007	NO			"6-1190948-5", "ES2000-NO.4-B7-0-60MM"			
3371890005	NO			"8-1192545-0", "ES-CAP-NO.1-C1-0-40MM"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
130599P007	NO			"6-1190948-5", "ES2000-NO.4-B7-0-60MM"			
3371890005	NO			"8-1192545-0", "ES-CAP-NO.1-C1-0-40MM"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0081930003	NO			"4-1190063-2", "ES-CAP-NO.1-C1-X-35MM"			
0081930005	NO			"4-1190063-3", "ES-CAP-NO.1-C1-X-40MM"			
085193P003	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
130599P007	NO			"6-1190948-5", "ES2000-NO.4-B7-0-60MM"			
193197P004	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			
2525596002	NO			"5-1191848-0", "RBK-ILS-125-NR1-0-50MM"			
269647-000	NO			"1-1191990-6", "ES-CAP-HW-NO.3-M8-0-45MM"			
3371890005	NO			"8-1192545-0", "ES-CAP-NO.1-C1-0-40MM"			
537637P041	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
636901P014	NO			"8-1195035-6", "QS1500-NO.3-F7-0-STK"			
7501716003	NO			"3-1195850-2", "RBK-ILS-125-NR4-0-75MM"			
D20444-000	NO			"1-1199653-5", "FL2500-NO.1-I8-0-STK"			
E43149-000	NO			"3-1199653-6", "FL2500-NO.2-I9-0-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0081930003	NO			"4-1190063-2", "ES-CAP-NO.1-C1-X-35MM"			
0081930005	NO			"4-1190063-3", "ES-CAP-NO.1-C1-X-40MM"			
085193P003	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
130599P007	NO			"6-1190948-5", "ES2000-NO.4-B7-0-60MM"			
193197P004	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2525596002	NO			"5-1191848-0", "RBK-ILS-125-NR1-0-50MM"			
269647-000	NO			"1-1191990-6", "ES-CAP-HW-NO.3-M8-0-45MM"			
3371890005	NO			"8-1192545-0", "ES-CAP-NO.1-C1-0-40MM"			
537637P041	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
636901P014	NO			"8-1195035-6", "QS1500-NO.3-F7-0-STK"			
7501716003	NO			"3-1195850-2", "RBK-ILS-125-NR4-0-75MM"			
D20444-000	NO			"1-1199653-5", "FL2500-NO.1-I8-0-STK"			
E43149-000	NO			"3-1199653-6", "FL2500-NO.2-I9-0-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
035377P004	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
063725P018	NO			"5-1190481-8", "ES2000-NO.2-B9-0-30MM"			
063725P022	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
121397P024	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
5070082131	NO			"2-1193965-3", "RNF-100-1/2-CL-STK"			
576105P004	NO			"7-1194570-9", "ES1000-NO.2-B9-X-STK"			
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
543633P051	NO			"3-1194264-7", "SCT-NO.1-E6-0-50MM"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0081930005	NO			"4-1190063-3", "ES-CAP-NO.1-C1-X-40MM"			
063725P011	NO			"5-1190481-1", "ES2000-NO.2-B9-0-50MM"			
085193P003	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
130599P003	NO			"6-1190948-1", "ES2000-NO.4-B7-0-75MM"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
1335390003	NO			"8-1190969-8", "ES-CAP-NO.3-B8-X-40MM"			
193197P004	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			
193197P008	NO			"5-1191401-1", "ES1000-NO.1-C1-X-50MM"			
206247P038	NO			"2-1191495-7", "SCT-NO.4-E2-0-STK"			
3371890003	NO			"7-1192545-9", "ES-CAP-NO.1-C1-0-35MM"			
415877P006	NO			"5-1193134-9", "FL2500-NO.1-I8-0-27MM"			
4367790003	NO			"1-1193283-5", "ES-CAP-NO.2-B9-0-35MM"			
5201976026	NO			"5-1194087-5", "RT-3-NO.2-0-1IN"			
5202062019	NO			"5-1194088-8", "RT-3-NO.1-0-STK"			
537637P041	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
543633P064	NO			"5-1194264-0", "SCT-NO.1-E6-0-STK"			
576105P004	NO			"7-1194570-9", "ES1000-NO.2-B9-X-STK"			
607381P046	NO			"5-1194804-3", "SCT-NO.2-E5-0-STK"			
829131P012	NO			"7-1196474-1", "ES2000-NO.1-C1-0-50MM"			
829131P019	NO			"7-1196474-7", "ES2000-NO.1-C1-0-27MM"			
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
D20444-000	NO			"1-1199653-5", "FL2500-NO.1-I8-0-STK"			
E95757-000	NO			"4-1199653-3", "FL2500-NO.4-J2-0-STK"			