

PRODUCT DISCONTINUATION NOTICE

PDN No.: 2022-008

Products:	Type	Nearest replacement(s)
	MUBW10-12A7	MIXA10WB1200TED / MIXA20WB1200TED
	MUBW15-12A7	MIXA20WB1200TED / MIXA30WB1200TED
	MUBW25-12A7	MIXA30WB1200TED / MIXA40WB1200TED
	MUBW35-12A7	MIXA40WB1200TED
	MUBW50-12A8	MIXA60WB1200TEH
	MUBW75-12T8	MIXA80WB1200TEH
	MWI15-12A7 / MWI15-12A7T	MIXA30W1200TED *
	MWI25-12A7 / MWI25-12A7T	MIXA30W1200TED * / MIXA41W1200TED
	MWI35-12A7	MIXA41W1200TED / MIXA60W1200TED *
	MWI50-12A7 / MWI50-12A7T	MIXA60W1200TED *
	MWI50-12T7T	MIXA40W1200TED / MIXA60W1200TED
	MWI75-12T7T	MIXA60W1200TED / MIXA80W1200TED
	MWI75-12A8 / MWI75-12A8T	MIXA80W1200TEH*
	MWI100-12A8 / MWI100-12A8T	MIXA100W1200TEH* / MIXG120W1200TEH *
	MWI150-12T8T	MIXA150W1200TEH / MIXG180W1200TEH
	MKI50-12F7	no replacement

Note *: Pin layout is different

Reason: Die discontinuation and low demand

Last time order date: 2023-02-28

Last time delivery date: 2024-10-31

Internal Reference: PO_2022-008

In case of any question, please contact

Initiator	Title/Function	Date	e-mail
Andreas Laschek-Enders IXYS Semiconductor GmbH Edisonstr. 15 D-68623 Lampertheim Phone: +49-6206-503-201 Fax: +49-6206-503-627	PM	Dec. 9 th 2022	alaschek-enders@littelfuse.com

Customer response:

(please fill in and return by e-mail, fax or mail within 4 weeks)

☐ for further questions / information Company: _____

please comment Name & Position: _____

Phone / Fax No.: _____

Comments: _____
