

 ENCLUSTRA <small>FPGA SOLUTIONS</small>	Enclustra - Product Change Notification (PCN)	No.: PCN_SP_2023-016
		Date: 09.08.2023

Affected Products	
Product Series	Mercury+ AA1
Affected Product Model	Product models with USB 3.0 controller FX3 Cypress chip
Affected Parts	[EN101914] ME-AA1-270-3E4-D11E-R2 [EN101917] ME-AA1-480-2I3-D12E-R2 [EN101915] ME-AA1-270-2I2-D11E-R2 [EN101916] ME-AA1-480-1E2-D12E-R2
Replacement Parts	[EN104217] ME-AA1-270-2I2-D11E-NFX3-R2 [EN104216] ME-AA1-270-3E4-D11E-NFX3-R2 [EN104218] ME-AA1-480-2I3-D12E-NFX3-R2

Type of PCN, Description and expected impact for customers	
Type of PCN	<p>A – Post on Enclustra Website</p> <input type="checkbox"/> Removal of Product Model (if no customer is affected) <input type="checkbox"/> Minor Revision without impact on customer <input type="checkbox"/> Other, specify: <p>B – Inform current customers</p> <input type="checkbox"/> Increase of minimum order quantity (MOQ) <input type="checkbox"/> Status Changes to end-of-life (EOL) <input checked="" type="checkbox"/> Removal of Product Model (if customer is affected) <input type="checkbox"/> Major Revision roll-out <input type="checkbox"/> Minor Revision with impact for customer <input type="checkbox"/> Other, specify: <p>C – Inform all affected customers</p> <input type="checkbox"/> Security related bug / Major non-conformance to specification <input type="checkbox"/> Other, specify:
Description of change	Removal of USB 3.0 controller FX3 Cypress chip.
Reason for change	Preferred product models.
Expected impact on customer	Loss of USB 3.0 interface.
Forecasted key milestones	Product models with FX3 chip remain available until stock depletion.

Details of change	
Details	Contact our support team for further details.

Contact	
Details	<p>If you have any questions or require additional information, please contact support@enclustra.com.</p> <p>Web: www.enclustra.com</p>