

**PCN809:** Carling RLD Dimmer Switch Shipment Update

**Issue Date:** August 4<sup>th</sup>, 2023

Dear Valued Customer,

This notice is to inform you an update to PCN725 regarding the alternate supply chain and temporary stop shipment of our RLD Dimmer Switches.

***Description of the Change:***

- PCN725 had notified of supply interruptions causing temporary stop shipment and potential alternate source on two board-level components (Microcontroller/MCU & EEPROM) of our dimmer switches.
- These interruptions will be resolved shortly, giving us the opportunity to ship finished goods with the originally specified components, upon exhausting current inventory of alternate parts.

***Reason for The Change:***

- We have been notified by our suppliers that lead times will return to normal on these components, allowing us to fulfill finished good demand according to previous lead time.

***Effective Date of the Change:***


- We will begin shipping finished goods with the original component upon exhaustion of the alternate stock. This will occur this Fall as a running change.

***What You Need to Do:***

- No action is required if you can accept parts that utilize alternate components.
- If you require parts with originally specified components, please contact your Littelfuse Customer Service or Inside Sales Representative to adjust request date for open orders.

If you have any questions, please contact your Customer Service or Inside Sales Representative. We appreciate your business and our continued partnership.

Sincerely,



Zachary Naughton  
Sr. Manager, Product Management  
Littelfuse Commercial Vehicle Products

Material	Sold-to party	Sold-to party Name	Account owner	LF Inside Sales Rep	P/N Description
RLD-00000103	71141	DIGI-KEY CORP	Tracy Pasnieski	Lori Levesque	LDC51DD13AAFE1FC