

## **Product Change Notification (PCN)**

| PCN Number                                 | 508845   | Date Issued  | September 01, 2020  |
|--|--|--|---|
| Reason for Change                          | Change to Product  |  |   |
| Change Type Description                    | This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change may affect the fit, form, function or appearance of the parts, or it may result in a change to the specification. The pictures below show an example of the possible differences.  |  |   |
| Reason for Short Notice                    | Corrective Actions   |  |   |
| Assessment of Change                       | Dimension analysis   |  |   |
| Internal Molex Qualification Date          | May 08, 2020   |  |   |
| Sample Availability Date<br>(Changed Part) | May 08, 2020   |  |   |
| Planned Implementation Date                | September 01, 2020   |  |   |
| Method of Identifying Change               | Factory order number   | SEL  |   |
| Before Change                              | After C  | hange  |   |
| Before and after change                    | Overv  | view   |   |
| before after                               | Confort<br>A sub-<br>diffe c<br>Chang<br>Produc<br>There is<br>No repa<br>No r | mance;<br>product element known as a metal angle plate is gettim<br>monector and was getting pressed in the current design<br>of the outer geometry to enable reverse application in<br>the simpact to firm dispersance of the product<br>act on Function and Fit<br>umber Impact<br>Including data fits | nt form in order to meet our product<br>changed. This metal angle plate was sticking to the hoods<br>This a undesirable. Cutoris for reverse use are added.<br>the connector is also enabled. |

molex

- Part Number Impact
   —See attached impacted parts list

 Qualification Reports and samples available upon request after the date shown above

Molex Confidential Information © Molex, LLC – All Rights Reserved. Unauthorized Ro

molex

## **molex**<sup>®</sup>

**Product Change Notification (PCN)** 

You may address any technical inquiries regarding this PCN by sending E-mail to pcn\_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:508845**" in the e-mail Subject line for faster response.

## RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com

| PCN #  | Molex Part # |
|--------|--------------|
| 508845 | 1120110021   |
| 508845 | 1120110022   |
| 508845 |              |
| 508845 | 1120110025   |
| 508845 | 1120110027   |
| 508845 | 1120130013   |
| 508845 | 1120130015   |
| 508845 | 1120140004   |
| 508845 | 1120140006   |
| 508845 | 1120160018   |
| 508845 | 1120160022   |
| 508845 | 1120160023   |
| 508845 | 1120165000   |
| 508845 | 1731070078   |
| 508845 | 1731070093   |
| 508845 | 1731070096   |
| 508845 | 1731070099   |
| 508845 | 1731070101   |
| 508845 | 1731070319   |
| 508845 | 1731070322   |
| 508845 | 1731070456   |
| 508845 | 1731071310   |
| 508845 | 1731090176   |
| 508845 | 1731090177   |
| 508845 | 1731090178   |
| 508845 | 1731090179   |
| 508845 | 1731090181   |
| 508845 | 1731090182   |
| 508845 | 1731090183   |
| 508845 | 1731090184   |
| 508845 | 1731130154   |
|        |              |