

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134

PRODUCT DISCONTINUANCE NOTICE

PDN #: M000806

DATE: 20-Jul-2015

Notice Type	Maxim Part Number	Recommeded Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	MAX1491CNI+	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX1492CNI+	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX196ACNI+	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX196AENI+	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX196BCNI+	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX196BENI+	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX197ACNI+	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX197AENI+	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX197BCNI+	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX197BENI+	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX198ACNI+	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX198BCNI+	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX198BENI+	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX199ACNI+	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX199AENI+	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX199BCNI+	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX199BENI+	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX3110ECNI+G36	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX3110EENI+G36	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX3111ECNI+G36	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX3111EENI+G36	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX5935CAX+	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX5945CAX+	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX5945CAX+T	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX5945EAX+	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX5945EAX+T	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Aug-2015

Discontinuance	MAX5952AEAX+	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX5952AUAX+	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX5952AUAX+T	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX5952CEAX+	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX6956ANI+	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX6957ANI+	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX7300ANI+	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured
Discontinuance	MAX7301ANI+	N/A	15-Nov-2015	20-Jul-2017	Part can be not longer manufactured