



CUSTOMER OPERATIONS  
160 RIO ROBLES  
SAN JOSE, CA 95134

PDN #: M000926I

DATE: 17-Jun-2017

## PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Lead-Free Conversion	73M2901CL-IGVR/F	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	73S8010R-DB	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	78P2351R-DB	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	78Q8430-100IGTR/F	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	DG421DY+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	DS1810-10+T&R	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	DS1815-20+T&R	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	DS1816-10+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	DS1816-10+T&R	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	DS1816-20+T&R	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	DS21Q354	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	DS21Q554	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	DS2705EVKIT+	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	DS2705U+T&R	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	DS2705U-CD1+T&R	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	DS2770BE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	HFRA29.12EVKIT	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	HFRD004EVKIT	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	HI1-0201-5	N/A	17-Jun-2017	17-Jun-2017	Part is leaded. Request information on lead-free version
Discontinuance	IH5047C/D	N/A	17-Jun-2017	17-Jun-2017	Part is leaded. Request information on lead-free version
Discontinuance	IH5047MJE	N/A	17-Jun-2017	17-Jun-2017	Part is leaded. Request information on lead-free version
Discontinuance	MAX1111AEPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX1122EGK+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX117EPI+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX1240CCPA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX1240CEPA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Jul-2017

Discontinuance	MAX1248BEPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX1249ACPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX13043EETD+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX13087ECPA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX13170EEVKIT+	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX13174EEVKIT+	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX141CQH+C10006	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX14505AEWC+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX14505AEWC+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX145BEPA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX14625AETA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX14625AETA+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX149BEPP+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX15009ATJ+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX15025BATB+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX15028ATB+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX15087EVKIT#	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX15087EWL+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX15087EWL+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX1510ATB/V+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX1510ATB/V+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX1513ETP+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX1513EVKIT	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX1517ETJ+TG104	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX1517ETJ+TGA8	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX1519ETL+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX152EPP+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX1533ETJ+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX1533ETJ+TG38	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX1533EVKIT	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX15501KGTJ+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX15501KGTJ+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX156AENG+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX159AEPA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX159BCPA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX1600EAI+W	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Jul-2017

Discontinuance	MAX16024EVKIT#	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX16047CETN+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX16047CETN+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX16048ETN+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX161CCPI+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX162BENG+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX162CENG+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX1630EVKIT-SO	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX1635EAI+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX1635EAI+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX163BCNG+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX163BENG+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX164BCNG+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX164BENG+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX166BEPP+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX166CEPP+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX166DCPP+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX166DEPP+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX167ACNG+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX167AENG+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX167BCNG+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX167BENG+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX16816ATJ+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX16920AEVKIT+	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX16929FGUI/V+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX16929HGUI/V+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX16948BGEE/V+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX16976AEE/V+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX16989ATJD/V+T	N/A	17-Jun-2017	17-Jun-2017	The part was not released
Discontinuance	MAX16989ATJF/V+T	N/A	17-Jun-2017	17-Jun-2017	The part was not released
Discontinuance	MAX170ACPA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX170BCPA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17100ETM+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17100ETM+C8W	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17100ETM+TC8W	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17100EVKIT+	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Jul-2017

Discontinuance	MAX17103ETJ+C9R	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17103ETJ+TC9R	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17106EVKIT+	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX17120ETJ+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX173ENG+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17401GTJ+TG40	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX1747EVKIT	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX174CEPI+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17501CATB+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17501CATB+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17501CAUD+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17501CAUD+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17501DATB+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17501DATB+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17501DAUD+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17501DAUD+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17502AATB+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17502AATB+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17502AAUD+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17502AAUD+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17502BATB+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17502BATB+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17502BAUD+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17502BAUD+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17502CATB+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17502CATB+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17502CAUD+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17502CAUD+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17502DATB+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17502DATB+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17502DAUD+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX17502DAUD+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX1773EVKIT	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX177ENG+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX178BENG+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX1798EUP+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured

**LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Jul-2017**

Discontinuance	MAX180CEPL+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX181AEPL+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX181BEPL+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX181CEPL+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX1820EVKIT	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX183AENG+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX183BENG+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX184ACNG+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX184AENG+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX184BENG+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX185ACNG+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX185AENG+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX185BENG+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX1880EUG+TG104	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX189CEPA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX191AENG+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX1938EVKIT	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX20010DATPK/V+T	N/A	17-Jun-2017	17-Jun-2017	The part was not released
Discontinuance	MAX20053AUD/V+TG2Z	N/A	17-Jun-2017	17-Jun-2017	The part was not released
Discontinuance	MAX2063ETM+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX2143BEGH/V+CCK	MAX2143DEGH/V+CCK	17-Jun-2017	17-Jun-2017	Reactivation
Discontinuance	MAX260ACNG+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX2655EVKIT	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX2656EXT+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX266AEP1+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX268ACNG+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX3003ETP+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX3007EUP+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX3007EUP+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX3096EPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX3098EACPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX314LEPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX31783ETM+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX31783ETM+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX3225EEPP+G2X	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX322EPA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Jul-2017

Discontinuance	MAX3267E/D	N/A	17-Jun-2017	17-Jun-2017	Part is leaded. Request information on lead-free version
Discontinuance	MAX3296C/D	N/A	17-Jun-2017	17-Jun-2017	Part is leaded. Request information on lead-free version
Discontinuance	MAX3296C/D-B50041	N/A	17-Jun-2017	17-Jun-2017	Part is leaded. Request information on lead-free version
Discontinuance	MAX3296LEVKIT	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX3463EPA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX3964C/D	N/A	17-Jun-2017	17-Jun-2017	Part is leaded. Request information on lead-free version
Discontinuance	MAX4173ATEUT+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4397SCTM+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4397SCTM+TG104	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4397SCTM+TG51	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4397SCTM+TGA8	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX44005EDT+QT	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4411BETP+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4455EVKIT	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX4455EVSYS	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX4462UETT+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4462UEUT+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4462UEUT+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4514CPA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4515CPA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4517CPA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4522EPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4523CPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4523EPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4529CPA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4536CPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4538CPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4566CPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4588CPI+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4597EXK+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4597EXK+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4610EPD+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4611EPD+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4612EPD+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4615CPD+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4619EPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Jul-2017

Discontinuance	MAX4630EPD+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4644CPA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4688CPA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4735ETE+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4735EUE+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4766BETA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4772ETT+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4772EUT+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4772EUT+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4790EUK+TG103	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4793ETT+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4838AELT+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4838AELT+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4838AEXT+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4838AEXT+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4842AEXT+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4842AEXT+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4842EXT+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4842EXT+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4846ELT+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4846ELT+G104	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4846ELT+TG104	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4846ELT+TGA8	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4846EXT+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX4852HETE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX501AENG+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX502BENG+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5039EUA+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5042ATN+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5057AASA+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5088ATE+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5089ATE+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5089EVKIT	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX513EPD+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX514BENG+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5150AEPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Jul-2017

Discontinuance	MAX5150BEPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5151ACPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5151AEPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5151BCPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5151BEPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5152ACPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5152AEPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5152BEPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5153ACPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5153AEPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5153BCPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5153BEPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5155ACPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5155AEPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5155BCPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5155BEPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5157ACPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5157AEPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5157BCPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5157BEPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5159EPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX520BEPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5251AEPP+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5251BEPP+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5253AEPP+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5253BCPP+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX530BENG+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX533ACPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX533AEPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX533BEPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5351AEPA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5351BCPA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5355CPA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5355EPA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5387EVKIT+	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX5388EVKIT+	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported

**LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Jul-2017**

Discontinuance	MAX5388EVMINIQU+	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX5393EVKIT+	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX5393EVMINIQU+	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX542BEPD+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX542CEPD+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX544AEPA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX550BEPA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX551BEPA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX552ACPA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX552AEPA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX552BCPA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX552BEPA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5556ESA+G0F	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5556ESA+TG0F	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5812PEUT+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5812PEUT+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5880AUXF+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5880AUXF+C75	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5880CUXF+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5880FUXF+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5880HUXF+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5880KUXF+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5901LAEUT+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5916EUI+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5958AETN+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5959AECS+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5959LECS+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5960AECS+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5960LECS+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5960LECS+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX5960LEVCMAXQU+	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX6173/D+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX6345TUT+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX6345TUT+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX6351LTUT+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX6351LTUT+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Jul-2017

Discontinuance	MAX6359SYUT+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX6359SYUT+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX6427PTUR+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX6427PTUR+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX6428MQUR+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX6428MQUR+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX6428MRUR+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX6428MRUR+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX6428ORUR+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX6428ORUR+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX6430FGUS+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX6430FGUS+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX6431EIUS+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX6431EIUS+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX6450BTA16T+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX6450BTA16T+TG47	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX662C/D	N/A	17-Jun-2017	17-Jun-2017	Part is leaded. Request information on lead-free version
Discontinuance	MAX6657YMSA+TG51	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX6668AUA40+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX6710OUT+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX6710OUT+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX6710PUT+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX6710PUT+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX6809SEUR+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX6813TEUR+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX6813TEUR+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX7031HATJ17+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX7412EPA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX7624EPE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX7645AEPP+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX7645AEPP+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX7645BEPP+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX7645BEPP+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX824SEXK+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX825MEXK+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX825YEXK+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Jul-2017

Discontinuance	MAX825YEXK+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8541EEE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8562ETA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8562ETA+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8634ELA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8634ETA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8634ETA+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8685AETD+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8685DETA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8685DETA+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8722EEG+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8728ETJ+T	MAX875BESA+	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8731ETI+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8731ETI+TG29	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8734EEI+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8784ETL+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8784ETL+TGA3	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8785ETI+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8797EVKIT+	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX8797GTI+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8797GTI+TGB4	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8865REUA+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8866SEUA+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8874SEUK+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8874SEUK+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX887EVKIT	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX8884EVKIT+	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX8900CEWV+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8903FETI+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8903FETI+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8971CEVKIT#	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX8971CEWP+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8982AEWO+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8982AEWO+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8982EVKIT#	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX8982EVKIT+	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Jul-2017

Discontinuance	MAX8982EWO+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8982EWO+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8982MEVKIT+	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX8982MEWO+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8982MEWO+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8982PEWO+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8982PEWO+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8982XEWO+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX8982XEWO+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX9270GTN/V+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX9500EEE+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX9504AELT+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX9504AELT+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX9504BELT+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX9504BELT+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX9508ATE+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX9653AUB+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX9653EVKIT+	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX9666ETP+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX9666ETP+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX9666EVKIT+	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX9673ETI+G0E	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX97001EWP+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX9719BEBE	N/A	17-Jun-2017	17-Jun-2017	Part is leaded. Request information on lead-free version
Discontinuance	MAX9719BETE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX9725EEBC+G45	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX9725EEBC+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX9725EEBC+TG45	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX9725EEBC+TG47	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX9725EEBC+TGD6	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAXQ612X-2041+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAXQ612X-2508+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAXQ612X-2509+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAXQ612X-2510+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAXQ612X-2513+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAXQ612X-2516+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured

**LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Jul-2017**

Discontinuance	MAXQ612X-2517+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAXQ612X-2518+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MX674AKEPI+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MX7520JN+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MX7520LN+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MX7524KEPE+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MX7528KEPP+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MX7528KN+2	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MX7528KN+4	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MX7528LEPP+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MX7530KN+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MX7530LN+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MX7547LN+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MX7572JN12+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MX7572KN05+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MX7572KN12+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MX7572LN12+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MX7576KN+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MX7581KN+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MX7672LN10+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MX7820LN+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MX7837AN+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	SUPEVKIT	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	VSC7156EKN	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	VSC7158EKN	N/A	17-Jun-2017	17-Jun-2017	EVKIT is No Longer Supported
Discontinuance	XLM4040AEX3-3.0V+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	XMAX16520GFO+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	XMAX16520GFO+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	XMAX16993ATJL/VY+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	XMAX16995ATPH/V+TW	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	XMAX17823AGCB/V+TW	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	XMAX17841BGUE/V+TW	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	XMAX20002ATPA/V+TW	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	XMAX20003ATPA/V+TW	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	XMAX20003ATPB/V+TG	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	XMAX20003ATPB/V+TW	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured

**LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Jul-2017**

Discontinuance	XMAX20010ATPA/V+TW	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	XMAX2087ACXD+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	XMAX2087CXD+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	XMAX32550SBA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_100800	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_90-B15BX+T01	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_90-T4725+V67	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_DS2465EDT+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_DS2465EDT+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_DS2745U+W	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_DS2745U+WDUPE	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_LM4040AEX3-3.0V+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX11198ATE40+_T1	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX11876EWJ+TCGO	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX1234AAUK+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX1234AAUK+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX1234BAUK+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX1234BAUK+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX1234CAUK+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX1234CAUK+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX1234DAUK+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX1234DAUK+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX12900ATJ#W	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX13326AUI/V+TW	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX13326AUI/V+W	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX14430CASE+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX14430CASE+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX14532AAP+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX14532AAP+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX16083UR26P+_T1	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX16089AXR32B/V+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX16089AXR32B/V+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX16134AKA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX16517A+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX16517A+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX16517C+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Jul-2017

Discontinuance	X_MAX16517C+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX16517E+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX16517E+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX16520GFO+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX16520GFO+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX16930BATLU/V+_T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX16984SATI/VY+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX16984SATI/VY+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX16993ATJL/VY+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX16995ATPH/V+W	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX17823AGCB/V+W	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX17823BGCB/V+W	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX17841BGUE/V+W	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX17880GUU/V+TW	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20002ATPA/V+W	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20002CATPC/V+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20002CATPC/V+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20002CATPD/V+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20002CATPD/V+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20003ATPA/V+W	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20003ATPB/V+W	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20003TPB/V+TCPO	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20010ATPA/V+TW	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20010CATPC/V+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20010CATPC/V+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20024CGXX/V+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20024CGXX/V+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20024EGXX/V+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20024FAXXA/V+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20024FAXXA/V+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20032ATIR/V+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20032ATIR/V+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20032ATIS/V+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20032ATIS/V+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20073ATAA/V+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20073ATAA/V+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured

**LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Jul-2017**

Discontinuance	X_MAX20073ATAC/V+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20073ATAC/V+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20074ATAA/V+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20074ATAA/V+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20074ATAB/V+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20074ATAB/V+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20074ATAC/V+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20074ATAC/V+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20091ATM/V+TW	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20091ATM/V+W	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20094ATIAB/VY+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20094ATIAB/VY+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20801TPB+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX20801TPB+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX2086CXD+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX2087ACXD+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX2087CXD+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX2087CXD+_DELET	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX23902A/D+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX241CAIT+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX30105EFD+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX30105EFD+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX31875TZS+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX31875TZS+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX32550SBA+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX3518ETP+C33_T1	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX36010-BNS+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX36010-BNS+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX5868EXE+W	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX5979GTJ+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX5979GTJ+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX6138CEXR33+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX6717UKTGG6+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX7762EWN+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX77734ENP+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX77734EWP+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured

**LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Jul-2017**

Discontinuance	X_MAX77734EWP+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX77874EWM+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX77874EWM+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX86100AEFF+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX86100AEFF+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX9276AGTN/V+TW	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX9276AGTN/V+W	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX9280AGTN/V+TW	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX9280AGTN/V+W	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX96945DGTV/VY+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX96945DGTV/VY+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAX9867EWW+G47	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAXFD+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAXM10002ALI+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAXM10002ALI+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAXM26200ALC+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_MAXQ61HC/D+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_TEST_SEAN	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_VT1676SBFQX+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_VT1676SBFQX_P1	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_VT505BFQ+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_VT505BFQ+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_X_MAX14532AAP+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_X_MAX14532AAP+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_X_MAX96945DGTV/VY+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_X_MAXM17574ALC+	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured
Discontinuance	X_X_MAXM17574ALC+T	N/A	17-Jun-2017	17-Jun-2017	Part can no longer be manufactured