

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134 PDN #: M000969I

DATE: 30-Apr-2019

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommeded Replacement	Last Order Date	Last Delivery Date	Reason
_ead-Free Conversion	MAX8516EUB/GG8	MAX8516EUB+	30-Apr-2019	29-Oct-2020	Part is leaded. Request information on lead-free version
Discontinuance	5962-9234501MPA	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	DS1086HU-C01+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	DS1086LU-440/V+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	DS1086LU-440/V+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	DS1086LU-455+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	DS1086LU-B66+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	DS1088EN-133+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	DS1088EN-133+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	DS1110S-300+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	DS1135LU-25+	DS1135LZ-25+	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	DS1230ABP-70IND+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	DS1231-35N+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	DS1302Z+T&R/C07	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	DS1306EN+T&R/C04	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	DS1315N-33+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	DS1345YP-70IND+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	DS1374C-18#	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	DS1672-3+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	DS1814CR-5-U+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	DS1817-10+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	DS1817-20+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	DS1817R-10-U+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	DS1818R-20-U+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	DS1819AR-5-U+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	DS1819BR-10-U+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured

Discontinuance	DS1819CR-20-U+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	DS1831B+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	DS1831C+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	DS3514T+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	DS3514T+T&R	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	ICL7621ACPA+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	ICL7631BC/D	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	ICL7631BCPE+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	ICL7631EC/D	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	ICL7631ECSE+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	ICM7212IPL+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX11131ATI+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX1115EKA+TG002	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX1159AEUI+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX11615EEE+C78	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX11615EEE+TC78	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX11627EEE/V+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX11627EEE/V+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX11803ETC+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX1202ACPP+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX120EAG+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX1232MLP/883B	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX1236EUA+CHV	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX12554ETL+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX12554ETL+D	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX12554ETL+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX1271BCNG+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX1271BENG+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX128ACNG+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX128AEAI+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX128AENG+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX134EQH+D	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX134EQH+TD	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX144AEPA+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX14602ETA+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX1492CAI+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured

Discontinuance	MAX150AEWP+	MAX15025CATB+	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX156BENG+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16005ETE+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16023PTAL33+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16023PTAL33+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16023PTAS25+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16023PTAS25+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16024LTBS+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16024LTBS+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16033PLB44+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16033PLB44+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16067ETJ+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16068ETI+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16125WTAA00+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16125WTAA00+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16125WTEA00+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16125WTEA00+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16126TCA/V+CN6	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16126TCA/V+TCN6	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16126TCC/V+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16126TCC/V+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16126TCD/V+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16126TCD/V+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX1615EUK+TG071	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX1644EAE+TG074	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX166AEPP+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16904RATB28/V+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16904RATB28/V+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16930BAGLC/VY+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16930BAGLC/VY+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16930BAGLD/VY+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16930BAGLD/VY+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16936RAUEA/V+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16936RAUEA/V+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX16977SAUE+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX173CNG+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured

Discontinuance	MAX178AENG+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX1840/W	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX188BCPP+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX189AEPA+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX1904BEAI+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX1904ETJ+TG074	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX1904ETJ+TG38	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX1953EUB+TG077	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX19588ETN+D	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX19793ETX+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX19793ETX+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX1999EEI+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX1999EEI+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX2140ETH+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX214EPI+G126	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX2172ETL+WC8S	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX260BEWG+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX31851RATB+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX31851RATB+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX319MJA	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX3202EEWS+G45	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX3202EEWS+TG45	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX325EUA+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX325EUA+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX3486CPA+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX3491ESD+TG069	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX3710ETG+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX3710ETG+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX3768CUB+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX3768CUB+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX3864E/D-B3A	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX4003EUA+C1D	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX409ACSA+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX409ACSA+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX4364ESA+CGL	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX4402AUA+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured

Discontinuance	MAX4412EXK+G21	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX454EPD+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX4723EUA+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX4780EUE+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX4780EUE+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX4791EUK+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX4836ETT33C+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX4854ETE+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
	MAX4854ETE+T	N/A	30-Apr-2019	29-Oct-2020	•
Discontinuance		N/A			Part can no longer be manufactured
Discontinuance	MAX5033BASA+CAU		30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX5085ATT+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX5110GWX+	MAX5113GWX+	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX5110GWX+T	MAX5113GWX+T	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX534AEPE+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX543BMJA/883B	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX5489ETE+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX5632UCB+D	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX5860HUXH+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX5902AAETT+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6023EBT41+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6023EBT41+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6070AAUT41+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6070BAUT41+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6071AAUT30+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX619EPA+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6306UK31D4+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6306UK31D4+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6308EUK00D3+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6308EUK00D3+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6316LUK29BX+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6316LUK45BX+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6336US22D2+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6336US22D2+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6336US24D1+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6345LUT+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6356TZUT+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured

Discontinuance	MAX6361LUT46+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
	MAX6361LUT46+T	N/A		29-Oct-2020 29-Oct-2020	Part can no longer be manufactured
Discontinuance			30-Apr-2019		•
Discontinuance	MAX6389XS30D2+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6422US46+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6422US46+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6443US23L+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6443US23L+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6444US31+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6444US31+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6444US31T+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6444US31T+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6502UKP045+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6502UKP045+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6504UKN035+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6504UKN035+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6505UTP085+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6653AEE+TG002	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6653AEE+TG071	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6654MEE+TG069	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6716AUTVHD3+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6716AUTVHD3+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6719AUTRVD1+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6719AUTRVD1+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6723AUTSYD3+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6723AUTSYD3+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6725KAVDD3+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6725KAVDD3+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6727AKASDD3+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6727AKASDD3+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6741XKTGD3+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6746KA26+TG071	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6751KA30+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6760TATAD3+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6760TATAD3+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6801UR44D3+TGA5	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6822SUK+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured

Discontinuance	MAX692AC/D	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX7057ASE+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX7057ASE+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX706RC/D	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX7407CPA+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX7407EPA+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX7414CPA+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX7503MSA+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX802TESA+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX802TESA+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX804SCSA+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX809SEUR+G49	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX810REUR+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX823TEUK+TG126	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX843ISA+TG068	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX8556ETE+TG071	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX8570ELT+G47	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX8570ELT+TG47	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX871EUK+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX8864SEUK+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX8875EUK25+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX8877EUK30+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX8878EUK33+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX9279GTN+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX9279GTN+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX9317CECJ+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX9386EUP+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX9386EUP+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX9395EHJ+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX9585AUB+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX9585AUB+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX9981ETX+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAXQ614V-2554+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAXQ614V-2566+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAXQ614V-L000+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MAXQ614V-UEI+T	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured

Discontinuance	MX7845KN+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	MXL1062CN8+	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured
Discontinuance	SD220+123	N/A	30-Apr-2019	29-Oct-2020	Part can no longer be manufactured