

|                                    |  |  |  |
|------------------------------------|--|--|--|
| <b>Product Name:</b>               | HPL – 649  |  |  |
|                                    | WireLock   |  |  |
| <b>Product Manager:</b>            | Jennifer Zhang   |  |  |
| <b>Subject:</b>                    | Notification of Change with Immediate Effectivity  |  |  |
| <b>Distribution:</b>               | Affected customers   |  |  |
| <b>Type of Change:</b>             | Design Change  |  |  |
| <b>Change Description:</b>         | Change the material escape structure of the product, and add exhaust groove, then generate split lines. Details can be checked in attached report. |  |  |
| <b>Reason for Change:</b>          | Optimize the male housing quality by molding process, no impact to mate with male housing on interface.  |  |  |
| <b>Affected Parts:</b>             | 10168908-040KALF   |  |  |
| <b>Effective Date of Change:</b>   | December,29 2023   |  |  |
| <b>Last Time Buy Date:</b>         | NA   |  |  |
| <b>Earliest Disty Return Date:</b> | NA   |  |  |
| <b>Last Time Shipment Date</b>     | NA   |  |  |
| <b>Datasheet Attached?</b>         | NA   |  |  |
| <b>Qual/Test Data Attached?</b>    | NA   |  |  |
| <b>Samples Availability Date:</b>  | 19 December ,2023  |  |  |
| <b>Available Alternatives?</b>     |  |  |  |
| <b>Questions?</b>                  | Contact your local ACS Representative, or Product Manager  |  |  |
|                                    | Jennifer Zhang / Product Manager   |  |  |
|                                    | Jennifer.Zhang@fci.com   |  |  |

**Note:**

Customers should contact Product Line Manager (or their local Amphenol Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .