

Product Discontinuance Notification

This is to inform you that the affected product(s) will be discontinued since there is no shipment record for 3 years. This change will take effect immediately from the date of this notification.

PDN No: PDN23007 rev0

Title: Product Discontinuance for ABS15LJ & ES1LX(H) series

Issue Date: 2023/12/4

If you have any questions concerning this change, please contact:

PDN Coordinator

Name : Sunnie Lin

E-Mail: sunnie.lin@mail.ts.com.tw

Phone: +886 8913 1588 ext. 2205

PDN Originator

Name : Daisy Liang

E-mail: daisy@mail.tsyew.com.cn

Phone: +86 5438691091 ext. 3108

Product Marketing

Name : Danny Lin

E-mail: danny.lin@ts.com.tw

Phone: +886 2 8913 1588 Ext. 2133

Effectivity:

Last Order Date: Immediately

Last Shipment Date: Immediately

Product Category (Description):

Taiwan Semiconductor discontinuance the product ABS15LJ & ES1LX(H) series.
The detailed part numbers are listed in the section of "Affected Product/Package".

Reason of Discontinuance:

Due to the low demand/ no demand for last 3 years, Taiwan Semiconductor Company will stop produce the products ABS15LJ & ES1LX(H) series.

Affected Product/Package:

Family	Package	Ordering Code	New Ordering Code
1.5A, 600V Low VF Standard Bridge Rectifier	ABS	ABS15LJ	None
1A, 200V - 600V Super Fast Surface Mount Rectifier	DO-214AC (SMA)	ES1LDH	ES1DH
1A, 200V - 600V Super Fast Surface Mount Rectifier	DO-214AC (SMA)	ES1LD	ES1D
1A, 200V - 600V Super Fast Surface Mount Rectifier	DO-214AC (SMA)	ES1LGH	ES1GH
1A, 200V - 600V Super Fast Surface Mount Rectifier	DO-214AC (SMA)	ES1LG	ES1G
1A, 200V - 600V Super Fast Surface Mount Rectifier	DO-214AC (SMA)	ES1LJ	ES1J
1A, 200V - 600V Super Fast Surface Mount Rectifier	DO-214AC (SMA)	ES1LJH	ES1JH