

Discontinuation of Transformers and Inductors not sold since 2019

For further information, please contact your regional Vishay office.

CONTACT INFORMATION

Americas

Pierre Lesur
71 chemin de la Mauniere
-
Hyerer France 83400
Phone: +33494123050
Fax: +33494123051
pierre.lesur@vishay.com

Europe

Pierre Lesur
71 chemin de la Mauniere
-
Hyerer France 83400
Phone: +33494123050
Fax: +33494123051
pierre.lesur@vishay.com

Asia

Pierre Lesur
71 chemin de la Mauniere
-
Hyerer France 83400
Phone: +33494123050
Fax: +33494123051
pierre.lesur@vishay.com

Description of Change: Obsolescence. In conformance with our Product Life management procedure, and due to lack of customer demand for more than 4 years, amplified by potential obsolescence risk on raw material, Sfernice Division is transferring old Transformers and Inductors to an End of Product Life status.

Classification of Change: No demand for more than 4 years

Expected Influence on Quality/Reliability/Performance: none

Part Numbers/Series/Families Affected: Please see materials list on the succeeding page.

Vishay Brand(S): Vishay Sfernice

Time Schedule:

Last Time Buy Date: Fri Aug 18, 2023

Last Time Ship Date: Sun Dec 31, 2023

Sample Availability: none

Product Identification: none

Qualification Data: none

This PTN is considered approved, without further notification, unless we receive specific customer concerns before Sun Jun 18, 2023 or as specified by contract.

Issued By: Pierre Lesur, pierre.lesur@vishay.com



The DNA of tech.

Product Termination Notification



Product Group: SF/Tue May 16, 2023/PTN-SF-335-2023-REV-0

LINWIMDB00C000530	LINWDMDB00C001016	LINPTVNB00C000901	LINPTVFB00A001376	LINWDNDB00D001956
TORWINSB00D002067D	LINPIVFB00D000372	LINPTVFB00D002059	PLALTPFB00M002076	PLALIVFB00M002077
PLAC100PUG	LINSTVFB00C002098	TORWDVDB00A001333	PLALINFB00V001902D	SC03V103NB25
PLAWIVFB00D001685	TORWIPNB23D000788	LINPIVFB00A001482	LINPTNFB00H002053	LINPIVFA15A001713
SC05V682NB25	PLALTVFB00V002056D	LINSTVFB00A001651	PLAWIVFB00D001720D	LINWDVDB00A001708
PLAWIVFB00V002057D	PLAPROTO0SMV001837	PLAWTVFB00D001719D	PLAC100S160	TORWINSB00A001620
SC04H472NB25	TORWINSB00A001621	PLA32PB43	TORWINSB00A001689	PLAPROTO0SMV001783
TORWTNSB00M001004	LINPINFB14D000234	TORPRO100830BM0081	TORPIPNB00D000790	TORPROTO1007150072
TORLTMB00M001834	TORPROTO1007150071	TORWDNDB00A001435	TORPROTO1007150070	TORWIVNB00A001646
TORPROTO1007020068	PLAC100P160	TORPROTO1003150028	SC03H103NB25	TORPROTO1003150027
SC03V682NB25	TORPROTO1003150026	SC05H473NB25	TORPRO100927BM0093	SC06V332NB25
TORPRO100830BM0083	PLALINFB00V001902	TORPRO100830BM0082	PLAWINFB00V001938D	TORPIMFB00A001572
PLALIVFB00V001923D	TORWIMFB00A001464	LINPINFB68D000235	TORWIVFB00A001577	TORLTMB00M000801
PLAC100PKIT	LINPROTO06CKV001774	SC03V102NB25	LINWDVDB00A001829	LINPTVFB14A001319
LINPTVFB00M000691	TORWINNB23C000432	TORWINFB00D001639	LINPIVFB00D000733	TORWDVDB00A001309
LINPIVFB25M000355	TORPIPNB00A000727	LINPTVFB00D000354	LINPTVFB25D000354	TORWIVNB00D000476
TORWIVDB00D000245	TORWIVNB40M000448	PLAPROTO0SMV001831	TORWTVFB00D000350	PLAC100P630
TORWINNB00D000378	PLAC100S400	LINWINFB25A000623	SC03H473NB25	LINPTVFB67A000207
SC03V332NB25	LINWTVFB00A000444	SC04H103NB25	TORWINFB25C000431	SC04V471NB25
PLAWIVFB00D001720	PLALTVFB00D001684	LINPRO110427CK0115	SC06V333NB25	LINPTVFB00A001705
SC06V472NB25	LINPROCK1002190013	PLA32PD41	LINPIVFB00A001706	PLAWIWF00V001921
LINPIVFB00D000525	PLALINFB00V001913D	TORPROCK1002190012	TORPICFB00C000209	LINPTVFB25M000138
PLAPROTO0SMV001784	PLALIVFB00V001924D	PLAPROTO0SMV001826	PLALTVFB00V001922D	PLAC100SUG
TRB023330JR10	LINPINFB68D000774	LINWICSB00D000834	LINPINFB19D000763	LINWIPSB00D001878
LINPINFB14D000233	LINPROTO5CKV001774	TORPIPNB00D000819	LINPROTO4CKV001774	LINPTNFB25D000041
LINPRO110729CK0129	PLAWTVFB00D001719	LINPTPSB00V001774	LINPROTO3CKV1774	LINPROTO1CKV1774
LINPROCK1003010014	LINPRO110729CK0130	LINSTVFB00D001816	LINPTPSB00V001851	LINSTVFB00D001707
LINWDVDB00A001830	LINPTVFB00D002058	LINWDVDB00A001718	LINPTVFB00D001578	LINPDVDB00A001390
LINPTVFB00D001531	TORLTMB00M001833	LINPTVFB00D001441	TORWDVDB00A001329	LINPIVFB00D001530
TORWDVDB00A001334	TORSTCFR10D000683	TORWDNDB00A001306	TORSTPNR15D001397	TORWDVDB00A001308
PLAWIVFB00D002005	TORWDNDB00A001307	LINSTNFB00D000550	LINPTNFB00C000069	LINSTNNB00D000264
PLAPROTO0SMV001836	LINSTDFR15D001395	LINPTVSB00T000851	LINSTDFR15D001885	TORWTVFB00A001644
LINSINDR15D001396	TORWIPNB00D000789	LINSTNFB00D001737	TRB0231R0KR10	TORSTPNR15D001397D
PLAC100P100	TORSTVFB00D001965D	PLAC100P400	TORSTPFB00D001775D	PLAC100S100
LINSINDR15D001786D	PLAC100S250	LINSINDR15D001916D	PLAC100S630	TORSTMNB00D002003
SC03H333NB25	TORWTPDB01D000628	SC03H682NB25	TORWTPDB01D000642	SC03V183NB25
PLALTVFB00D001686	SC03V333NB25	TORWIVNB00C000382	SC03V471NB25	LINPTVFB00C002038D
SC04H333NB25	LINPIVFB00C002039D	SC04H473NB25	LINPTVFB00C002037D	SC05H103NB25
SC05H682NB25	SC05H332NB25	SC05V103NB25	SC05V333NB25	SC05V183NB25
PLAPIPFB00D002002	SC05V473NB25	PLAPTPFB00D002001D	SC05V332NB25	PLAPIPFB00D002000D
SC06V102NB25	TRB023470KR10	SC06V471NB25	TRB023220KA15	PLA32PA44
SC03H102NB25	PLA32PC42	PLALINFB00V002016D	PLAWIWF00V001920	PLALINFB00V001913
PLAPIPFB00D002002D				