

## Product Change Notification

### PCN-ICC-1905-2018

Business Unit	Product Line Code	Type of Change	Action	Date of Issue
ICC - Industrial Cabinet	BE2	Product Change Notification	Notify Distributors and Field	7/9/2018

*The following Phoenix Contact products have been modified. Existing specifications will be met or exceeded. Please review and acknowledge this document and inform your personnel as needed.*

#### Description for Product Change Notification

The production process of the FBS jumpers has been optimized in the following manner...

- 1.) The mechanical connection of the two-layered metal was reinforced. (Not visible, joint position is over molded by plastic)
- 2.) The punch process of the predetermined breaking point has been optimized (New tooling concept, not visible)


These modifications have no relation to the fit, form or function of the bridging system. They also have no influence on any technical data, approvals, function, handling or design.

#### Stock Status

Can existing stock still be used?	Yes
Is mixture of stock acceptable?	Yes

#### Transaction Dates

Date modification goes into effect from Germany:	7/5/2018
Expected first shipment (from Phoenix Contact) of the modified products(s):	7/9/2018





## Product Change Notification

*Should you have any issues with the timeline or content of this product change, please contact Phoenix Contact using the information below. Customers should acknowledge receipt of the PCN within 30 days of delivery of the PCN; provided, however, that the failure to acknowledge receipt does not affect the product change or the effective date thereof.*

**Contact Info:**

Cory Myer  
cmyer@phoenixcon.com

Thank you,

*Alan P. Sappe'*

---

Alan Sappe

Product Marketing Manager - Industrial Cabinet Conn.



Phoenix Contact Inc.  
P.O. BOX 4100  
Harrisburg, PA 17111-0100  
Phone: 717-944-1300  
Fax: 717-944-1625

## Product Change Notification

Part #	Type Description
3000706	FBS 50-3,5
3000707	FBS 50-3,5 GY
3000708	FBS 50-3,5 BU
3030116	FBS 2-4
3030117	FBS 2-4 BU
3030118	FBS 2-4 GY
3030129	FBS 3-4
3030130	FBS 3-4 BU
3030131	FBS 3-4 GY
3030132	FBS 4-4
3030133	FBS 4-4 BU
3030145	FBS 5-4
3030146	FBS 5-4 BU
3030158	FBS 10-4
3030160	FBS 10-4 GY
3030284	FBS 2-8
3030297	FBS 3-8
3030307	FBS 4-8
3030310	FBS 5-8
3030323	FBS 10-8
3030352	FBS 20-4
3030353	FBS 20-4 BU
3030354	FBS 20-4 GY
3032363	FBS 1/3-8
3032376	FBS 1/4-8
3032381	FBS 1/5-8
3032470	FBS 6-8
3032567	FBS 2-8 BU
3032570	FBS 3-8 BU
3032583	FBS 4-8 BU
3032596	FBS 5-8 BU
3032606	FBS 10-8 BU
3032621	FBS 2-8 GY
3032622	FBS 3-8 GY
3032635	FBS 4-8 GY
3032648	FBS 5-8 GY
3032651	FBS 10-8 GY
3032664	FBS 6-8 GY
3032677	FBS 6-8 BU
3033830	FBS 2-8 CT
3033833	FBS 10-8 CT
3036851	FBS 10-4 BU
3213014	FBS 2-3,5
3213027	FBS 3-3,5
3213030	FBS 4-3,5
3213043	FBS 5-3,5
3213056	FBS 10-3,5



Phoenix Contact Inc.  
P.O. BOX 4100  
Harrisburg, PA 17111-0100  
Phone: 717-944-1300  
Fax: 717-944-1625

## Product Change Notification

3213069	FBS 20-3,5
3213086	FBS 2-3,5 BU
3213099	FBS 3-3,5 BU
3213109	FBS 4-3,5 BU
3213112	FBS 5-3,5 BU
3213125	FBS 10-3,5 BU
3213138	FBS 20-3,5 BU
3213153	FBS 2-3,5 GY
3213167	FBS 3-3,5 GY
3213180	FBS 4-3,5 GY
3213183	FBS 5-3,5 GY
3213196	FBS 10-3,5 GY
3213206	FBS 20-3,5 GY